

Indian Affairs																
Fiscal Year 2011 Priority Backlogs for Supplemental Funding																
Region	Loc #	Location Name	Bid Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank	
Central Office	L03-01	Haskell Indian Nations University	104	L03-01-104-M-008-1	M	1	Open	\$481,294	Install new Geothermal heat pump units in classroom building	Current system does not allow for individual heat/cool in separate zones. Current unit is aged and replacement parts are obsolete and is not energy efficient.	Occupied	BIA Education	School, Post-Secondary, Boarding	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	104	L03-01-104-M-009-1	M	1	Open	\$10,479	Upgrade Chiller Electrical Service	Current system has insufficient capacity. Fuses blow when both compressors are turn on.	Occupied	BIA Education	School, Post-Secondary, Boarding	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	104	L03-01-104-S-001-1	S	1	Open	\$11,110	Replace Carpet	Ripped/Trip Hazard	Occupied	BIA Education	School, Post-Secondary, Boarding	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	121	L03-01-121-M-018-1	M	1	Open	\$221,960	Replace aged condensers that have exceeded its useful life	Existing unit has exceeded its useful life and many shop orders on these units	Occupied	BIA Education	Office	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	121	L03-01-121-S-001-1	S	1	Open	\$14,986	REPLACE STEEL EXTERIOR DOOR	ALTERNATE EGRESS	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	121	L03-01-121-S-002-1	S	1	Open	\$43,430	Replace Carpet	Stained/Torn/Ripped/Trip Hazard	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	121	L03-01-121-S-003-1	S	1	Open	\$43,430	Replace Floor Tiles	Cracked/Broken/Trip Hazard/Exposed Sherp Edges	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	124	L03-01-124-S-001-1	S	1	Open	\$80,600	Modify Exits	To meet Handicapped Accessibility requirements	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	125	L03-01-125-M-008-1	M	1	Open	\$5,669	REPLACE ASPHALT SHINGLES, 300 SF AND OVER	AME Requested Backlog	Occupied	BIA Education	Office	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	125	L03-01-125-S-001-1	S	1	Open	\$80,600	Modify Exits	To meet Handicapped Accessibility requirements	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-F-001-2	F	2	Open	\$7,373	Install remote annunciator control panel	Currently the panel is located in the boiler room and food service staff do not have access to determine if panel is in "trouble" "alarm" or "normal" modes	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	F-2	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-007-1	M	1	Open	\$7,639	REPLACE KITCHEN GRILL, GAS	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-026-1	M	1	Open	\$24,045	Replace condenser. Current unit has exceeded its useful life.	Unit has exceeded its useful life and also has numerous leaks	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-027-1	M	1	Open	\$14,220	REPLACE FOOD STEAMER, UP TO 10 KW	Existing unit is obsolete, replacement parts are difficult to obtain	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-028-1	M	1	Open	\$13,508	REPLACE COMMERCIAL BAKE OVEN, 1 SECTION, ELECTRIC CONNECTION	existing units obsolete and replacement parts are difficult to obtain	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-029-1	M	1	Open	\$44,452	REPLACE SHELL AND TUBE HEAT EXCHANGER, HOT WATER OR STEAM, 120 - 240 GPM	Existing tank is original to building and past useful life.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-030-1	M	1	Open	\$141,913	Replace Water Wash Grill Ventilators	Current system does not work and staff cannot clean the grease out of the exhaust duct.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-031-1	M	1	Open	\$86,196	Replace pass through coolers (2)	Two pass through coolers are not operable and need replacement.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-033-1	M	1	Open	\$2,525	REPLACE LAVATORY FAUCET WITH POP-UP DRAIN	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-034-1	M	1	Open	\$19,952	REPLACE TERRAZZO FLOOR	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-035-1	M	1	Open	\$8,072	CONDUCT STRUCTURAL ENGINEERING STUDY ON FOUNDATION AND FLOOR SYSTEM	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	126	L03-01-126-M-041-1	M	1	Open	\$18,995	REPLACE INDUSTRIAL ALUMINUM SIDING, MULTIPLE STORY	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	128	L03-01-128-S-002-1	S	1	Open	\$252,500	Install New Food Service Equipment	Replacement parts for equipment is obsolete/Worn/Can Potentially Cause Injury	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-003-1	M	1	Open	\$54,766	Install new intercom system	Due to current trends in violence and to comply with mandates for safer schools, this item is a critical part of Haskell's safety plan to protect students, staff, and faculty	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-006-1	M	1	Open	\$68,044	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 1531 TO 2170 MBH	Replacement of original boiler - past useful life	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-007-1	M	1	Open	\$21,324	REPLACE FAN COIL UNIT, CHILLED WATER AND OR HOT WATER HEATING COILS, HORIZONTAL/VERTICAL, OVER 1-1/2	AME Requested Backlog	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-008-1	M	1	Open	\$7,029	REPLACE PLASTER CEILING ON IRREGULAR CURVED SURFACES AND BEAMS, NO LATH, OVER 5 SF PER LOCATION	AME Requested Backlog	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-009-1	M	1	Open	\$4,353	REPLACE INTERIOR PLASTER WALL, NO LATH, OVER 5 SF	AME Requested Backlog	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	12	L03-01-12-M-012-1	M	1	Open	\$11,932	REPLACE CIRCULATING PUMP, BASE-MOUNTED, OVER 1-1/2 UP TO 5 HP	Inspected by AME: VALDEZ 25-OCT-1999	Occupied	BIA Education	Auditorium	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	1	L03-01-1-M-006-1	M	1	Open	\$54,766	Install new intercom system	Due to current trends in violence and to comply with mandates for safer schools, this item is a critical part of Haskell's safety plan to protect students, staff, and faculty	Occupied	BIA Education	Office	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	4	L03-01-4-M-011-1	M	1	Open	\$82,946	Install new intercom system and connect to mainframe located in Winnemucca complex.	Due to current trends in violence and to comply with mandates for safer schools, this item is a critical part of Haskell's safety plan to protect students, staff, and faculty. This cost estimate was provided by a security systems contractor and will connect bldg #4 to mainframe located at southeast of campus	Occupied	BIA Education	Office	Poor	M-1	
Central Office	L03-01	Haskell Indian Nations University	4	L03-01-4-S-002-1	S	1	Open	\$7,375	Install Windows	Damaged and hard to open/close	Occupied	BIA Education	Office	Poor	S-1	
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-024-1	M	1	Open	\$1,944,111	REPLACE SEWER PIPE, CAST IRON, 8", UP TO 6 FT DEEP	AME Requested Backlog				N/A	M-1	
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-036-1	M	1	Open	\$10,625	RELOCATE TELEPHONE PBX SWITCH/EQUIPMENT	RELOCATE TELEPHONE PBX SWITCH/EQUIPMENT, UPGRADE, FROM BUILDING 37 TO BUILDING 123. COST SOURCE: RS MEANS FACILITIES 2008 ITEMS 16710-400-0070/0350/0450(MULTI RACK ENCLOSURE - 1 EA, FIBER SPLICE- 1 EA, CABLE - 150 LF); 02580-420-5600(DUCT - 130 LF); 02220-360-0400/0015 (SAWCUT PAVEMENTS - 90 LF); 02315-620-2850 (TRENCHING - 130LF)	Inspected by AME: VALDEZ 25-OCT-1999				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-038-1	M	1	Open	\$36,258	Existing CAT-5 and CAT-5E networking cables are worn and do not meet existing rated cabling requirements	Existing CAT-5 and CAT-5e cables are general purpose and produce hazardous chemicals. Replace with CAT-6 Plenum rated cables that meet UL 910.				N/A	M-1	
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-039-1	M	1	Open	\$4,157	REPLACE ALUMINUM LIGHT POLE, OVER 20 UP TO 40 FT	AME Requested Backlog				N/A	M-1	

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-052-1	M	1	Open	\$105,320	Install closed circuit surveillance system for parking lots and Ree Cloud Hall	required to detect vandalism and safety concerns				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-057-1	M	1	Open	\$2,759	Repair cable entry port, install ground buss and ground kits	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-058-1	M	1	Open	\$4,392	Install guy anchor grounding, ground bars and repair tower grounding	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-059-1	M	1	Open	\$8,174	Install ground kits, reroute cable and repair cable support hardware	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-060-1	M	1	Open	\$4,380	Install lee bridge	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-061-1	M	1	Open	\$3,013	Replace tower members	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-062-1	M	1	Open	\$2,989	Install site ground ring and warning signage	Mindbank inspection				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-074-1	M	1	Open	\$24,213	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-083-1	M	1	Open	\$63,820	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-085-1	M	1	Open	\$2,822	REPLACE LANDSCAPE CURBING, CONCRETE	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-086-1	M	1	Open	\$63,273	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	Pavement is dire need of replacement has cracks and holes				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-089-1	M	1	Open	\$92,599	Install new CCTV Cameras	Additional CCTV cameras are necessary to monitor the 320 acre campus.				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-093-1	M	1	Open	\$6,425	REPLACE CORRUGATED METAL STORM DRAINAGE PIPE, 12" DIAMETER	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-095-1	M	1	Open	\$47,300	REPLACE 3 PHASE PAD-MOUNTED TRANSFORMER; 5 KV TO 15 KV PRIMARY, 120/208V OR 277/480V SECONDARY, 300	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-096-1	M	1	Open	\$4,310	REPLACE TANK MONITORING SYSTEM	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-098-1	M	1	Open	\$7,803	REPLACE UP TO 8" PIPE BOLLARDS	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-101-1	M	1	Open	\$316,463	REPLACE SEWER PIPE, CAST IRON, 6", UP TO 6 FT DEEP	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-102-1	M	1	Open	\$2,777	CLEAN AND SEAL CONCRETE CRACKS IN SITE PAVEMENTS	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-103-1	M	1	Open	\$3,335	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-104-1	M	1	Open	\$6,056	REPLACE CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-104-1	M	1	Open	\$4,105	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-114-1	M	1	Open	\$4,475	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-115-1	M	1	Open	\$17,897	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-119-1	M	1	Open	\$15,288	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-120-1	M	1	Open	\$7,623	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-123-1	M	1	Open	\$17,379	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-124-1	M	1	Open	\$3,574	REPLACE CAST IN PLACE CONCRETE STAIRS, BASED ON SF OF TREADS AND LANDING	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-126-1	M	1	Open	\$10,203	REPLACE CAST IRON CONCRETE STAIR TREAD INSERTS	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-127-1	M	1	Open	\$16,482	REPLACE BRICK PAVERS, GROUTED JOINTS	AME Requested Backlog				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-M-129-1	M	1	Open	\$41,158	Defective underground telephone cable throughout campus	Current underground telephone cable is defective and worn.				N/A	M-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-S-001-1	S	1	Open	\$247,450	Replace Concrete Sidewalk	Missing/Spalled/Cracked				N/A	S-1
Central Office	L03-01	Haskell Indian Nations University	Ground	L03-01-X01-S-002-1	S	1	Open	\$6,241	Replace Galvanized Steel Pipe Rails	Broken				N/A	S-1
Eastern Oklahoma Region	G09-02	Jones Academy Dormitory	Ground	G09-02-X01-M-023-1	M	1	Open	\$32,268	Flashing Caution Lights for County Road on south side of campus.	To increase the safety and security for students on campus.				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	233	S78-23-233-M-004-1	M	1	Open	\$33,389	Interior of building needs to be painted	The building is aged and is need of facelift for cleaner learning environment for students	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	233	S78-23-233-M-010-1	M	1	Open	\$6,825	REPLACE BRANCH CIRCUIT DEVICES IN THE 7,492 GSF MIDDLE SCHOOL, (WORN/DETERIORATED), THROUGHOUT BUILDING.	Inspected by AME: VERA CRUZ 07-FEB-2000	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	233	S78-23-233-M-013-1	M	1	Open	\$80,993	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Inspected by AME: VERA CRUZ 07-FEB-2000	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	233	S78-23-233-M-015-1	M	1	Open	\$10,233	REPLACE DOOR CLOSER, RACK AND PINION SURFACE MOUNTED	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	233	S78-23-233-M-017-1	M	1	Open	\$20,250	REPLACE LIGHTING SYSTEM IN A 7,492 GSF MIDDLE SC	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-008-1	M	1	Open	\$68,287	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-013-1	M	1	Open	\$233,733	REPLACE 2-3 STORY HIGH SCHOOL PLUMBING SYSTEM	Inspected by AME: VERA CRUZ 07-FEB-2000	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-019-1	M	1	Open	\$681,423	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), MULTIPLE STORY	We have experienced water leaks in the exterior walls of the building	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-022-1	M	1	Open	\$59,113	REPLACE DOUBLE STEEL BOX LOCKERS, 12" X 15" X 36"	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-024-1	M	1	Open	\$79,815	REPLACE UNBALLASTED SINGLE PLY MEMBRANE, RUBBER/PLASTIC ROOFING, 300 SF AND OVER	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-026-1	M	1	Open	\$39,856	Paint is peeling and walls are in need of repairs	To provide students with clean and refreshed atmosphere—building is 40 years of age	Occupied	Grant Education	School, Secondary, Day	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-031-1	M	1	Open	\$5,315	REPLACE WATER CLOSET COMPARTMENT; PHENOLIC REPLACE BRANCH CIRCUIT DEVICES	Inspected by AME; BALL 07-FEB-2000	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	234	S78-23-234-M-034-1	M	1	Open	\$17,771	REPLACE BRANCH CIRCUIT DEVICES IN THE 33,236 GS	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-013-1	M	1	Open	\$12,182	REPLACE PANELBOARD, 225 AMPS, 4 WIRE, 120/208V, UP TO 42 CIRCUITS	Inspected by AME; VERA CRUZ 07-FEB-2000	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-032-1	M	1	Open	\$55,103	REPLACE CENTRIFUGAL ROOF EXHAUSTER, 1950 CFM, 12" BELT DRIVEN, ROOF OR WALL MOUNTED	Inspected by AME; VERA CRUZ 07-FEB-2000	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-033-1	M	1	Open	\$85,511	Building throughout interior needs to be repainted	Building is aged, to refresh and clean environment for staff and students	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-035-1	M	1	Open	\$8,995	INSTALL SURVEILLANCE CAMERA	Need to monitor activities around building during normal and after working hours	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-038-1	M	1	Open	\$5,920	REPLACE RIGID CONDUIT, 1-1/4" UP TO 2", UP TO 16' ABOVE FINISHED GRADE	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-M-040-1	M	1	Open	\$7,096	REPLACE PANELBOARD 400 AMP MAIN BREAKER, 120/208V 3 PHASE, 4 WIRE, UP TO 42 CIRCUIT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	255	S78-23-255-S-001-1	S	1	Open	\$27,138	REPLACE WOOD, SOLID CORE, INTERIOR DOOR AND HARDWARE	Requesting funds for safety deficiencies	Occupied	Grant Education	Dormitory, School	Poor	S-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-014-1	M	1	Open	\$11,372	REPLACE PREFABRICATED METAL FRAMED SKYLIGHT	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-015-1	M	1	Open	\$97,214	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-017-1	M	1	Open	\$24,432	OSB Board Material used for hallways and classroom separation with no smoke resistance	Walls are not fire rated in hallways and classroom separation is not provided for	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-031-1	M	1	Open	\$39,993	Walls need to be painted and patched	Building is aged and needs to be updated and walls need to be repaired	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-032-1	M	1	Open	\$26,541	REPLACE 12" X 12" STAPLED OR CEMENTED MINERAL FIBER ACOUSTIC CEILING TILES	FACCOM Inspected by AME; BALL 07-FEB-2000	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-033-1	M	1	Open	\$20,893	UPGRADE TO DDC CONTROL SYSTEM FOR HVAC FROM PNEUMA UPGRADE TO DDC CONTROL SYSTEM FOR HVAC FROM PNEUMATIC CONTROL SYSTEM,(DETERIORATED), CURRENTLY PNEUMATIC, COMPONENTS ARE SEVERLY DETERIORATED OR BYPASSED DUE TO IMPROPER FUNCTION, THROUGHOUT BUILDING, MAIN CONTROL BOARD IN ROOM 140.	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	269	S78-23-269-M-034-1	M	1	Open	\$3,098	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	AME Requested Backlog	Occupied	Grant Education	School, Secondary, Day	Poor	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-013-1	M	1	Open	\$4,727	REPLACE DRAINAGE PIPE UP TO 12" DIAMETER	There is standing water near sidewalks and building #237				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-014-1	M	1	Open	\$3,856	REPLACE DRAINAGE PIPE UP TO 12" DIAMETER	This will keep the water from further damage to building				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-016-1	M	1	Open	\$1,133,650	REPLACE 4" DOMESTIC WATER MAINS AND 1-1/2" LATERALS	Inspected by AME; VERA CRUZ 07-FEB-2000				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-019-1	M	1	Open	\$3,900	Handrails are rusting at the base	Handrails are a safety hazard--there are only a few bases that are still holding on				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-028-1	M	1	Open	\$10,898	REPLACE DRAINAGE PIPE UP TO 12" DIAMETER	Wash out flows underneath visitors dugout and causes trip hazards and is a continuous maintenance problem after each rain				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-037-1	M	1	Open	\$19,608	REPLACE COOLING TOWER, AXIAL FAN, INDUCED DRAFT, OVER 80 UP TO 160 TONS	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-035-1	M	1	Open	\$58,427	INSTALL WALKWAY COVER, UP TO 8' WIDE AND 10' TALL	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-041-1	M	1	Open	\$2,560	REPLACE DRAINAGE PIPE UP TO 12" DIAMETER	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-045-1	M	1	Open	\$11,846	RESET CAP OR COPING STONES UP TO 6" THICK	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-048-1	M	1	Open	\$2,915	REPLACE CONCRETE SITE WALL, UP TO 8" THICK	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-047-1	M	1	Open	\$31,127	REPLACE INDUSTRIAL CHAIN LINK FENCE AND POSTS, 3 STRANDS BARBED WIRE, 10' HIGH	AME Requested Backlog				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-052-1	M	1	Open	\$51,634	Propane tank farm is not up to NFPA/ANSI #58 standards	Will not be able to receive propane in year 2012				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-053-1	M	1	Open	\$15,468	UNSAFE PLAYING CONDITIONS ON BASEBALL WARNING TRACK DUE TO EROSION	To prevent further erosion and fix trip and fall hazard areas				N/A	M-1
Eastern Region	S78-23	Choctaw Central School	Ground	S78-23-X01-M-054-1	M	1	Open	\$8,952	No canopy to entrance of buildings at 4 buildings	To protect building floor tile and provide covering for students during rain				N/A	M-1
Eastern Region	S57-02	Indian Island School	Ground	S57-02-X01-M-002-1	M	1	Open	\$18,780	REPLACE RUBBER-ACRYLIC BASE RESILIENT ATHLETIC PAVEMENT	AME Requested Backlog				N/A	M-1
Eastern Region	S57-02	Indian Island School	Ground	S57-02-X01-M-004-1	M	1	Open	\$6,075	REPLACE BACKSTOP ON PLAYING FIELD	AME Requested Backlog				N/A	M-1
Eastern Region	S57-02	Indian Island School	Ground	S57-02-X01-M-007-1	M	1	Open	\$14,850	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 8' HIGH	AME Requested Backlog				N/A	M-1
Great Plains Region	A06-02	American Horse School (Allen)	430	A06-02-430-M-002-1	M	1	Open	\$4,460	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-02	American Horse School (Allen)	430	A06-02-430-S-001-1	S	1	Open	\$2,921	REPLACE CONCRETE SIDEWALK	The sidewalk at the front of the building is sloped inward of the building causing water and ice to build up around the building creating possible slip hazards.	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-02	American Horse School (Allen)	430	A06-02-430-S-002-1	S	1	Open	\$4,848	INSTALL STEEL PIPE RAILING	The new concrete ramp at the secondary exit has no handrails.	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-02	American Horse School (Allen)	Ground	A06-02-X01-M-012-1	M	1	Open	\$51,845	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2002	A01-12-2002-M-015-1	M	1	Open	\$16,245	REPLACE COMBINATION STOVE/REFRIGERATOR/SINK, FOR APARTMENTS AND EFFICIENCIES	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2002	A01-12-2002-M-020-1	M	1	Open	\$4,432	REPLACE FUSE BOX WITH PANELBOARD 225 AMP, 3 PHASE, 120/208 VOLT, 42 CIRCUITS	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2002	A01-12-2002-M-026-1	M	1	Open	\$11,693	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment. System doesn't not have a chemical treatment system. There is no AV device near either door. No battery-type exit luminaires at each door.	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment.	Occupied	BIA Education	Dormitory, School	Poor	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2005	A01-12-2005-M-008-1	M	1	Open	\$95,304	REPLACE INDOOR AIR HANDLING UNIT, MULTI-ZONE, OVER 9,000 UP TO 13,200 CFM	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2005	A01-12-2005-M-009-1	M	1	Open	\$2,791	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2005	A01-12-2005-M-010-1	M	1	Open	\$10,390	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment. Current boiler does not have properly sized combustion air openings, need to install a motorized dampers in the combustion air opening, a chemical feeder for boiler, provide LED exit luminaires at each door. Provide an AV device near center on the room. Provide a boiler shut-off switch at the interior door with signage.	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment.	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	2005	A01-12-2005-S-002-1	S	1	Open	\$32,311	REPLACE BOILER, GAS/OIL FIRED, STEAM/HOT WATER, REPLACE HEATING HOT WATER EXPANSION TANK, REPLACE CENTRIFUGAL PUMP HEAD, HIGH HEAD PRESSURE PUMP-MOTOR SET	FACCOM Inspected by AME: BENDER 17-MAY-99	Occupied	BIA Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-005-1	M	1	Open	\$26,311	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-008-1	M	1	Open	\$15,860	REPLACE CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-009-1	M	1	Open	\$12,335	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-013-1	M	1	Open	\$14,790	Provide funding for ratification of work accomplished by CRST telephone authority	ratification costs				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-015-1	M	1	Open	\$281,898	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-019-1	M	1	Open	\$6,244	REPAIR CHAIN LINK FENCE, FABRIC ONLY	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-021-1	M	1	Open	\$7,180	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-022-1	M	1	Open	\$3,834	REPLACE CONCRETE APRON	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-023-1	M	1	Open	\$408,633	REPLACE BLEACHERS, WOOD WITH STEEL UNDER STRUCTURE	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-M-024-1	M	1	Open	\$125,437	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Great Plains Region	A01-12	Cheyenne-Eagle Butte School	Ground	A01-12-X01-S-001-1	S	1	Open	\$19,800	Sidewalks	Sidewalk is deteriorating and creates trip hazards				N/A	S-1
Great Plains Region	A10-05	Little Eagle Day School	Ground	A10-05-X01-M-008-1	M	1	Open	\$3,137	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A10-05	Little Eagle Day School	Ground	A10-05-X01-M-014-1	M	1	Open	\$26,213	OVERLAY EXISTING PAVEMENT WITH 1" WEARING COURSE	AME Requested Backlog				N/A	M-1
Great Plains Region	A10-05	Little Eagle Day School	Ground	A10-05-X01-S-003-1	S	1	Open	\$8,800	REPLACE MULCH AROUND PLAYGROUND EQUIPMENT	EXISTING PLAYGROUND AREA LACKS SUFFICIENT SURFACING MATERIALS				N/A	S-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-M-007-1	M	1	Open	\$11,752	REPLACE FLUSH STEEL EXTERIOR DOUBLE DOORS WITH FRAME AND HARDWARE, UP TO 8' X 8'	This backlog previously had a rank and category of M-007-3, it is not available for funding.	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-M-010-1	M	1	Open	\$3,953	REPLACE DRYWALL CEILING WITH FIRE RATED DRYWALL	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-M-011-1	M	1	Open	\$12,355	REPLACE SLIDING WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, ALUMINUM FRAME	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-M-012-1	M	1	Open	\$5,584	REPLACE STEEL EXTERIOR DOOR WITH FRAME AND HARDWARE, UP TO 8' X 7'	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-M-013-1	M	1	Open	\$7,330	REPLACE WOOD LAMINATE FLOATING FLOOR	AME Requested Backlog	Occupied	Grant Education	School, Middle, Day	Poor	M-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-S-001-1	S	1	Open	\$23,435	REPLACE FIRE ALARM SYSTEM REPLACE FIRE ALARM SYSTEM IN A 6022 GSF MIDDLE SCHOOL(SYSTEM IS NON-OPERATIONAL) MAIN PANEL LOCATED IN THE CLOSET OF THE RESOURCE/SPECIAL EDUCATION ROOM AT THE SOUTHWEST END OF THE BUILDING.	The fire alarm system is non-operational.	Occupied	Grant Education	School, Middle, Day	Poor	S-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-S-002-1	S	1	Open	\$5,229	REPLACE FLUSH STEEL EXTERIOR DOUBLE DOORS WITH FRAME AND HARDWARE, UP TO 8' X 8'	DOOR WILL NOT OPEN OR CLOSE PROPERLY.	Occupied	Grant Education	School, Middle, Day	Poor	S-1
Great Plains Region	A06-05	Little Wound/Kyle	349	A06-05-349-S-007-1	S	1	Open	\$9,415	REPLACE WOOD INTERIOR SOLID CORE DOOR, FRAME AND HARDWARE 3' X 7'	FACCOM	Occupied	Grant Education	School, Middle, Day	Poor	S-1
Great Plains Region	A06-05	Little Wound/Kyle	Ground	A06-05-X01-M-014-1	M	1	Open	\$3,058	REPLACE CAST IN PLACE CONCRETE STAIRS, BASED ON SF OF TREADS AND LANDING	AME Requested Backlog				N/A	M-1
Great Plains Region	A06-05	Little Wound/Kyle	Ground	A06-05-X01-M-024-1	M	1	Open	\$93,766	DEMOLISH ELEVATED WATER TOWER, 100,000 TO 500,000 GAL	AME Requested Backlog				N/A	M-1
Great Plains Region	A06-05	Little Wound/Kyle	Ground	A06-05-X01-M-025-1	M	1	Open	\$6,042	REPLACE WALKWAY LIGHT FIXTURE, 250W METAL HALIDE	AME Requested Backlog				N/A	M-1
Great Plains Region	A06-05	Little Wound/Kyle	Ground	A06-05-X01-M-040-1	M	1	Open	\$2,161,225	This is ARRA Project No. 9YA06069 - Replace the existing domestic sewer mains and service lines, appurtenances throughout site. The aged system has deteriorated and needs replacement with new PVC pipes.	The existing aged and deteriorated is in need of replacement.				N/A	M-1
Great Plains Region	A06-05	Little Wound/Kyle	Ground	A06-05-X01-S-001-1	S	1	Open	\$3,806	REPLACE GALVANIZED STEEL PIPE RAIL, TWO RAILS	AME Requested Backlog				N/A	S-1
Great Plains Region	A15-02	Lower Brule Day School	324	A15-02-324-M-006-1	M	1	Open	\$4,020	REPLACE ELECTRIC BASEBOARD HEATER, 6' TO 10', 1500 TO 1875 WATTS	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A15-02	Lower Brule Day School	324	A15-02-324-M-007-1	M	1	Open	\$8,034	RENOVATE RESIDENTIAL BATHROOM, 40 SF	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A15-02	Lower Brule Day School	324	A15-02-324-S-001-1	S	1	Open	\$6,851	REPLACE CARPET	THERE IS CARPETING THAT IS TORN AND MAY CAUSE TRIP HAZARDS	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-M-024-1	M	1	Open	\$2,842	REPLACE INTERIOR CMU WALL OVER 4 SF PER LOCATION	AME Requested Backlog	Occupied	Contract Education	School, Secondary, Day	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-M-037-1	M	1	Open	\$30,750	REPLACE STAINLESS STEEL SHOWER COLUMN GROUP SHOWER, 6 HEADS	AME Requested Backlog	Occupied	Contract Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-M-041-1	M	1	Open	\$5,566	REPLACE FIRE RETARDANT STAGE CURTAIN, VELOUR, MEDIUM WEIGHT	AME Requested Backlog	Occupied	Contract Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-M-045-1	M	1	Open	\$913,400	Existing roof is aged and deteriorated and is leaking and in need of immediate replacement.	This roof needs immediate replacement	Occupied	Contract Education	School, Secondary, Day	Poor	M-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-001-1	S	1	Open	\$2,564	REPLACE FIRE HOSE CABINET	HAVE BEEN VANDALIZED. MAY NOT OPERATE AS INTENDED DURING AN EMERGENCY.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-003-1	S	1	Open	\$3,696	REPLACE EXTERIOR DOOR, FRAME AND HARDWARE	EXIT DOOR NOT ARRANGED TO BE OPENED READILY	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-004-1	S	1	Open	\$56,893	REPLACE COMMERCIAL KITCHEN EXHAUST HOOD WITH FIRE SUPPRESSION.	THE KITCHEN VENTILATION HOOD EXTINGUISHING SYSTEM HAS A NON-COMPLIANCE TAG INDICATING THERE ARE NO AUTOMATIC SHUT-OFFS AND UNPROTECTED GREASE PRODUCING AREA/APPLIANCES.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-005-1	S	1	Open	\$15,580	REPLACE THE KETTLE AND PRESSURE COOKER	NON-OPERATIONAL OR DO NOT OPERATE PROPERLY.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-006-1	S	1	Open	\$2,663	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	HE EXIT DOOR TO THE EXTERIOR IS DIFFICULT TO OPEN PROPERLY. DOOR IS DAMAGED AND STICKS IN FRAME.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-009-1	S	1	Open	\$7,700	INSTALL INTERIOR EMERGENCY, EXIT, OR COMBINATION FIXTURE	DO NOT HAVE EXIT SIGNS OVER THE EXIT DOORS.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-010-1	S	1	Open	\$2,648	REPLACE EXPLOSION PROOF INCANDESCENT FIXTURE	FINISH ROOM - LIGHTING LACKS COVERS FOR SPARK/EXPLOSION PROOF LIGHTS	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-011-1	S	1	Open	\$4,076	REPLACE 3' X 7' WOOD EXTERIOR DOOR, FRAME AND HARDWARE	EXIT DOORS (2) NOT ARRANGED TO BE OPENED READILY (LOCK OR DEVICE REQUIRES KEY, TOOL, SPECIAL KNOWLEDGE).	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	344	A15-02-344-S-013-1	S	1	Open	\$10,870	REPLACE COMMERCIAL DISHWASHER	COMMERCIAL DISHWASHER IN THE KITCHEN IS NON-OPERATIONAL.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	345	A15-02-345-S-001-1	S	1	Open	\$4,000	REPLACE WOOD EXTERIOR DOOR, FRAME AND HARDWARE	EXIT DOOR IS DETERIORATING CAUSING THE DOOR TO STICK IN THE FRAME.	Occupied	Contract Education	School, Middle, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	345	A15-02-345-S-003-1	S	1	Open	\$51,249	UNDER PIN FOUNDATION.	THE BUILDING IS SETTLING CAUSING MANY CRACKS BETWEEN THE WALLS, ROOF, AND FLOORS. WATER LEAKS IN CAUSING DETERIORATION DUE TO WATER DAMAGE AND CREATING MANY HAZARDS THROUGHOUT	Occupied	Contract Education	School, Middle, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	345	A15-02-345-S-005-1	S	1	Open	\$48,245	REPLACE ROOF	THE ROOF LEAKS CAUSING DAMAGE TO THE ROOF, CEILING, WALLS, AND TO ELECTRICAL SYSTEMS. THIS MAY CAUSE SLIP AND ELECTRICAL SHOCK HAZARDS	Occupied	Contract Education	School, Middle, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	345	A15-02-345-S-011-1	S	1	Open	\$11,132	INSTALL STROBE AND HORN, WIRED TO EXISTING SYSTEM	THE FIRE ALARM SYSTEM HAS NO VISUAL DEVICES FOR PEOPLE WITH HEARING DISABILITIES.	Occupied	Contract Education	School, Middle, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	345	A15-02-345-S-012-1	S	1	Open	\$4,247	REPLACE FIRE ALARM CONTROL PANEL	THE FIRE ALARM SYSTEM IS NON-OPERATIONAL	Occupied	Contract Education	School, Middle, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	370	A15-02-370-S-002-1	S	1	Open	\$6,644	REPLACE STAIRS AND RAMP	DETERIORATED AND NON COMPLIANT	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	370	A15-02-370-S-003-1	S	1	Open	\$15,467	RELEVEL MODULAR UNIT	THE FLOOR IN THE CENTER OF THE BUILDING IS HEAVING UP CAUSING DOORS TO STICK IN THEIR FRAMES. THERE ARE LARGE GAPS FORMING BETWEEN THE FLOOR AND WALLS AND ALSO BETWEEN THE FLOOR AND CEILING. THIS MAY WEAKEN THE OVERALL STRUCTURE OF THE BUILDING.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	370	A15-02-370-S-004-1	S	1	Open	\$5,456	REPLACE DRYWALL WITH FIRE RATED DRYWALL	THE INTERIOR WALL FINISH IS UNRATED WOOD PANELING.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	370	A15-02-370-S-005-1	S	1	Open	\$13,471	DEMOLISH, REMOVE AND DISPOSE OF ENTIRE BUILDING	BLDG IS NOT SAFE TO USE. IS TO BE REPLACED WITH NEW PORTABLE BLDG THAT IS TO ARRIVE SEPT. 2004.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-001-1	S	1	Open	\$4,532	REPLACE WOOD RAMP WITH RAILS TO ACCOMMODATE ADA REQUIREMENTS	THE FRONT ENTRY/EXIT STAIRS, LANDINGS, AND RAMP ARE DETERIORATING CAUSING MANY POTENTIAL TRIPPING HAZARDS.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-003-1	S	1	Open	\$3,236	REPLACE ROOF	ROOF IS LEAKING. WATER IS DAMAGING THE CEILING AND THE FLOOR. CAUSING THE BUILDING TO WEAKEN.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-004-1	S	1	Open	\$15,473	RELEVEL TRAILER	THE BUILDING FLOOR IS HEAVING UP IN THE MIDDLE OF THE FLOOR CAUSING LARGE GAPS BETWEEN THE FLOOR AND WALLS AND ALSO THE FLOOR AND CEILING. WATER LEAKS INTO THE BUILDING AS A RESULT. THE NORTH AND SOUTH WALLS APPEAR TO BE SAGGING ALSO. CEILING MAYFALL.	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-005-1	S	1	Open	\$5,855	REPLACE WINDOWS AND INSTALL EMERGENCY LIGHTING	HE WINDOWS ARE BOARDED UP DUE TO BROKEN GLASS FROM THE WINDOWS, THERE IS NO NATURAL LIGHTING ENTERING THE BUILDING AND THERE ARE NO EMERGENCY LIGHTS	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-006-1	S	1	Open	\$2,688	REPLACE WOOD STAIRS	THERE ARE NO STAIRS AND LANDINGS AT BOTH NORTH EXITS	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	371	A15-02-371-S-007-1	S	1	Open	\$6,774	REPLACE FIRE ALARM SYSTEM	THERE ARE NO MANUAL PULL STATIONS FOR THE FIRE ALARM SYSTEM. SYSTEM APPEARS TO BE INCOMPLETE AND NON-OPERATIONAL	Occupied	Contract Education	School, Secondary, Day	Poor	S-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-002-1	M	1	Open	\$7,269	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 6' HIGH	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-004-1	M	1	Open	\$21,084	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-007-1	M	1	Open	\$8,167	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 6' HIGH	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-009-1	M	1	Open	\$49,839	INSTALL FOOTBALL OR SOCCER FIELD LIGHTING, PER POLE	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-010-1	M	1	Open	\$6,448	REPLACE WALKWAY POLE AND LUMINAIRE, UP TO 200W INCANDESCENT	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-011-1	M	1	Open	\$32,659	REPLACE ASPHALT EXERCISE TRACK	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-012-1	M	1	Open	\$284,249	RESURFACE TENNIS COURT, 1/4" RUBBER, VINYL OR URETHANE	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-013-1	M	1	Open	\$42,620	REPLACE ASPHALT BASKETBALL COURT	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-019-1	M	1	Open	\$135,643	The front parking lot is aged/deteriorated and in need of replacement.	The parking lot is original construction and in need of replacement.				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-020-1	M	1	Open	\$60,803	Existing back parking lot is in need of milling, grading, resurfacing and all associated work.	The parking lot is original construction and in need of replacement.				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-022-1	M	1	Open	\$5,853	AERATE, FERTILIZE AND OVERSEED BASEBALL FIELD	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-026-1	M	1	Open	\$21,472	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-M-028-1	M	1	Open	\$83,150	CONSTRUCT TENNIS COURTS	AME Requested Backlog				N/A	M-1

Region	Loc #	Location Name	Blgd Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-S-001-1	S	1	Open	\$15,523	REPLACE ROOF	CEILING LEAKING AND HAS MOLD CREATING HAZARD				N/A	S-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-S-002-1	S	1	Open	\$2,507	REPLACE CHAIN LINK FENCE AND POSTS	HERE IS A PLAYGROUND BETWEEN THE MAIN ELEMENTARY SCHOOL CAMPUS AND THE FIRE STATION BUILDING WHICH AT RECESS TIME, KIDS CLIMB ON TOP OF A POWER TRANSFORMER AND SOMETIMES CLIMB ON THE ROOF OF THE FIRE STATION. CONCRETE PLAYGROUND COURT IS BREAKING UP AND HAS HOLES. MAY CAUSE INJURY TO STUDENTS.				N/A	S-1
Great Plains Region	A15-02	Lower Brule Day School	Ground	A15-02-X01-S-003-1	S	1	Open	\$24,150	REPLACE CONCRETE PAVEMENT.					N/A	S-1
Great Plains Region	A04-03	Mandaree Day School	Ground	A04-03-X01-M-017-1	M	1	Open	\$7,695	Install warning signage and fence ground ring	Mindbank inspection				N/A	M-1
Great Plains Region	A04-03	Mandaree Day School	Ground	A04-03-X01-M-018-1	M	1	Open	\$3,482	Develop compound	Mindbank inspection				N/A	M-1
Great Plains Region	A04-03	Mandaree Day School	Ground	A04-03-X01-M-020-1	M	1	Open	\$3,094	Install site ground ring	Mindbank inspection				N/A	M-1
Great Plains Region	A04-03	Mandaree Day School	Ground	A04-03-X01-M-031-1	M	1	Open	\$6,982	REPLACE BASKETBALL GOAL	AME Requested Backlog				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-006-1	M	1	Open	\$25,068	REPLACE FLUORESCENT FIXTURE, 2' X 4', RECESSED, GRID MOUNT, UP TO 4-40 WATT LAMPS, INTERIOR	FACCOM Inspected by AME. BALL 17-MAY-99	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-007-1	M	1	Open	\$5,521	REPLACE 4" THICK WOOD PLANK ROOF DECKING	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-020-1	M	1	Open	\$25,816	REPLACE BASEMENT WALLS THROUGHOUT, BASED ON FOOTPRINT OF STRUCTURE	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-022-1	M	1	Open	\$3,332	REPLACE EXTERIOR, WALL PACK, HID UP TO 175 WATT	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-023-1	M	1	Open	\$9,893	REPLACE COMMERCIAL WATER HEATER, ELECTRIC, 80 TO 100 GALLONS	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-M-025-1	M	1	Open	\$69,019	REPLACE INDOOR AIR-HANDLING UNIT, SINGLE ZONE, UP TO 2,000 CFM	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-S-001-1	S	1	Open	\$19,257	REPLACE FIRE ALARM CONTROL PANEL, ADDRESSABLE	existing system does not have visual devices	Occupied	Grant Education	School, Elementary, Boarding	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	43	A02-05-43-S-003-1	S	1	Open	\$6,738	REPLACE EMERGENCY AND EXIT LIGHT COMBINATION	Some exit signs and emergency lights are not operational	Occupied	Grant Education	School, Elementary, Boarding	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	49	A02-05-49-M-012-1	M	1	Open	\$7,230	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	FACCOM Inspected by AME. CHRISMAN 17-MAY-99	Occupied	Grant Education	Dormitory, School	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	49	A02-05-49-S-002-1	S	1	Open	\$3,462	REPLACE EXHAUST FAN	THE VENTILATION SYSTEM IN THE RESTROOMS IS NOT ADOQUATE	Occupied	Grant Education	Dormitory, School	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	50	A02-05-50-M-028-1	M	1	Open	\$4,035	REPLACE FIRE ALARM CONTROL PANEL, ADDRESSABLE	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	50	A02-05-50-M-029-1	M	1	Open	\$93,405	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 8-7/8" HIGH 1"- 1-1/4" COPPER TUBE	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	50	A02-05-50-S-001-1	S	1	Open	\$32,382	REPLACE FIRE RATED DOUBLE DOOR SYSTEM IN CORRIDOR	missing fire rated doors	Occupied	Grant Education	Dormitory, School	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	50	A02-05-50-S-002-1	S	1	Open	\$7,977	Replace interior doors at nurses office and little boys break room	existing opens against the means of egress and has knob type hardware	Occupied	Grant Education	Dormitory, School	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	50	A02-05-50-S-003-1	S	1	Open	\$9,031	REPLACE CENTRIFUGAL SUPPLY OR EXHAUST FAN, 5,080 CFM, 20" DIAMETER, IN LINE, COMPLETE WITH DISCONNECT SWITCH	mold and mildew build up in room perhaps causing illness)	Occupied	Grant Education	Dormitory, School	Poor	S-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-012-1	M	1	Open	\$581,580	REPLACE UNDERGROUND STEAM AND CONDENSATE PIPING IN TRENCH BETWEEN BUILDINGS, UP TO 500 LF OF 6" STEAM PIPE	There is a leak in the steam lines that need to be repaired immediately. In order to prevent further damage and energy loss.				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-015-1	M	1	Open	\$47,473	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-017-1	M	1	Open	\$2,873	REPLACE FIRE HYDRANT, 8" DEEP	AME Requested Backlog				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-020-1	M	1	Open	\$450,000	Demolition, improvement and Repair associated with Infrastructure.	Needed for completion of project.				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-027-1	M	1	Open	\$17,350	REPLACE FIRE HYDRANT, 6" TO 8" DEEP	AME Requested Backlog				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-031-1	M	1	Open	\$34,265	Provide all site work for relocation of portable building from Nah-ah-Shing, Minnesota.	Needed for Education Program				N/A	M-1
Great Plains Region	A02-05	Pierre Indian Learning Center	Ground	A02-05-X01-M-032-1	M	1	Open	\$82,980	Provide all site work for installation of portable building from Kayenta, AZ, with steps and ramps, including utilities.	Needed for education program.				N/A	M-1
Great Plains Region	A10-03	Rock Creek Grant School (Bullhead)	Ground	A10-03-X01-M-008-1	M	1	Open	\$4,347	REMOVE ABOVE GROUND FUEL OIL STORAGE TANK, UP TO 1000 GALLON	AME Requested Backlog				N/A	M-1
Great Plains Region	A10-03	Rock Creek Grant School (Bullhead)	Ground	A10-03-X01-M-009-1	M	1	Open	\$19,073	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog				N/A	M-1
Great Plains Region	A10-03	Rock Creek Grant School (Bullhead)	Ground	A10-03-X01-S-001-1	S	1	Open	\$5,887	REPLACE CONCRETE SIDEWALK	SIDEWALK AROUND THE SCHOOL BUILDINGS ARE DETERIORATING CAUSING MANY POTENTIAL TRIPPING HAZARDS.				N/A	S-1
Great Plains Region	A10-03	Rock Creek Grant School (Bullhead)	Ground	A10-03-X01-S-002-1	S	1	Open	\$2,603	REPLACE CONCRETE SIDEWALK	WALK AT THE SOUTHWEST EXIT DISCHARGE FROM THE MAIN SCHOOL BUILDING IS DETERIORATING. TRIP HAZARDS.				N/A	S-1
Great Plains Region	A07-10	Sicangu Owayawa Oil (Rosebud Dormitory)	1001	A07-10-1001-M-015-1	M	1	Open	\$655,603	Existing roof is aged/deteriorated and in need of replacement.	The existing roof is in need of replacement.	Occupied	BIA Education	Dormitory, School	Poor	M-1
Great Plains Region	A07-10	Sicangu Owayawa Oil (Rosebud Dormitory)	1001	A07-10-1001-M-030-1	M	1	Open	\$25,695	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment. Current boiler does not have properly sized combustion air openings, need to install a motorized dampers in the combustion air opening, a chemical feeder for boiler and replace portions of the branch wiring and there are no signs for the boiler shut-off switch there are also no fire AVV devices and pull station at each door.	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment.	Occupied	BIA Education	Dormitory, School	Poor	M-1
Great Plains Region	A18-02	Theodore Jamerson Elementary School	900045	A18-02-900045-S-001-1	S	1	Open	\$6,085	Modify door to open with egress travel but open against the guard railing.	Door opens against egress travel	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A18-02	Theodore Jamerson Elementary School	900045	A18-02-900045-S-002-1	S	1	Open	\$3,367	Replace fire alarm control panel	trouble light is on indicating a possible failure	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A18-02	Theodore Jamerson Elementary School	Ground	A18-02-X01-M-008-1	M	1	Open	\$2,945	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog				N/A	M-1
Great Plains Region	A09-05	Tiospa Zina Tribal School	900000G	A09-05-900000G-S-005-1	S	1	Open	\$2,941	FIRE ALARM SYSTEM	FACCOM	Occupied	Grant Education	Shop, Multi-Purpose	Poor	S-1
Great Plains Region	A04-05	White Shield School	450	A04-05-450-M-004-1	M	1	Open	\$5,238	REPLACE DRYWALL CEILING, OVER 5 SF PER LOCATION	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Great Plains Region	A04-05	White Shield School	Ground	A04-05-X01-M-024-1	M	1	Open	\$5,734	REPLACE HORIZONTAL LIQUID PROPANE TANK, UP TO 275 GALLONS	AME Requested Backlog				N/A	M-1
Great Plains Region	A04-05	White Shield School	Ground	A04-05-X01-S-001-1	S	1	Open	\$32,490	REPLACE CONCRETE SIDEWALK, OVER 8 SF AND/OR DETERIORATING AROUND THE SCHOOL CAMPUS AREA AND THE HOUSING AREA IN WHICH TRIP HAZARDS ARE CREATED					N/A	S-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-016-1	M	1	Open	\$268,653	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-017-1	M	1	Open	\$13,657	REPLACE WATER TREATMENT SYSTEM	Inspected by AME: BORKMAN 21-JUN-1999	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-028-1	M	1	Open	\$17,624	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment. Lacks motorized dampers in the combustion air opening and interlock with the operation of the boilers. Need to provide signs for the boiler shut-off switches. Room lacks LED exit luminaires and emergency bugaya luminaires. Boiler 3 repair/replace boiler tube.	Per TSA Task Order No. 20-A, Boiler Inspections and Boiler Room Assessment.	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-030-1	M	1	Open	\$3,807	INSTALL DUCTLESS SPLIT SYSTEM, UP TO 1-1/2 TONS	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-031-1	M	1	Open	\$6,136	REPLACE FLANGED 3-WAY VALVE AND ACTUATOR, 8" - 8"	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-032-1	M	1	Open	\$6,845	REPLACE PUMP, BASE-MOUNTED, OVER 1-1/2 UP TO 5 HP	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-033-1	M	1	Open	\$596,982	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 1531 TO 2170 MBH	Inspected by AME: BORKMAN 21-JUN-1999	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-M-040-1	M	1	Open	\$1,757,782	This is ARRA Project No. BYA08070 - The existing 2-pipe heating system is 48 years old and is in need of replacement.	The existing 2-pipe heating system is aged and in need of replacement.	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-S-001-1	S	1	Open	\$14,165	REPLACE DOOR CLOSER, RACK AND PINION SURFACE MOUNTED	DOOR CLOSURES MISSING OR DISCONNECTED	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-S-004-1	S	1	Open	\$9,709	REPLACE CARPET	TEARINGS AND COMING LOOSE MAY CAUSE POSSIBLE TRIP HAZARDS	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-S-007-1	S	1	Open	\$20,189	REPLACE PANIC HARDWARE	MISSING/DAMAGED	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-S-008-1	S	1	Open	\$6,261	REPLACE EXIT DOORS	THE NORTH EXIT DOORS FROM THE WEST WING ARE DAMAGED AND ARE DIFFICULT TO OPEN	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-06	Wounded Knee District School	2300	A06-06-2300-S-009-1	S	1	Open	\$22,072	REPLACE WOOD FIRE DOOR AND CLOSURE HARDWARE, WITH UP TO 45 MINUTE RATING IN CORRIDOR, 8' X 7'	EXISTING DOORS NOT FIRE RATED OR DIFFICULT TO OPEN	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-M-008-1	M	1	Open	\$2,974	REPLACE ENGRAVED WOOD SIGN AND POST, OVER 6 UP TO 16 SF					N/A	M-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-M-011-1	M	1	Open	\$7,059	REPLACE CONCRETE CURB AND GUTTER, RADIUS					N/A	M-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-S-002-1	S	1	Open	\$82,880	INSTALL AN ORDINARY HAZARD SPRINKLER SYSTEMS AT 5 PORTABLE BUILDINGS	BUILDING IS SPRINKLED AT LIGHT HAZARD				N/A	S-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-S-003-1	S	1	Open	\$4,888	INSTALL INTERIOR EMERGENCY, EXIT, OR COMBINATION FIXTURE IN PORTABLE BUILDINGS	BUILDING EXIT LIGHT INOPERABLE				N/A	S-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-S-005-1	S	1	Open	\$3,349	REPLACE DOOR CLOSERS AT PORTABLE BUILDINGS	FIRE DOOR(S) ARE NOT SELF-CLOSING (DO NOT HAVE CLOSER(S).				N/A	S-1
Great Plains Region	A06-06	Wounded Knee District School	Ground	A06-06-X01-S-006-1	S	1	Open	\$8,154	REPLACE ASPHALT PAVING	(THERE IS A STREET IN FRONT OF THE MAIN SCHOOL BUILDING THAT HAS POT HOLES THAT MAY CAUSE TRIP OR OTHER HAZARDS				N/A	S-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	22	F53-13-22-F-001-2	F	2	Open	\$101,003	Bring corridor walls up to Fire code. From foundation slab to ceiling. With possible replacement of wooden studs with steel studs and widen corridors where needed.	needs widening.	Occupied	BIA Education	School, Secondary, Day	Poor	F-2
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	22	F53-13-22-M-030-1	M	1	Open	\$73,766	CLEAN BUILDING METAL DUCT SYSTEM	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	22	F53-13-22-M-067-1	M	1	Open	\$351,900	Replace all demolished electrical, telephone and data cabling and raceways through remodeled and replaced high school walls.	High School lacks adequate classroom spaces and electrical infrastructure.	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	22	F53-13-22-M-069-1	M	1	Open	\$1,200,600	HVAC System is inadequate to provide heating, cooling, and fresh air to the high school.	Inadequate and aged system does not provide necessary heating, cooling or fresh air flow to classrooms and offices.	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	22	F53-13-22-M-070-1	M	1	Open	\$29,082	REPLACE INTERCOM REMOTE STATION	No building wide intercom or messaging system exists in the building to provide emergency warnings or directions	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	25	F53-13-25-M-002-1	M	1	Open	\$12,818	REPLACE CARPET	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	25	F53-13-25-M-003-1	M	1	Open	\$201,485	Replace all metal clad interior walls and renovate with fire rated materials, redesign floor plan, rewrite Demo and replace HVAC system to provide appropriate heating, cooling and ventilation for educational space	Educational space is formerly a garage, not suitable classroom space	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	25	F53-13-25-M-006-1	M	1	Open	\$105,800	CLEAN AND REPLACE CAULK IN EXTERIOR WALL JOINTS/FLASHING	Inadequate heating, cooling and ventilation to this educational space	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	25	F53-13-25-M-007-1	M	1	Open	\$3,146	REPLACE INSULATED STEEL SANDWICH PANELS, SINGLE STORY	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	25	F53-13-25-M-008-1	M	1	Open	\$16,529	Install and ground TVSS, exterior lighting and safety climb tower	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Day	Poor	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-009-1	M	1	Open	\$2,838	Install ground buss, ground bars and ground kits	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-010-1	M	1	Open	\$3,326	Install ground kits on cable	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-011-1	M	1	Open	\$2,615	Install ground kits on cable	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-012-1	M	1	Open	\$4,865	Install tes bridge	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-013-1	M	1	Open	\$2,653	Repair tower grounding	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-014-1	M	1	Open	\$2,504	Reroute cable	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-015-1	M	1	Open	\$2,504	Replace antenna mounts	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-016-1	M	1	Open	\$2,690	Repair cable support hardware	Mindbank Inspection				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-017-1	M	1	Open	\$3,360	Install site ground ring and warning signage	Mindbank Inspection				N/A	M-1

Region	Loc #	Location Name	Blgd Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-018-1	M	1	Open	\$11,667	REPLACE CHAIN LINK FENCE AND POSTS, RESIDENTIAL, 8' HIGH	AME Requested Backlog				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-030-1	M	1	Open	\$6,760	RESURFACE TENNIS COURT	AME Requested Backlog				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-031-1	M	1	Open	\$5,730	RESURFACE BASKETBALL COURT USING ACRYLIC EMULSION	AME Requested Backlog				N/A	M-1
Midwest Region	F53-13	Bug-O-Nay-Ge-Shig School	Ground	F53-13-X01-M-041-1	M	1	Open	\$4,287	REPLACE WOOD MECHANICALLY STABILIZED RETAINING WALL	AME Requested Backlog				N/A	M-1
Navajo Region	N34-27	Alamo Navajo School	Ground	N34-27-X01-M-012-1	M	1	Open	\$3,589	REPLACE ALUMINUM LIGHT POLE, OVER 14' TO 20'	AME Requested Backlog				N/A	M-1
Navajo Region	N34-27	Alamo Navajo School	Ground	N34-27-X01-M-036-1	M	1	Open	\$3,995	REPLACE STEEL PIPE RAIL, 1-1/4" DIAMETER	AME Requested Backlog				N/A	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-M-002-1	M	1	Open	\$60,992	REPLACE EVAPORATIVE COOLER UP TO 4215 CFM, 3/4 HP	Inspected by AME: PETIT 19-APR-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-M-009-1	M	1	Open	\$131,669	REPLACE APARTMENT OR DORMITORY PIPING AND INSULATION FOR 2 PIPE HEATING SYSTEM, STEAM/HOT WATER	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-002-1	S	1	Open	\$18,985	Sprinkler system at control valve not sounding alarm system.	Sprinkler system at control valve not sounding alarm system.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-003-1	S	1	Open	\$11,351	Replace Exhaust Fans	To comply with the Uniform Mechanical Code: Ventilation.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-005-1	S	1	Open	\$25,056	Domestic Water Supply Piping	To meet the Uniform Plumbing Code and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-006-1	S	1	Open	\$26,887	REPLACE WALL/FLOOR MOUNTED WATER CLOSET, TANK TYPE	To meet the Health Code Compliance guidelines and is a deficiency citation in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-008-1	S	1	Open	\$13,622	REPLACE FIRE ALARM SYSTEM, COLLEGE DORMITORY	To meet the National Fire Codes - NFPA Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-010-1	S	1	Open	\$8,078	REPLACE DUPLEX CONDENSATE PUMPS, MOTOR, FLOAT SWITCH, RECEIVER, 3/4 HP, 15 GPM	To meet the Uniform Plumbing Code Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-013-1	S	1	Open	\$2,637	Replace exit lights throughout the building.	The exit lights are old and deteriorated throughout the building (23).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-015-1	S	1	Open	\$2,943	Replace emergency light fixtures.	The emergency lights in the building are old and deteriorated throughout the building (23).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-016-1	S	1	Open	\$2,648	Replace 23 toilet bowl flanges.	The flanges are old and deteriorated and in need of replacement (23).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1204	N32-13-1204-S-017-1	S	1	Open	\$5,400	Post Indicating Valve	To properly shut off valve and to meet BIE requirements.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-M-013-1	M	1	Open	\$43,731	REPLACE EVAPORATIVE COOLER UP TO 4215 CFM, 3/4 HP	Inspected by AME: PETIT 19-APR-1999	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-002-1	S	1	Open	\$18,985	Sprinkler system at control valve not sounding alarm system.	Sprinkler system at control valve not sounding alarm system.	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-003-1	S	1	Open	\$93,654	Replace thin and/or plexi-glass windows.	To be in compliance with the National Fire Codes - NFPA Compliance	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-005-1	S	1	Open	\$13,622	REPLACE FIRE ALARM SYSTEM, COLLEGE DORMITORY	To meet the National Fire Codes - NFPA Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-006-1	S	1	Open	\$11,084	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	To meet the Accessibility (ADA) Code Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-007-1	S	1	Open	\$8,078	REPLACE DUPLEX CONDENSATE PUMPS, MOTOR, FLOAT SWITCH, RECEIVER, 3/4 HP, 15 GPM	To meet the Uniform Plumbing Code Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-010-1	S	1	Open	\$2,637	Exit Lights	The exit lights are old and deteriorated throughout the building (23).	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-011-1	S	1	Open	\$2,835	Emergency Lights need replacement.	The emergency lights in the building are old and deteriorated throughout the building (23).	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-012-1	S	1	Open	\$2,648	Toilet bowl flanges.	The flanges below the toilet bowl are old and deteriorated and in need of replacement (23).	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-013-1	S	1	Open	\$5,400	Post Indicating Valve	To properly shut off valve and to meet BIE requirements.	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-020-1	S	1	Open	\$265,729	REPLACE HEATING SYSTEM EQUIPMENT, BOILER, PIPING AND FIN TUBE RADIATORS, REMOVE ASBESTOS PIPE INSULATION	Inspected by AME: PETIT 19-APR-1999	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1205	N32-13-1205-S-059-1	S	1	Open	\$7,569	REPLACE PANIC HARDWARE	FACCOM	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-M-009-1	M	1	Open	\$131,669	REPLACE APARTMENT OR DORMITORY PIPING AND INSULATION FOR 2 PIPE HEATING SYSTEM, STEAM/HOT WATER	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-M-014-1	M	1	Open	\$62,675	REPLACE EVAPORATIVE COOLER 4215 UP TO 8300 CFM, 1-1/2 HP	Inspected by AME: PETIT 19-APR-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-003-1	S	1	Open	\$18,985	Sprinkler system at control valve not sounding alarm system.	Sprinkler system at control valve not sounding alarm system.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-004-1	S	1	Open	\$65,716	Connect to new system when funding is available for building replacement.	Connect to new system when funding is available for building replacement.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-005-1	S	1	Open	\$26,887	REPLACE WALL/FLOOR MOUNTED WATER CLOSET, TANK TYPE	To meet the Health Code Compliance guidelines and is a deficiency citation in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-007-1	S	1	Open	\$37,335	REPLACE TYPE L COPPER PIPE, 1" TO 1-1/4"	To meet the Uniform Plumbing Code and is cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-008-1	S	1	Open	\$4,647	REPLACE 3' X 7' FIRE DOOR IN CORRIDOR, INCLUDING FRAME, UP TO 45 MINUTES	To meet the National Fire Code guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-009-1	S	1	Open	\$13,622	REPLACE FIRE ALARM SYSTEM, COLLEGE DORMITORY	To meet the National Fire Codes - NFPA Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-010-1	S	1	Open	\$11,084	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	To meet the Accessibility (ADA) Code Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-011-1	S	1	Open	\$8,078	REPLACE DUPLEX CONDENSATE PUMPS, MOTOR, FLOAT SWITCH, RECEIVER, 3/4 HP, 15 GPM	To meet the Uniform Plumbing Code Compliance guidelines and is a cited deficiency in the annual Safety Inspection.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-014-1	S	1	Open	\$2,637	Exit lights need replacement.	The exit lights are old and deteriorated throughout the building (23).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-015-1	S	1	Open	\$2,835	Emergency lights need replacement.	The emergency lights in the building are old and deteriorated throughout the building (23).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-016-1	S	1	Open	\$2,648	Toilet bowl flanges need replacement.	The flanges below the toilet bowl are old and deteriorated and in need of replacement.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-017-1	S	1	Open	\$5,400	Post Indicating Valve	To properly shut off valve and to meet BIE safety requirements.	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Blyazh Community School (Shiprock, NM)	1206	N32-13-1206-S-018-1	S	1	Open	\$11,351	Replace Exhaust Fans.	To comply with the Uniform Mechanical Code Compliance: Ventilation.	Occupied	BIA Education	Dormitory, School	Poor	S-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	1206	N32-13-1206-S-022-1	S	1	Open	\$10,031	Replace old panic hardware on doors.	To comply with the National Fire Codes - NFPA: Life Safety Code (101).	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	1340	N32-13-1340-S-002-1	S	1	Open	\$61,830	Connect fire alarm to new system.	Safety Inspection Deficiency.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	1340	N32-13-1340-S-003-1	S	1	Open	\$66,312	Fire alarm system not connected to the central dispatch station.	Fire alarm system not connected to the central dispatch station.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	Ground	N32-13-X01-M-015-1	M	1	Open	\$6,896	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 6' HIGH	AME Requested Backlog			N/A	M-1	
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	Ground	N32-13-X01-M-018-1	M	1	Open	\$10,917	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 6' HIGH	AME Requested Backlog			N/A	M-1	
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	Ground	N32-13-X01-M-022-1	M	1	Open	\$6,540	CHIP, CLEAN AND PATCH, CONCRETE PAVEMENT	AME Requested Backlog			N/A	M-1	
Navajo Region	N32-13	Atsa Biyaazh Community School (Shiprock, NM)	Ground	N32-13-X01-S-020-1	S	1	Open	\$34,563	REPLACE FIRE ALARM SYSTEM, SENIOR HIGH SCHOOL	FACCOM			N/A	S-1	
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-M-010-1	M	1	Open	\$43,047	REPLACE WINDOW WALL	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-M-014-1	M	1	Open	\$12,179	REPLACE WINDOW WALL	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-M-019-1	M	1	Open	\$32,130	Building needs HVAC	Install new units	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-M-020-1	M	1	Open	\$6,686	REPLACE COMMERCIAL DISHWASHER	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-S-002-1	S	1	Open	\$41,584	REPLACE PLUMBING SYSTEM IN THE 6,808 GSF KITCHEN. BUILDING INCLUDES A COMMERCIAL KITCHEN, CAFETERIA, GYM, FOOD STORAGE AND 3 RESTROOMS.	Severity Leaking	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N32-03	Aztec Dormitory	826	N32-03-826-S-003-1	S	1	Open	\$31,921	Replace Windows	Energy Inefficient	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-019-1	M	1	Open	\$12,342	REPLACE/INSTALL INTERCOM SYSTEM	communication is needed for school lock downs, emergency services, and daily operations.	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-023-1	M	1	Open	\$26,776	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-024-1	M	1	Open	\$3,169	Server room needs to have controlled environment	Server enviro control	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-025-1	M	1	Open	\$30,676	REPLACE WALK-IN COOLER, 8' X 20'	Units outdated and are not in safe operating condition	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-026-1	M	1	Open	\$3,325	Sidewalk in front has deteriorated and is dangerous	Sidewalk deteriorated	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-M-036-1	M	1	Open	\$17,143	Gym floor needs new tile due to water and settling of floor	New gym tile	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	700	N35-23-700-S-002-1	S	1	Open	\$5,840	REPLACE FIRE ALARM CONTROL PANEL, ADDRESSABLE	INDICATES TROUBLE MODE	Occupied	BIA Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-23	Black Mesa Community School	703	N35-23-703-M-008-1	M	1	Open	\$3,960	REPLACE ROLLED ROOFING, 300 SF AND OVER	AME Requested Backlog	Occupied	Grant Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-23	Black Mesa Community School	703	N35-23-703-S-010-1	S	1	Open	\$4,354	INSTALL INTERIOR EMERGENCY, EXIT, OR COMBINATION FIXTURE	FACCOM	Occupied	Grant Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-23	Black Mesa Community School	Ground	N35-23-X01-M-002-1	M	1	Open	\$50,573	REPLACE PROPANE TANK, 5000 GAL	Upgrade tank farm			N/A	M-1	
Navajo Region	N35-23	Black Mesa Community School	Ground	N35-23-X01-M-017-1	M	1	Open	\$11,663	REPLACE CONCRETE SIDEWALK, OVER 8 SF	Old sealant cracked due to exposure			N/A	M-1	
Navajo Region	N35-23	Black Mesa Community School	Ground	N35-23-X01-M-018-1	M	1	Open	\$26,251	REPLACE SEWER PIPE, PVC, SDR 35, 8", UP TO 6 FT DEEP	Replace sewer mains			N/A	M-1	
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-F-001-2	F	2	Open	\$174,551	REPLACE WET PIPE SPRINKLER FIRE PROTECTION SYSTEM, ORDINARY HAZARD, ONE FLOOR, FROM 10,000 TO 50,000 SF	Upgrade fire sprinkler system	Occupied	BIA Education	Multi-Purpose	Poor	F-2
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-001-1	M	1	Open	\$40,553	REPLACE BOILER BURNER, 750 UP TO 3000 MBH	FACCOM inspected by AME: BENDER 21-JUN-1999	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-010-1	M	1	Open	\$36,761	REPLACE PANELBOARD, 225 AMPS, 3 PHASE, 4 WIRE, 277/480V, UP TO 42 CIRCUITS	Upgrade electrical system and distribution panels due to overloads / power surges.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-011-1	M	1	Open	\$198,799	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	To replace E.P.D.M. roof membrane to a E.P. roof membrane due to settlement of the building and causing separation.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-012-1	M	1	Open	\$36,526	THEATRICAL STATIONARY SPOT LIGHT, UP TP 800 WATT	Upgrading old fixtures	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-013-1	M	1	Open	\$35,371	REPLACE HID, HIGHBAY FIXTURE, UP TO 400 WATT, UP TO 40' ABOVE GRADE	Upgrading gym lighting	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-014-1	M	1	Open	\$146,587	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 545 TO 882 MBH	Upgrade boilers	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-017-1	M	1	Open	\$100,283	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	Restucco walls	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-035-1	M	1	Open	\$8,212	REPLACE AIR COMPRESSOR SINGLE STAGE COMPRESSOR UP TO 2 HP	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-040-1	M	1	Open	\$166,145	Sunport Shade System for Playgrounds.	To provide adequate shade for the safety of the students.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-041-1	M	1	Proposed	\$88,502	To replace air-conditioning units.	Upgrade swampcoolers with roof top air conditioning units for better air quality for students and staff.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-043-1	M	1	Open	\$393,984	REPLACE LIGHTING AND BRANCH WIRING THROUGHOUT THE 34,741 GSF BUILDING. COST SOURCE RS MEANS SF COST 2008, PAGE 199	Energy upgrade	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-047-1	M	1	Open	\$461,828	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Plumbing has deteriorated	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-051-1	M	1	Open	\$169,535	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 10 UP TO 15 TON	The heating, cooling and ventilation system are out of compliance, and needs to be upgraded for comfort zone.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-054-1	M	1	Open	\$14,407	REPLACE SHELL AND TUBE HEAT EXCHANGER, HOT WATER OR STEAM, 64 - 96 GPM	The heat exchanger needs to be replaced due to deteriorating and scaling.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-059-1	M	1	Open	\$30,443	REPLACE COPPER CABLE, #4/0	TO PROTECT THE HIGH RISE GYMNASIUM BUILDING FROM LIGHTNING.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-057-1	M	1	Open	\$48,562	REPLACE CERAMIC WALL TILE	THE CERAMIC TILES ARE OLD AND DETERIORATED IN ROOMS 110A, 110, 114, 114A, 115, 115B AND 115A.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-058-1	M	1	Open	\$22,170	TO REPLACE CEILING IN THE CORRIDORS, FOYER AND LOBBY.	TO REPLACE THE CEILING IN CORRIDOR, 144, 122, 131, 121, 152, FOYER, 153, 101 AND LOBBY 102, (AGED AND DETERIORATED).	Occupied	BIA Education	Multi-Purpose	Poor	M-1

Region	Loc #	Location Name	Blg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-059-1	M	1	Open	\$128,169	TO UPGRADE (H.V.A.C.) SYSTEM IN THE LIBRARY.	TO STAY IN COMPLIANCE WITH THE LIFE SAFETY CODE (101) SECTION 7-2.1	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-060-1	M	1	Open	\$4,151	UPGRADE NETWORK HUBS FOR COMPUTERS AND COMMUNICATION.	TO REPLACE NETWORK HUBS FOR COMPUTERS AND COMMUNICATION, (OBSOLETE AND DETERIORATED).	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-061-1	M	1	Open	\$280,888	TO REPLACE THE EXTERIOR WALL ON THE WEST SIDE OF THE BUILDING.	TO REPLACE THE EXTERIOR WALL ALONG THE WEST SIDE OF THE BUILDING, THE ROOMS ARE 123,138,140,137,142,144, AND 143 DUE TO WALL MOVING OUTWARD.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-062-1	M	1	Open	\$148,014	To replace metal floor deck and concrete.	To replace floor deck due to settlement of the building.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-064-1	M	1	Open	\$31,777	To support steel columns that are supporting the gymnasium ceiling and roof.	Install vertical steel columns to support the columns inside the gymnasium, due to settlement of the building.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-065-1	M	1	Open	\$195,360	To replace the exterior wall on the southwest side of the building	To replace the exterior walls along the southwest side of the building, the rooms are 108,113,110,116A,115,115A,118,and 119, due to wall moving outward.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-066-1	M	1	Open	\$12,890	REPLACE 2" X 12" ROOF JOISTS/RAFTERS (4/12 PITCH OR LESS)	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-067-1	M	1	Open	\$947,429	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-068-1	M	1	Open	\$3,492	REPLACE DOWNSPOUT, GALVANIZED STEEL, UP TO 8" IN DIAMETER	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-069-1	M	1	Open	\$2,733	REPLACE INSULATED CLEAR WINDOW GLASS, SET WITH GASKET	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-071-1	M	1	Open	\$8,694	REPLACE STAGE CURTAIN, VELOUR, MEDIUM WEIGHT	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-073-1	M	1	Open	\$98,895	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 7-1/2 TON UP TO 10 TON	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-075-1	M	1	Open	\$97,996	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 7-1/2 TON UP TO 10 TON	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-076-1	M	1	Open	\$7,227	REPLACE CIRCULATING PUMP, BASE-MOUNTED, OVER 1-1/2 UP TO 5 HP.	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-077-1	M	1	Open	\$2,553	INSTALL 1" POWER POLE WITH 4 - 120V RECEPTACLES, UP TO 25' CIRCUIT LENGTH	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-078-1	M	1	Open	\$393,129	To reveal (-) negative slope on the existing floor and foundation.	To stay in compliance with the life safety code .	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-079-1	M	1	Open	\$16,232	REPLACE ROOFTOP VENTILATOR, RECTANGULAR, ALUMINUM/GALVANIZED 48" X 80"	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-080-1	M	1	Open	\$127,011	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-081-1	M	1	Open	\$11,275	Install a 30 KVA Transformer for the server Rm, and also the computer Rm.	To install 30 KVA transformers to the server Rm, and the Computer Rm, to serve 10 station for the students. At current the Rms are overloading the Panel which is causing the breakers to trip. The electrician will install two Transformers and panels to serve the overcurrent panels, and to stay in compliance with the NFPA- National Fire Protection Association- Life Safety & Fire Codes.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-083-1	M	1	Open	\$3,974	To replace duct in the Gymnasium.	To replace the ducts in the Gymnasium and to stay in compliance with E.P.A., Indoor Air Quality.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-084-1	M	1	Open	\$30,320	TO REPLACE T-TRACK FOR SUSPENDED CEILING.	CEILING IS WATER DAMAGE FROM ROOF LEAKS, AND NEED TO BE IN COMPLIANCE WITH NFPA 101, LIFE SAFETY CODE.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-085-1	M	1	Open	\$81,671	New exterior doors, frames and hardware needed in main hall, gym and admin areas are needed	Old doors not repairable	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-M-086-1	M	1	Open	\$40,000	Building has settled and foundation and soil analysis needs to be performed by a professional firm	Foundation has settled	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-S-002-1	S	1	Open	\$11,466	REPLACE BASKETBALL SCOREBOARD, ONE SIDED	School function	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-S-003-1	S	1	Open	\$8,803	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, UP TO 3 TON	Personnel comfort	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-S-004-1	S	1	Open	\$3,872	REPLACE INTERCOM MASTER STATION, 25 BRANCH CAPABILITY	Communications need	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-S-005-1	S	1	Open	\$7,592	Need new toilet partitions	Personnel and ADA compliant	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1000	N35-20-1000-S-066-1	S	1	Open	\$2,214	FIRE RATE DOORS	FACCOM	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-F-001-2	F	2	Open	\$93,175	REPLACE WET PIPE SPRINKLER FIRE PROTECTION SYSTEM, ORDINARY HAZARD, ONE FLOOR, FROM 10,000 TO 50,000 SF	Building does not have a sprinkler system and poses a fire hazard.	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-004-1	M	1	Open	\$427,596	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	Roof leaking	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-006-1	M	1	Open	\$135,037	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS),SINGLE STORY	Restucco	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-009-1	M	1	Open	\$39,351	REPLACE 2" X 4" FIBERGLASS OR MINERAL SUSPENDED ACoustICAL CEILING TILES, INCLUDING GRID, OVER 500 SF PER ROOM	Upgrade ceiling tiles.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-011-1	M	1	Open	\$185,599	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Plumbing has deteriorated	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-018-1	M	1	Open	\$31,188	REPLACE LIGHT FIXTURES THROUGHOUT THE CLASSROOMS.	OLD AND OBSOLETE AND TO STAY IN COMPLIANCE WITH THE NATIONAL ELECTRICAL CODE.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-019-1	M	1	Open	\$24,772	TO CLEAN DUCT SYSTEM.	TO STAY IN COMPLIANCE WITH THE INDOOR AIR QUALITY (IAQ), UNDER (EPA).	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-020-1	M	1	Open	\$68,752	To replace 18 gauge metal floor deck.	To replace metal floor deck due to settlement of the building.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-023-1	M	1	Open	\$11,349	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 3 TON UP TO 5 TON	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-024-1	M	1	Open	\$155,087	To reveal (-) negative slope on the existing floor and foundation.	To stay in compliance with the life safety code.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-025-1	M	1	Open	\$32,098	To install Thermostat controller in Room, 102, 104, 106, 107, 108, 110, 111, 116, 118, 118A, 130 and 132.	To Install Thermostat controller in Room, 102, 104, 106, 107, 108, 110, 111, 116, 118, 118A, 130 and 132. The rooms are manually control, and need to convert to an Automatic controller to conserve energy and be in compliance with ANSI/ASME CSD-1-1995 Controls and Safety Devices for Automatically Fired Boilers.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-027-1	M	1	Open	\$15,236	REPLACE CENTRIFUGAL EXHAUST FAN, 4910 CFM, 23" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-028-1	M	1	Open	\$44,821	TO REPLACE T-TRACK FOR SUSPENDED CEILING.	CEILING IS WATER DAMAGE THROUGHOUT BUILDING, AND TO STAY IN COMPLIANCE WITH NFPA 101, LIFE SAFETY CODE.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-M-029-1	M	1	Open	\$9,122	New exterior doors, frames and hardware needed	Old doors not repairable	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-20	Chinle Boarding School	1001	N35-20-1001-S-001-1	S	1	Open	\$417,580	REPLACE SCHOOL AND COLLEGE EDUCATION BUILDING COOLING AND HEATING SYSTEM 10,000 TO 40,000 SF	Environmental comfort	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-F-001-2	F	2	Open	\$114,605	REPLACE WET PIPE SPRINKLER FIRE PROTECTION SYSTEM, ORDINARY HAZARD, ONE FLOOR, UP TO 10,000 SF	Sprinkler system required for upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-003-1	M	1	Open	\$363,420	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION AND GENERAL FLASHING, FOR USE ON PARAPET ROOFS (300 SF AND OVER)	Roof leaking	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-008-1	M	1	Open	\$135,037	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	new stucco	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-013-1	M	1	Open	\$42,598	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTICAL CEILING TILES, INCLUDING GRID, UNDER 500 SF PER ROOM	Upgrade ceiling tiles.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-015-1	M	1	Open	\$185,590	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Upgrade deteriorated plumbing	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-022-1	M	1	Open	\$273,949	TO UPGRADE THE HEATING UNITS THROUGHOUT THE CLASSROOMS.	TO REPLACE THE HEATING UNITS THROUGHOUT THE CLASSROOMS. (OBSOLETE)	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-024-1	M	1	Open	\$24,772	TO CLEAN DUCT SYSTEM.	TO STAY IN COMPLIANCE WITH THE INDOOR AIR QUALITY (IAQ), UNDER (EPA).	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-025-1	M	1	Open	\$58,752	To replace 18 gauge metal floor deck.	To replace metal floor deck due to settlement of the building.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-031-1	M	1	Open	\$2,553	INSTALL 10' POWER POLE WITH 4 - 120V RECEPTACLES, UP TO 25' CIRCUIT LENGTH	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-032-1	M	1	Open	\$155,097	To relevel (-) negative slope on the floor and foundation.	To stay in compliance with the life safety code.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-034-1	M	1	Open	\$32,098	To install Thermostat controller to the floor mount heaters.	To install Thermostat controller in rooms 102, 104, 108, 108A, 108, 110, 112, 116, 118, 120, 130, and 132. The rooms are manually control, and need to convert to an Automatic controller to conserve energy and be in compliance with ANSI / ASME CSD-1-1985 Control and Safety Devices for Automatically Fired Boilers.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1002	N35-20-1002-M-035-1	M	1	Open	\$44,921	TO REPLACE T-TRACK FOR SUSPENDED CEILING.	CEILING IS WATER DAMAGE FROM ROOF LEAKS, AND NEED TO BE IN COMPLIANCE WITH NFPA 101, LIFE SAFETY CODE.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-F-001-2	F	2	Open	\$114,605	REPLACE WET PIPE SPRINKLER FIRE PROTECTION SYSTEM, ORDINARY HAZARD, ONE FLOOR, FROM 10,000 TO 50,000 SF	Upgrade with sprinkler system	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-002-1	M	1	Open	\$487,148	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION AND GENERAL FLASHING, FOR USE ON PARAPET ROOFS (300 SF AND OVER)	Roof leaking	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-004-1	M	1	Open	\$126,645	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	New stucco	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-008-1	M	1	Open	\$29,478	To install Thermostat controller to the floor mount unit heaters.	To install Thermostat Controller in room 104, 108, 109, 113, 117, 121, 128B, and 130. The rooms are manually control, and need to convert to an Automatic controller to conserve energy and be in compliance with ANSI/ASME CSD-1-1985 Controls and Safety Devices for Automatically Fired Boilers.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-008-1	M	1	Open	\$5,520	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTIC CEILING TILES, NO GRID	Upgrade ceiling tiles.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-011-1	M	1	Open	\$169,027	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Upgrade deteriorated plumbing	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-013-1	M	1	Open	\$232,115	TO UPGRADE THE HEATING UNITS THROUGHOUT THE CLASSROOMS.	TO REPLACE THE HEATING UNITS THROUGHOUT THE CLASSROOMS. (DETERIORATED)	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-016-1	M	1	Open	\$21,377	TO CLEAN DUCT SYSTEM.	TO STAY IN COMPLIANCE WITH THE INDOOR AIR QUALITY (IAQ) , UNDER (EPA).	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-017-1	M	1	Open	\$49,870	To replace 18 gauge metal floor deck.	To replace metal floor deck due to settlement of the building.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-022-1	M	1	Open	\$131,413	To relevel (-) negative slope on the existing floor and foundation.	To stay in compliance with the life safety code.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-023-1	M	1	Open	\$5,590	To replace commercial water heater, 73 up to 110 G.P.H. in room 127.	Due to aged on hot water boiler, and to stay in compliance with ANSI/ASME CSD-1-1985 Controls and Safety Devices for Automatically Fired Boilers.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-025-1	M	1	Open	\$40,008	TO REPLACE T-TRACK FOR SUSPENDED CEILING.	CEILING IS WATER DAMAGE FROM ROOF LEAKS, AND NEED TO BE IN COMPLIANCE WITH NFPA 101, LIFE SAFETY CODE.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-M-026-1	M	1	Open	\$8,122	Install new exterior doors, frames and hardware as needed	Old doors not repairable	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1003	N35-20-1003-S-001-1	S	1	Open	\$7,553	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	Privacy and ADA	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-F-001-2	F	2	Open	\$114,605	REPLACE WET PIPE SPRINKLER FIRE PROTECTION SYSTEM, ORDINARY HAZARD, ONE FLOOR, FROM 10,000 TO 30,000 SF	Upgrade for fire sprinkler system	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-001-1	M	1	Open	\$487,148	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION AND GENERAL FLASHING, FOR USE ON PARAPET ROOFS (300 SF AND OVER)	roof leaking	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-002-1	M	1	Open	\$24,331	REPLACE CENTRIFUGAL EXHAUST FAN, 4010 CFM, 23' SQUARE OR ROUND, ROOF OR WALL MOUNTED	FACCOM Inspected by AME: BENDER 21-JUN-1988	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-003-1	M	1	Open	\$126,645	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	New stucco	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-007-1	M	1	Open	\$160,663	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTIC CEILING TILES, NO GRID	Upgrade ceiling tiles.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-010-1	M	1	Open	\$191,509	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	Upgrade deteriorated plumbing	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-014-1	M	1	Open	\$232,115	TO UPGRADE THE HEATING UNITS THROUGHOUT THE CLASSROOMS.	TO REPLACE THE HEATING UNITS THROUGHOUT THE CLASSROOMS. (DETERIORATED)	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-015-1	M	1	Open	\$21,377	TO CLEAN DUCT SYSTEM.	TO STAY IN COMPLIANCE WITH THE INDOOR AIR QUALITY (IAQ) , UNDER (EPA).	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-016-1	M	1	Open	\$48,958	To replace 18 gauge metal floor deck.	To replace metal floor deck due to settlement of the building.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-019-1	M	1	Open	\$2,553	INSTALL 10' POWER POLE WITH 4 - 120V RECEPTACLES, UP TO 25' CIRCUIT LENGTH	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-020-1	M	1	Open	\$125,902	To relieve (-) negative slope on the existing floor and foundation.	To stay in compliance with the life safety code.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-021-1	M	1	Open	\$29,476	To install Thermostat controller to the floor mount unit heaters.	To install Thermostat controller in room 104, 108, 109, 113, 117, 121, 126, and 130. The rooms are manually control, and need to convert to an Automatic controller to conserve energy and be in compliance with ANSI/ASME OSD-1-1995 Controls and Safety Devices for Automatically Fired Boilers.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-022-1	M	1	Open	\$40,808	TO REPLACE T-TACK FOR SUSPENDED CEILING.	CEILING IS WATER DAMAGE FROM ROOF LEAKS, AND NEED TO BE IN COMPLIANCE WITH NFPA 101, LIFE SAFETY CODE.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-M-023-1	M	1	Open	\$9,122	Install new exterior doors, frames and hardware as needed	Old doors not repairable	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-S-001-1	S	1	Open	\$4,305	Cabinets and sinks old	Usable equipment	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1004	N35-20-1004-S-002-1	S	1	Open	\$7,652	Partitions falling down	Privacy and ADA	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-M-005-1	M	1	Open	\$2,780	REPLACE FIRE ALARM CONTROL PANEL	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-M-017-1	M	1	Open	\$6,738	REPLACE EXPANSION TANK, OVER 120 UP TO 180 GAL	The expansion tank needs replacement due to the fact that it has a pin hole on the bottom of the tank and poses a danger for the boilers.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-M-018-1	M	1	Open	\$428,718	REPLACE ELEMENTARY SCHOOL PLUMBING SYSTEM	The entire plumbing has aged and deteriorated.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-M-025-1	M	1	Open	\$159,855	TO REPLACE FIRE TUBE BOILERS, TWO PASS SYSTEM.	THE BOILERS ARE AT ITS USEFUL LIFE, ALSO TO STAY IN COMPLIANCE WITH THE AMERICAN SOCIETY OF MECHANICAL ENGINEERS (ASME) CODES.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-M-026-1	M	1	Open	\$197,439	To replace 18 gauge metal floor deck.	To replace metal floor deck due to settlement of the building.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1009	N35-20-1009-S-062-1	S	1	Open	\$44,757	REPLACE WINDOW, ALUMINUM DOUBLE HUNG, INCLUDING INSULATING GLASS, 13 TO 24 SF	FACCOM Inspected by AME: BAKER 21-JUN-1999	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-002-1	M	1	Open	\$17,419	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTICAL CEILING TILES, INCLUDING GRID, OVER 600 SF PER ROOM	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-007-1	M	1	Open	\$99,951	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	To replace roof	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-008-1	M	1	Open	\$3,032	REPLACE CENTRIFUGAL EXHAUST FAN, 4910 CFM, 23" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-010-1	M	1	Open	\$12,146	REPLACE EXTERIOR, WALL PACK, HID UP TO 175 WATT	The building has low visibility at night and poses a danger for security.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-011-1	M	1	Open	\$28,988	REPLACE PLUMBING SYSTEM FOR OFFICE OR COMMERCIAL SPACE UP TO 6000 SF	The plumbing system has aged and deteriorated.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-012-1	M	1	Open	\$78,443	UPGRADE/REPLACE ELECTRICAL SYSTEM REPLACE ELECTRICAL SYSTEM FOR A 5102 GSP ELEMENTARY SCHOOL. COST SOURCE: RS MEANS SF COST 2008, PAGE 199	The service panel surges at times, and poses a fire danger.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-014-1	M	1	Open	\$63,230	REPLACE COMMERCIAL/OFFICE SINGLE ZONE ROOFTOP UNIT COOLING AND HEATING SYSTEM UP TO 10,000 SF	NOT IN COMPLIANT TO AIR QUALITY	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-015-1	M	1	Open	\$2,607	REPLACE WALL/FLOOR MOUNTED WATER CLOSET, TANK TYPE	THE BASE TO THE WATER CLOSETS ARE CRACKED AND NEEDS TO BE REPLACED.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-017-1	M	1	Open	\$20,412	To replace metal roof decking for build-up roofing.	To replace metal roof decking, due to settlement of the building which is causing roof leaks.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-018-1	M	1	Open	\$77,816	To relieve (-) negative slope on the concrete floor and foundation.	The soil is unstable and causing the foundation to shift, also to stay in compliance with the life safety code.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	1022	N35-20-1022-M-020-1	M	1	Open	\$4,856	To replace the loading bumpers and guard rails.	To stay in compliance with the life safety code.	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-F-001-2	F	2	Open	\$94,953	To replace Fire Hydrants.	To Upgrade Fire Hydrants (Aged), due to safety.				N/A	F-2
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-005-1	M	1	Open	\$283,113	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	the road is becoming a hazard to drive on				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-008-1	M	1	Open	\$4,456	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-013-1	M	1	Open	\$43,276	REPLACE BLEACHERS, WOOD WITH STEEL UNDER STRUCTURE	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-028-1	M	1	Open	\$9,420	REPLACE CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-032-1	M	1	Open	\$309,809	INSTALL, REPLACE FOOTBALL FIELD	upgrades due to substandard playing surface that can cause injury, and footholds that could cause physical injury and liability. Upgrade essential for safe play for health programs and sporting activities				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-034-1	M	1	Open	\$13,863	REPLACE VINYL COATED BENCH UP TO 8'	The wooden Benches poses a safety Hazard, due to (AGED).				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-035-1	M	1	Open	\$30,393	REPLACE MULCH AROUND PLAYGROUND EQUIPMENT, UP TO 3" THICK	To prevent injuries for students that play at the playgrounds.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-038-1	M	1	Open	\$585,616	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	To prevent tort claims on private vehicles, GSA vehicles, and school buses. The estimates for the pavements are Ash Street, Birch Street, Cedar Street, Fir Street, Pine Street, Pinon Street, Ash Drive, and portion of Circle Drive.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-037-1	M	1	Open	\$57,783	REPLACE RESIDENTIAL SPRINKLER SYSTEM	The landscape has aged and deteriorated.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-038-1	M	1	Open	\$9,789	REPLACE ASPHALT PARKING LOT	To prevent tort claims on the firetrucks and G.S.A. vehicles.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-040-1	M	1	Open	\$7,528	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	TO FILL IN POT HOLES FOR CIRCLE DRIVE, AND TO PREVENT TORT CLAIMS ON SCHOOL BUSES AND G.S.A. VEHICLES. THE SQ.FTG. IS AT AN ESTIMATE OF 26FT.X 880FT. THIS IS AN EMERGENCY, DUE TO BUSING STUDENTS TO MANYFARMS HIGH SCHOOL CAFETERIA ON A DAILY BASE.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-041-1	M	1	Open	\$153,326	To replace the baseball field on the north side of the facility management building # 1018.	Upgrade the softball field due to substandard playing surface, which could cause injuries and liability issues to the school.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-044-1	M	1	Open	\$7,033	REPLACE METAL BASKETBALL BACKBOARD, EXTERIOR	THE BASKETBALL GOALS HAVE DETERIORATED AND (AGED).				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-047-1	M	1	Open	\$18,967	REPLACE CONCRETE PATIO, OVER 8 SF	TO INSTALL CONCRETE PADDING FOR THE TWO DUMSTERS. CURRENTLY THEY ARE LOCATED ON THE DIRT SURFACE, ON THE SOUTH SIDE OF THE KITCHEN. ON INCOMEMENT WEATHER DAYS ITS HARD FOR THE COMPACTOR TO PICKUP THE CONTAINERS.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-048-1	M	1	Open	\$324,251	REPLACE PLAYGROUND, COMPLEX	THE PLAYGROUND EQUIPMENTS ARE OLD AND DETERIORATED.				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-051-1	M	1	Open	\$3,437	TO REPLACE GATE VALVE AT THE ELEVATED TANK.	TO STAY IN COMPLIANCE WITH THE (SAFE DRINKING WATER ACT).				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-052-1	M	1	Open	\$3,034	TO INSTALL A GATE VALVE BETWEEN THE BOOSTER PUMP HOUSING AND THE ELEVATED TANK.	A SAFETY HAZARD EXIST BETWEEN THE BOOSTER PUMP AND THE ELEVATED TANK. (NO SHUT OFF VALVE).				N/A	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-057-1	M	1	Open	\$3,058	REPLACE POLE MOUNTED LIGHT FIXTURE, UP TO 1000W. HID	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-058-1	M	1	Open	\$9,276	REPLACE POLE MOUNTED LIGHT FIXTURE, UP TO 1000W. HID	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-064-1	M	1	Open	\$11,817	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-070-1	M	1	Open	\$9,585	REPLACE CONCRETE PATIO, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-078-1	M	1	Open	\$16,512	REPLACE GRAVEL SURFACE, SPREAD BY MACHINE	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-080-1	M	1	Open	\$4,466	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-090-1	M	1	Open	\$9,703	REPLACE CHAIN LINK FENCE AND POSTS, RESIDENTIAL, 4' HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-092-1	M	1	Open	\$6,172	Valving must be installed to control both water systems from one location	Install gate valves for control THE B-140 WITH BOOSTER PUMP AND THE T-200S ARE BOTH EXCELLENT CHOICES FOR WATERING OUR FOOTBALL FIELD DOWN THE CENTERLINE IN A SINGLE PASS. AT THE COMPLETION OF THE IRRIGATION CYCLE, THE WATER REEL CAN BE REMOVED FROM THE FIELD AUTOMATICALLY, AND ENHANCE PLAYING CONDITIONS, REDUCING THE RISK OF PLAYER INJURIES. AT CURRENT THERE IS NO GRASS ON THE FOOTBALL FIELD, DUE TO LACK OF IRRIGATION SYSTEM TO THE FIELD AND ALSO TO STAY IN COMPLIANCE WITH THE LIFE SAFETY CODE				N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-M-094-1	M	1	Open	\$9,530	TO INSTALL TURF IRRIGATION SYSTEM FOR THE FOOTBALLFIELD.					N/A	M-1
Navajo Region	N35-20	Chinle Boarding School	Ground	N35-20-X01-S-002-1	S	1	Open	\$26,573	REPAIR / REPLACE PIPE	DETERIORATED				N/A	S-1
Navajo Region	N35-04	Cottonwood Day School	606	N35-04-606-M-003-1	M	1	Open	\$294,345	REPLACE MODIFIED BITUMINOUS ROOFING, TORCH APPLIED	Roof has deteriorated beyond repair	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	808	N35-04-808-M-024-1	M	1	Open	\$38,110	REPLACE METAL COPING	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	606	N35-04-606-M-034-1	M	1	Open	\$371,188	UPGRADE/REPLACE LIGHTING FIXTURES/SWITCHES	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	606	N35-04-606-S-001-1	S	1	Open	\$11,840	UPGRADE/REPLACE LIGHTING FIXTURES,(AGING/INEFFICIENT), THROUGHOUT BUILDING. COST SOURCE: RS MEANS SF COSTS 2008, PAGE 199	Missing throughout classrooms	Occupied	BIA Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-04	Cottonwood Day School	608	N35-04-608-M-031-1	M	1	Open	\$27,971	Install smoke detector, wired to existing fire alarm system	Missing throughout classrooms	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	608	N35-04-608-M-035-1	M	1	Open	\$6,477	REPLACE STEAM KETTLE, 60 GAL WITH STEAM JACKET, TILTING WITH POSITIVE LOCK, STAINLESS STEEL	kettles needed for food preparation for daily operations	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	608	N35-04-608-M-035-1	M	1	Open	\$6,477	REPLACE FAN COIL UNIT WITH CHILLED WATER, HORIZONTAL/VERTICAL, OVER 3 TO 7-1/2 TON	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-04	Cottonwood Day School	608	N35-04-608-S-002-1	S	1	Open	\$48,851	Replace refrigerator/freezer walk-in box,	Needs replacement	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-04	Cottonwood Day School	608	N35-04-608-S-003-1	S	1	Open	\$3,127	Install smoke detector, wired to existing fire alarm system	Missing detectors in kitchen, public restrooms, and janitors closet	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-04	Cottonwood Day School	612	N35-04-612-S-001-1	S	1	Open	\$2,854	Install smoke detectors	Missing in classroom area	Occupied	BIA Education	School, Kindergarten	Poor	S-1
Navajo Region	N35-04	Cottonwood Day School	Ground	N35-04-X01-F-002-2	F	2	Open	\$19,719	Replacement personal protective turnout clothing AKA bunkers.	replace old and worn out personal protective turn out gear, to meet fire and safety codes				N/A	F-2
Navajo Region	N35-04	Cottonwood Day School	Ground	N35-04-X01-F-002-1	M	1	Open	\$48,260	Clean up old abandoned well site	Clean up old well head				N/A	M-1
Navajo Region	N35-04	Cottonwood Day School	Ground	N35-04-X01-M-009-1	M	1	Open	\$593,479	REPLACE PROPANE TANK, 5000 GAL.	Upgrade tank farm				N/A	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-F-001-2	F	2	Open	\$4,807	Fire suppression for kitchen appliances	Upgrade needed for kitchen appliances	Occupied	BIA Education	School, Elementary, Day	Poor	F-2
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-019-1	M	1	Open	\$22,261	REPLACE TYPE L COPPER PIPE, 1/2" TO 3/4"	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-021-1	M	1	Open	\$45,933	REPLACE INDOOR AIR HANDLING UNIT, MULTI-ZONE, OVER 4,000 UP TO 8,500 CFM	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-040-1	M	1	Open	\$3,748	REMOVE PLUMBING FIXTURE, INCLUDING CAPPING WATER AND SANITARY LINES	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-042-1	M	1	Open	\$3,314	INSTALL DUCTLESS SPLIT SYSTEM, UP TO 1-1/2 TONS	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-044-1	M	1	Open	\$14,141	REPLACE REFRIGERATOR/FREEZER WALK-IN BOX, PREFAB, ALUMINUM, COMPLETE UNIT WITH DOOR, FLOOR AND REFR	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-045-1	M	1	Open	\$31,931	REPLACE WALK-IN COOLER, 8' X 20'	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-047-1	M	1	Open	\$3,125	REPLACE FIRE RETARDANT STAGE CURTAIN, VELOUR, MEDIUM WEIGHT	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-M-051-1	M	1	Open	\$3,201	REPLACE ALUMINUM BOX GUTTERS	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N32-05	Cove Day School	308	N32-05-308-S-003-1	S	1	Open	\$11,319	Complete Replacement/Upgrade of Fire Alarm System	The existing fire alarm system is deteriorated and does not meet code compliances with NFPA 101; fire alarm system will also tie into new portable classroom bldg, and the Fac. Mgmt. shop building.	Occupied	BIA Education	School, Elementary, Day	Poor	S-1
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-F-001-2	F	2	Open	\$13,662	Replaces 3 Fire Hydrants to school campus	Old fire hydrants				N/A	F-2
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-F-002-2	F	2	Open	\$15,387	Fire Hydrants	Replace old fire hydrants				N/A	F-2
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-M-020-1	M	1	Open	\$69,480	REPLACE EXISTING LAGOON LINER WITH 120 MIL, HIGH DENSITY POLYETHYLENE (HDPE) ۰۰۰۰۰۰۰۰	AME Requested Backlog				N/A	M-1
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-M-021-1	M	1	Open	\$38,088	REPLACE INDUSTRIAL CHAIN LINK FENCE AND POSTS, 3 STRANDS OF BARBED WIRE, 6' HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-M-022-1	M	1	Open	\$6,850	REPLACE BACKSTOP ON PLAYING FIELD	AME Requested Backlog				N/A	M-1
Navajo Region	N32-05	Cove Day School	Ground	N32-05-X01-M-024-1	M	1	Open	\$3,100	REPLACE MANHOLE COVER, UP TO 36" DIAMETER	AME Requested Backlog				N/A	M-1
Navajo Region	N38-05	Crystal Boarding School	Ground	N38-05-X01-M-011-1	M	1	Open	\$9,407	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N38-05	Crystal Boarding School	Ground	N38-05-X01-M-012-1	M	1	Open	\$20,501	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1
Navajo Region	N38-05	Crystal Boarding School	Ground	N38-05-X01-M-014-1	M	1	Open	\$21,855	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N38-05	Crystal Boarding School	Ground	N38-05-X01-M-015-1	M	1	Open	\$3,803	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-018-1	M	1	Open	\$9,820	REPLACE INDUSTRIAL CHAIN LINK FENCE AND POSTS, 3 STRANDS OF BARBED WIRE, 6' HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-019-1	M	1	Open	\$17,669	REPLACE CONCRETE SITE WALL, UP TO 8" THICK	AME Requested Backlog				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-022-1	M	1	Open	\$18,746	REPLACE ABRATOR, OVER 7.5 UP TO 10 HP	AME Requested Backlog				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-023-1	M	1	Open	\$69,732	REPLACE 6" CONCRETE RAMP WITH STEEL CURB AND RAILS TO ACCOMMODATE ADA REQUIREMENTS	AME Requested Backlog				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-024-1	M	1	Open	\$4,227	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-M-026-1	M	1	Open	\$3,780	Evaluate condition of elevated water tank and provide a detail list of needs to bring the tank into proper specifications and provide cost estimate	Upgrade domestic water tank				N/A	M-1
Navajo Region	N36-05	Crystal Boarding School	Ground	N36-05-X01-S-002-1	S	1	Open	\$42,302	REPLACE METAL CANOPY, 12' X 40'	Open area hazardous when ice				N/A	S-1
Navajo Region	N34-03	Dibe Yazhi Habin'ln Olla Inc. (Borrogo Pass)	Ground	N34-03-X01-M-007-1	M	1	Open	\$25,313	REPLACE REVERSE OSMOSIS TREATMENT SYSTEM 12,000 TO 15,000 GPD	The school is currently having domestic water issues due to hard water and contaminants that might exist in our school water distribution system and the hardship that we have experience this past summer.				N/A	M-1
Navajo Region	N34-03	Dibe Yazhi Habin'ln Olla Inc. (Borrogo Pass)	Ground	N34-03-X01-M-012-1	M	1	Open	\$234,000	Elevated water tank needs renovation	Renovate water tank				N/A	M-1
Navajo Region	N34-03	Dibe Yazhi Habin'ln Olla Inc. (Borrogo Pass)	Ground	N34-03-X01-M-013-1	M	1	Open	\$172,133	REPLACE PVC WATER SUPPLY PIPE, 4", SCHEDULE 80, UP TO 6 FT DEEP	The water system provides reddish color water and smells to the school campus - facility & government tenants.				N/A	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-001-1	M	1	Open	\$6,500	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	Inspected by AME: BRABHAM 16-JAN-01	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-003-1	M	1	Open	\$31,232	REPLACE PVC PIPE, 2-1/2" TO 4"	The existing sewer lines are cast iron. They are corroded, plug debris, rusted and pose a safety concern to the students and staff by sewers backing up into the school. The sewer lines are also breaking and causing puddles of water to accumulate under the buildings causing stinking smell that students and teachers are complaining of headache and feel nauseous. Molds are present in some areas.	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-009-1	M	1	Open	\$3,269	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL HANDICAP	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-012-1	M	1	Open	\$22,860	REPLACE ROOFTOP MOUNTED SPACE HEATERS, GAS-FIRED, OVER 190 UP TO 225 MBH	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-015-1	M	1	Open	\$48,509	Windows are old and warped and need replacement with thermal pane	Install thermal pane	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-022-1	M	1	Open	\$11,574	REPLACE TYPE L COPPER PIPE, 1" TO 1-1/4"	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4001	N34-24-4001-M-024-1	M	1	Open	\$3,211	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-013-1	M	1	Open	\$22,960	REPLACE ROOFTOP MOUNTED SPACE HEATERS, GAS-FIRED, OVER 180 UP TO 225 MBH	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-014-1	M	1	Open	\$29,527	Windows are old and warped and need replacement with thermal pane	Install thermal pane	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-018-1	M	1	Open	\$4,494	REPLACE PANELBOARD 100 AMPS, 3 PHASE 277/480V, 4- WIRE, UP TO 20 CIRCUITS	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-019-1	M	1	Open	\$3,923	REPLACE PANELBOARD, 100A, 120/208V, 4-WIRE, UP TO 30 CIRCUIT	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-021-1	M	1	Open	\$29,012	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-023-1	M	1	Open	\$15,063	REPLACE TYPE L COPPER PIPE, 1" TO 1-1/4"	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4002	N34-24-4002-M-027-1	M	1	Open	\$15,108	REPLACE PANELBOARD 600 AMP MAIN BREAKER, 277/480V 3 PHASE, 4 WIRE, UP TO 42 CIRCUIT	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4003	N34-24-4003-M-002-1	M	1	Open	\$25,309	Windows are old, warped and need replacement with thermal pane	Need thermal pane	Occupied	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4003	N34-24-4003-M-016-1	M	1	Open	\$10,365	REPLACE TYPE L COPPER PIPE, 1" TO 1-1/4"	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-004-1	M	1	Open	\$8,438	Windows are old and warped and need replacement with thermal pane	Install thermal pane	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-011-1	M	1	Open	\$3,289	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL, HANDICAP	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-012-1	M	1	Open	\$11,656	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-013-1	M	1	Open	\$12,576	REPLACE TYPE L COPPER PIPE, 1" TO 1-1/4"	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-014-1	M	1	Open	\$3,107	REPLACE WOOD INTERIOR SOLID CORE DOOR, FRAME AND HARDWARE, UP TO 3' X 7'	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-018-1	M	1	Open	\$5,092	REPLACE FIXED SASH WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, STEEL FRAME	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4004	N34-24-4004-M-019-1	M	1	Open	\$114,697	REPLACE RADIANT HEATER, FIN TUBE, WALL HUNG WITH SLOPED TOP COVER	AME Requested Backlog	Occupied	Grant Education	Gymnasium	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-008-1	M	1	Open	\$35,339	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 345 TO 892 MBH	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-013-1	M	1	Open	\$15,314	REPLACE ROOFTOP MOUNTED SPACE HEATERS, GAS-FIRED, OVER 300 UP TO 450 MBH	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-018-1	M	1	Open	\$4,226	REPLACE EXIT LIGHT W/BATTERY BACKUP, INTERIOR	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-021-1	M	1	Open	\$19,859	REPLACE INDOOR AIR-HANDLING UNIT, SINGLE ZONE, OVER 2,000 UP TO 4,000 CFM	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-022-1	M	1	Open	\$14,719	REPLACE COMMERCIAL DISHWASHER	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-023-1	M	1	Open	\$3,888	REPLACE STANDARD COMMERCIAL COOKTOP RANGE WITH OVEN	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-025-1	M	1	Open	\$8,035	REPLACE COMMERCIAL FOOD MIXER, 60 QUART	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4005	N34-24-4005-M-029-1	M	1	Open	\$42,070	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, OVER 893 UP TO 1530 MBH	AME Requested Backlog	Occupied	Grant Education	Kitchen	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4006	N34-24-4006-M-002-1	M	1	Open	\$7,482	REPLACE WALL MOUNTED LAVATORY WITH FAUCET AND DRAIN, 19" X 17"	FACCOM Inspected by AME: WATSON 16-FEB-99	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzilth-na-o-dith-hle Community School	4006	N34-24-4006-M-008-1	M	1	Open	\$12,843	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	FACCOM Inspected by AME: WATSON 16-FEB-99, Inspected by AME: BORKMAN 16-JAN-01	Occupied	Grant Education	Dormitory, School	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4005	N34-24-4005-M-029-1	M	1	Open	\$118,110	Windows are old and warped and need replacement with thermal pane	Install thermal pane	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4006	N34-24-4006-M-029-1	M	1	Open	\$45,002	REPLACE PANELBOARD 800 AMP MAIN BREAKER, 277/480V 3 PHASE, 4 WIRE, UP TO 42 CIRCUIT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4006	N34-24-4006-M-031-1	M	1	Open	\$43,108	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4006	N34-24-4006-M-033-1	M	1	Open	\$86,473	REPLACE TYPE L COPPER PIPE, 1-1/2" TO 2-1/2"	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4006	N34-24-4006-M-035-1	M	1	Open	\$3,557	REPLACE EXTERIOR LOUVERED FLUSH STEEL DOOR, UP TO 3' X 7'	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4006	N34-24-4006-M-036-1	M	1	Open	\$4,670	REPLACE ALUMINUM DOWNSPOUT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-008-1	M	1	Open	\$340,881	REPLACE RADIANT HEATER, FIN TUBE, WALL, HUNG WITH SLOPED TOP COVER	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-007-1	M	1	Open	\$21,593	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	Inspected by AME: BRABHAM 16-JAN-01	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-015-1	M	1	Open	\$49,358	REPLACE PVC PIPE, 2-1/2" TO 4"	The existing sewer lines cast iron they are corroded, plug with debris, rusted, and poses a safety concern to the students and staff by sewers backing up into the school building. The sewer lines are also breaking causing puddles of water to accumulate under the buildings causing sickening smell that students and staff are complaining of headache and feel sick nauseous.	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-023-1	M	1	Open	\$118,110	Windows are old and warped and need replacement with thermal pane	Install thermal pane	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-026-1	M	1	Open	\$45,002	REPLACE PANELBOARD 800 AMP MAIN BREAKER, 277/480V 3 PHASE, 4 WIRE, UP TO 42 CIRCUIT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-029-1	M	1	Open	\$86,473	REPLACE TYPE L COPPER PIPE, 1-1/2" TO 2-1/2"	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-041-1	M	1	Open	\$9,907	REPLACE ALUMINUM DOWNSPOUT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-042-1	M	1	Open	\$8,524	CHIP, CLEAN AND PATCH, CONCRETE PAVEMENT	AME Requested Backlog	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4007	N34-24-4007-M-043-1	M	1	Open	\$23,397	REPLACE WALL MOUNTED LAVATORY WITH FAUCET AND DRAIN, 19" X 17"	FACCOM Inspected by AME: WATSON 16-FEB-99	Occupied	Grant Education	Dormitory, School	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4014	N34-24-4014-M-001-1	M	1	Open	\$8,959	REPLACE CARPET	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4014	N34-24-4014-M-007-1	M	1	Open	\$4,714	REPLACE AIR COOLED CONDENSER UNIT, WITH COMPRESSOR, 2-1/2 UP TO 3 TONS	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4014	N34-24-4014-M-008-1	M	1	Open	\$9,438	REPLACE STEEL EXTERIOR DOOR WITH VISION LITE, FRAME AND HARDWARE, UP TO 3' X 7'	AME Requested Backlog	Occupied	Grant Education	School, Other, Boarding	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4202	N34-24-4202-M-001-1	M	1	Open	\$4,567	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied by Others	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4202	N34-24-4202-M-010-1	M	1	Open	\$2,847	REPLACE TYPE L COPPER PIPE, 1/2" TO 3/4"	AME Requested Backlog	Occupied by Others	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4202	N34-24-4202-M-011-1	M	1	Open	\$3,890	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied by Others	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4305	N34-24-4305-M-006-1	M	1	Open	\$2,847	REPLACE TYPE L COPPER PIPE, 1/2" TO 3/4"	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4305	N34-24-4305-M-007-1	M	1	Open	\$6,379	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4307	N34-24-4307-M-002-1	M	1	Open	\$2,847	REPLACE TYPE L COPPER PIPE, 1/2" TO 3/4"	AME Requested Backlog	Occupied by Others	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	4307	N34-24-4307-M-003-1	M	1	Open	\$6,379	REPLACE PVC PIPE, 2-1/2" TO 4"	AME Requested Backlog	Occupied by Others	Grant Education	Office	Poor	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-F-001-2	F	2	Proposed	\$189,798	Currently the fire alarm system has trouble modes and cannot be cleared due to unavailability of replacement parts.	The fire alarm needs to be replaced as the system parts are no longer available. The fire alarm system services the school buildings and dormitories. Currently the system has trouble modes and cannot be cleared due to unavailability of replacement parts. The fire alarm system is needed for the safety of students and staff.			N/A	F-2	
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-002-1	M	1	Open	\$3,210	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-005-1	M	1	Open	\$9,231	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-006-1	M	1	Open	\$64,012	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	Streets need repair				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-010-1	M	1	Open	\$5,857	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-017-1	M	1	Open	\$3,735	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-021-1	M	1	Open	\$3,735	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-022-1	M	1	Open	\$3,210	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-024-1	M	1	Open	\$3,210	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-039-1	M	1	Open	\$12,728	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-042-1	M	1	Open	\$37,320	REPLACE ASPHALT BASKETBALL COURT	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-046-1	M	1	Open	\$1,031,097	REPLACE 8" GAS MAINS AND LATERALS	FACCOM Inspected by AME: WATSON 16-FEB-99; Inspected by AME: BORKMAN 16-JAN-01				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-049-1	M	1	Open	\$5,753	REPLACE CONCRETE PATIO, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-053-1	M	1	Open	\$37,363	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-054-1	M	1	Open	\$111,030	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-055-1	M	1	Open	\$8,340	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzllth-na-o-dlth-hle Community School	Ground	N34-24-X01-M-057-1	M	1	Open	\$163,805	INSTALL FOOTBALL OR SOCCER FIELD LIGHTING, PER POLE	AME Requested Backlog				N/A	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-058-1	M	1	Open	\$20,877	INSTALL ADDITIONAL PARKING LOT/AREA 30' LIGHT STANDARD, ONE 400 WATT HID FIXTURE	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-059-1	M	1	Open	\$81,987	INSTALL BASEBALL FIELD LIGHTING, PER POLE	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-060-1	M	1	Open	\$90,821	INSTALL ADDITIONAL PARKING LOT/AREA 30' LIGHT STANDARD, TWO 400 WATT HID FIXTURES	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-061-1	M	1	Open	\$1,593,798	REPLACE 4" DOMESTIC WATER MAINS AND 1-1/2" LATERALS	FACCOM Inspected by AME: WATSON 16-FEB-99; Inspected by AME: BORKMAN 16-JAN-01				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-062-1	M	1	Open	\$22,991	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-065-1	M	1	Open	\$75,000	A/E site assessment and engineering design study is needed for evaluation and contracting repairs and construction at various buildings	Site assessment from A/E firm				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-067-1	M	1	Open	\$6,273	REPLACE CONCRETE SIDEWALK, OVER 6 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-068-1	M	1	Open	\$3,585	CLEAN AND SEAL CONCRETE CRACKS IN SITE PAVEMENTS	AME Requested Backlog				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-M-079-1	M	1	Open	\$1,000,000	An additional sewer lagoon with all necessary regulations and attachments is needed for this location.	Upgrade sewer system				N/A	M-1
Navajo Region	N34-24	Dzilit-ne-o-dith-nle Community School	Ground	N34-24-X01-S-057-1	S	1	Proposed	\$153,904	REPLACE FIRE ALARM SYSTEM, JUNIOR HIGH SCHOOL, (INOPERATIVE) THROUGHOUT SCHOOL AND QUARTERS AREA. INCLUDES CONTROL PANELS, PULL STATIONS, CONDUIT AND WIRING BETWEEN BUILDINGS.	Upgrade system to reflect new fire alarm system				N/A	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-M-003-1	M	1	Open	\$1,228,004	REPLACE MODIFIED BITUMINOUS ROOFING, TORCH APPLIED	Roof leak throughout entire area.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-M-004-1	M	1	Open	\$132,522	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 7" HIGH UP TO 3/4 COPPER TUBE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-M-011-1	M	1	Open	\$147,716	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 3081 TO 4720 MBH	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-M-018-1	M	1	Open	\$7,382	REPLACE COMMERCIAL WATER HEATER, GAS, 73 UP TO 110 GPH	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-001-1	S	1	Open	\$9,520	REPLACE VENTILATION	INADEQUATE FOR CLASSROOMS	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-002-1	S	1	Open	\$26,066	INSTALL SMOKE DETECTOR, WIRED TO EXISTING FIRE ALARM SYSTEM	MISSING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-005-1	S	1	Open	\$183,177	REPLACE VINYL ASBESTOS FLOOR TILES WITH 12" X 12" VINYL FLOOR TILES	CRACKED	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-006-1	S	1	Open	\$1,178,404	UNDER PIN FOUNDATION, UP TO 18' BELOW GRADE, UP TO 3' DEEP BY 3' WIDE FOOTING, OVER 150 UP TO 300 LF	SETTLEMENT IN WING C AND 108	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-009-1	S	1	Open	\$9,786	REPLACE CARPET	BUNCHES UP, PRESENTING TRIP HAZARD.	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-010-1	S	1	Open	\$2,583	REPLACE VENETIAN BLINDS	INADEQUATE SUPPORT	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-119-1	S	1	Open	\$220,850	REMOVE AND REPLACE CONCRETE BEAM, REPLACE MODIFIED BITUMINOUS ROOFING	FACCOM Inspected by AME: DAUENHAUER 19-APR-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-122-1	S	1	Open	\$237,507	REPLACE VINYL ASBESTOS FLOOR TILES (VAT) WITH 12" X 12" VINYL FLOOR TILES	FACCOM Inspected by AME: DAUENHAUER 18-APR-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	431	N36-08-431-S-123-1	S	1	Open	\$10,887	REPLACE LAVATORY, VANITY TOP MOUNT, WITH FAUCET AND DRAIN, REPLACE BASE CABINETS, HARDWOOD, PREFINISHED	FACCOM Inspected by AME: WATSON 18-APR-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-M-003-1	M	1	Open	\$16,754	REPLACE FOOD STEAMER, UP TO 10 KW	Kitchen Equipment Aged	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-M-004-1	M	1	Open	\$13,104	REPLACE STEAM KETTLE, 60 GAL WITH STEAM JACKET, TILTING WITH POSITIVE LOCK, STAINLESS STEEL	Replace Steam Kettle	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-M-005-1	M	1	Open	\$13,437	REPLACE COMMERCIAL COOKING RANGE WITH OVEN	Replace Kitchen Oven	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-M-016-1	M	1	Open	\$2,650	REPLACE LOUVERED EXTERIOR STEEL DOUBLE DOORS WITH FRAME, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-M-018-1	M	1	Open	\$9,710	REPLACE COMMERCIAL GARBAGE DISPOSAL, 5 HP	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-S-001-1	S	1	Open	\$3,991	REPLACE CAFETERIA PORTABLE FOLD UP TABLES	SUDDENLY SNAPS AND HARD TO FOLD UP	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	434	N36-08-434-S-060-1	S	1	Open	\$131,643	REPLACE BUILT-UP ROOFING	FACCOM Inspected by AME: DAUENHAUER 19-APR-1999	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	435	N36-08-435-M-004-1	M	1	Open	\$4,595	REPLACE STEEL ROOF DECKING	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	435	N36-08-435-M-017-1	M	1	Open	\$25,063	REPLACE SHOWER RECEPTOR MEMBRANE/LINER, CERAMIC TILE, REPLACE SHOWER MIXING VALVE UNIT AND SHOWER HEAD, EXPOSED TYPE	FACCOM Inspected by AME: WATSON 18-APR-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	435	N36-08-435-M-025-1	M	1	Open	\$7,809	REPLACE ANGLE IRON IN ROOF FRAME	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	435	N36-08-435-S-079-1	S	1	Open	\$307,751	REPLACE PLUMBING SYSTEM INCLUDING TOILET AND SERVICE FIXTURES, SUPPLY AND DRAINAGE PIPING	FACCOM Inspected by AME: WATSON 19-APR-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	436	N36-08-436-M-008-1	M	1	Open	\$32,899	REPLACE WOOD INTERIOR SOLID CORE DOOR, FRAME AND HARDWARE, 3' X 7'	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-08	Greasewood Springs Community School	438	N36-08-436-S-002-1	S	1	Open	\$17,965	REPLACE CARPET	UNRAVELING/TRIP HAZARD IN ROOMS 118 AND 126	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	436	N36-08-436-S-004-1	S	1	Open	\$4,113	REPLACE FIRE ALARM CONTROL PANEL, 8 ZONE	NOT IN PROPER OPERATING CONDITION	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	504	N36-08-504-S-009-1	S	1	Open	\$6,080	REPLACE ASPHALT SHINGLES	FACCOM Inspected by AME: DAUENHAUER 19-APR-1999	Occupied	BIA Education	School, Middle, Boarding	Poor	S-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-F01-M-001-1	M	1	Open	\$134,766	REPLACE GAS MAINS AND SERVICE LINES INCLUDING APPURTENANCES, STEEL	FACCOM Inspected by AME: WATSON 19-APR-1999				N/A	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-020-1	M	1	Open	\$200,365	REPLACE GENERATOR SET, GAS/GASOLINE, OVER 80 KW UP TO 100 KW	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-021-1	M	1	Open	\$41,208	REPLACE BLEACHERS, WOOD WITH STEEL UNDER STRUCTURE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-022-1	M	1	Open	\$176,823	INSTALL BASEBALL FIELD LIGHTING, PER POLE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-023-1	M	1	Open	\$137,331	INSTALL ADDITIONAL PARKING LOT/AREA 30' LIGHT STANDARD, ONE 400 WATT HID FIXTURE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-024-1	M	1	Open	\$175,890	INSTALL FOOTBALL OR SOCCER FIELD LIGHTING, PER POLE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-025-1	M	1	Open	\$135,660	Clean up old abandoned well site	Clean up well site				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-028-1	M	1	Open	\$8,467	REPLACE CHAIN LINK FENCE AND POSTS, RESIDENTIAL, OVER 4' TO 8' HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-027-1	M	1	Open	\$222,379	REPLACE METAL OPEN RAIL GATE, OVER 18 UP TO 24 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-033-1	M	1	Open	\$108,053	REPLACE FIRE HYDRANT, 6" TO 8" DEEP	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-034-1	M	1	Open	\$3,044	REPLACE POST VALVE INDICATOR	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-036-1	M	1	Open	\$22,357	REPLACE 6" THICK CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-038-1	M	1	Open	\$4,785	REPLACE 6" THICK CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-039-1	M	1	Open	\$32,593	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-040-1	M	1	Open	\$96,488	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-041-1	M	1	Open	\$40,774	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-046-1	M	1	Open	\$20,604	REPLACE BLEACHERS, WOOD WITH STEEL UNDER STRUCTURE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-M-049-1	M	1	Open	\$3,570	Evaluate condition of elevated water tank and provide a detail list of needs to bring the tank into proper specifications and provide cost estimate	Upgrade domestic water tank				N/A	M-1
Navajo Region	N36-08	Greasewood Springs Community School	Ground	N36-08-X01-S-001-1	S	1	Open	\$4,580	INSTALL MANUAL PULL STATION	AME Requested Backlog				N/A	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-002-1	M	1	Open	\$72,852	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, OVER 893 UP TO 1530 MBH	Tubing are old	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-034-1	M	1	Open	\$14,353	REPLACE LIGHTING FIXTURE LENS, 1' X 4' FLUORESCENT	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-040-1	M	1	Open	\$151,471	REPLACE CARPET	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-044-1	M	1	Open	\$10,818	REPLACE EXTERIOR SLIDING PATIO DOOR 96" X 96", TWO PANELS	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-048-1	M	1	Open	\$12,330	REPLACE CERAMIC WALL TILE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-097-1	M	1	Open	\$6,272	the school campus fencing is inadequate security fencing for homeland security of the campus buildings; 10% of the school is fenced 80% of the school ground is not fenced	protection of school ground and buildings	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-119-1	M	1	Open	\$120,530	REPLACE WALL MOUNTED LAVATORY WITH FAUCET AND DRAIN, 18" X 17"	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-135-1	M	1	Open	\$22,916	REPLACE STAINLESS STEEL SHOWER COLUMN GROUP SHOWER, 6 HEADS	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-150-1	M	1	Open	\$20,910	REPLACE CENTRIFUGAL UTILITY FAN, 1 TO 1 1/2 HP, 6700 CFM, PEDESTAL MOUNT	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-155-1	M	1	Open	\$8,085	REPLACE FIXED SASH WINDOW, OVER 24 SF UP TO 36 SF, INSULATING GLASS, STEEL FRAME	Inspected by AME: FALLS 20-SEP-1999	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-157-1	M	1	Open	\$809,439	CLEAN BUILDING METAL DUCT SYSTEM	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-166-1	M	1	Open	\$81,840	REPLACE FIXED SASH WINDOW, OVER 6 SF UP TO 12 SF, INSULATING GLASS, STEEL FRAME	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-179-1	M	1	Open	\$13,476	REPLACE WOOD FIRE DOOR IN CORRIDOR, NO FRAME, UP TO 45 MINUTE RATING	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-180-1	M	1	Open	\$23,562	REPLACE ENAMEL STEEL SHOWER WITH STONE RECEPTOR, 32" X 32"	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-184-1	M	1	Open	\$11,759	REPLACE DOUBLE DOOR WITH FRAME, FULL GLASS STEEL EXTERIOR WITH HARDWARE, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-189-1	M	1	Open	\$6,815	REPLACE AIR COMPRESSOR, SINGLE STAGE, RECIPROCATING, 5 HP WITH 60 GALLON TANK	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-187-1	M	1	Open	\$7,664	REPLACE PANELBOARD, 225 AMPS, 3 PHASE, 4 WIRE, 277/480V, UP TO 42 CIRCUITS	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-195-1	M	1	Open	\$22,832	outdoor nelson's park (student's volleyball area) needs tables, benches for residential students	our outdoor student activities area are all old the lumber are old falling apart and safety hazard for students sitting on them by nelson's park which we have old volleyball area	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-198-1	M	1	Open	\$39,305	sleeping and living quarters 22 x 14 sq ft the carpet is 30 plus year old	the air quality of the students sleeping quarter is low, because the carpet is old worn down from over uses from shampoo, vacuum and year after years of uses and beside its healthy for the student health problems	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-199-1	M	1	Open	\$3,465	REPLACE EXTERIOR, WALL PACK, HID UP TO 175 WATT	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-200-1	M	1	Open	\$5,681	REPLACE PNEUMATIC MODULATING THREE-WAY VALVE, FLANGED, OVER 3" UP TO 6"	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-201-1	M	1	Open	\$4,222	REPLACE PNEUMATIC MODULATING THREE-WAY VALVE, FLANGED, UP TO 3"	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-203-1	M	1	Open	\$15,258	REPLACE CENTRIFUGAL EXHAUST FAN, 13780 CFM, 35" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-204-1	M	1	Open	\$44,382	REPLACE COMMERCIAL DISHWASHER	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-205-1	M	1	Open	\$7,970	REPLACE COMMERCIAL GARBAGE DISPOSAL, 1-1/2 HP	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-206-1	M	1	Open	\$28,451	REPLACE COMMERCIAL BAKE OVEN, 2 SECTIONS, GAS	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-207-1	M	1	Open	\$24,998	REPLACE STEAM KETTLE, 80 GALLON	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-208-1	M	1	Open	\$2,548	REPLACE SLIDING WINDOW, OVER 6 SF UP TO 12 SF, INSULATING GLASS, ALUMINUM FRAME	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-213-1	M	1	Open	\$4,994	REPLACE DOOR CLOSER, RACK AND PINION SURFACE MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-219-1	M	1	Open	\$33,446	REPLACE FLOOR TILE , UP TO 1" X 1" SCRIM BACKED	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-222-1	M	1	Open	\$39,650	REPLACE PAINTED EXTERIOR CMU WALL, MULTIPLE STORY	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-227-1	M	1	Open	\$11,803	REPLACE MODIFIED BITUMINOUS ROOFING, TORCH APPLIED	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-228-1	M	1	Open	\$4,555	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTIC CEILING TILES, NO GRID	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-230-1	M	1	Open	\$416,500	school building air vents has alot debris of trash in the floors and ceiling	clean air act; for throughout the school building	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-231-1	M	1	Open	\$1,487,500	electrical upgrade throughout school building; the building is 30 years old we need upgrade the electrical panels, transformer, services lines and breakers	bring the school building up to standard of the need proper electrical services nees	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-232-1	M	1	Open	\$148,750	Intercom system for the school building needs upgrade and repairs	Intercom system is hazard because some area wiring is exposed and hanging	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-233-1	M	1	Open	\$148,750	the phone system need to be repair - existing phone lines, cables, connector and panels are 30 years old with the school building	phone is old cables, cut, worn, crackend not working correctly	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-235-1	M	1	Open	\$170,900	VE additive alternate- Thermostatic mixing valves needed at dormitory showers	Mixing valves for water temp control	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-239-1	M	1	Open	\$357,000	auditorium carpets, stadium seating, dividers, floor tiles, restrooms, water fountains, needs replacements with 30 years worn downs over uses	the carpet from the sewer backup needs replacements, seating are moving and broken, dividers are stuck in one area, floor tiles are missing	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-245-1	M	1	Open	\$5,332	roofing paper blow off from the wind storm	the building is weight room for the students the building needs to be repairs	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-249-1	M	1	Open	\$370,900	VE additive alternate-Energ efficient fixtures needed on lighting	Install energy efficient fixtures	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-250-1	M	1	Open	\$160,200	VE additive alternate- Lighting controls needed	Add lighting controls	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-251-1	M	1	Open	\$22,500	VE additive alternate-Central dust collection system needed at wood shop	Dust collection system	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-252-1	M	1	Open	\$28,900	VE additive alternate-Surge suppression system needed	Surge suppressor	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-253-1	M	1	Open	\$34,700	VE additive alternate-ECM fan coil units recommended	Recommend fan coil units	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-254-1	M	1	Open	\$36,600	VE additive alternate-Emergency generator needed	Emergency generator	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-257-1	M	1	Open	\$181,594	Exterior need to be thermal pane	New thermal pane windows	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-M-258-1	M	1	Open	\$1,061,452	Exterior walls need new stucco with insulation	New stucco walls with insulation	Occupied	BIA Education	School, Secondary, Boarding	Peer	M-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-003-1	S	1	Open	\$4,695	REPLACE STEEL EXTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-004-1	S	1	Open	\$2,517	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-005-1	S	1	Open	\$3,944	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-008-1	S	1	Open	\$4,692	REPLACE STEEL EXTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-007-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-008-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-009-1	S	1	Open	\$10,085	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-010-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-011-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-012-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-013-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-014-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-015-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-016-1	S	1	Open	\$4,695	REPLACE STEEL EXTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-017-1	S	1	Open	\$4,972	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-018-1	S	1	Open	\$17,351	INSTALL ISOLATED SPRINKLER SYSTEM	MISSING IN ROOM G103	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1
Navajo Region	N33-22	Greyhills High School	385	N33-22-385-S-019-1	S	1	Open	\$11,285	REPLACE DRY TYPE TRANSFORMER 45 KVA TO 75 KVA	TELECTICAL PANELS AND TRANSFORMERS THROUGHOUT ARE ANTICQUATED, LACK A CONTINUOUS GROUNDING PATH AND ARE INADEQUATE TO HANDLE THE LOAD AS EVIDENCED BY A RECENT 15 KVA TRANSFORMER FIRE IN A THE BOILER ROOM CAUSED BY OVERLOAD	Occupied	BIA Education	School, Secondary, Boarding	Peer	S-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N33-22	Greyhills High School	365	N33-22-365-S-668-1	S	1	Open	\$10,126	INSTALL AN ORDINARY HAZARD, WET PIPE SPRINKLER SYSTEM FOR AN INDIVIDUAL SPACE	Inspected by AME: PETIT 20-SEP-1999	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-22	Greyhills High School	365	N33-22-365-S-688-1	S	1	Open	\$241,891	REPLACE STEEL EXTERIOR DOOR AND HARDWARE, VISION LITE, REPLACE PANIC HARDWARE, REPLACE DOOR CLOSER, REPLACE EXTERIOR DOOR WEATHER STRIPPING, NEOPRENE/ALUMINUM STRIP, REPLACE THRESHOLD WEATHER STRIPPING, DOOR SWEEP, BRUSH STYLE	Inspected by AME: FALLS 20-SEP-1999	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-023-1	M	1	Open	\$238,000	Elevated water tank needs renovation	Renovate water tank				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-026-1	M	1	Open	\$11,345	REPLACE WOOD STOCKADE FENCE	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-029-1	M	1	Open	\$5,415	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-054-1	M	1	Open	\$4,239	REPLACE MANHOLE/CATCH BASIN, PRECAST CONCRETE TO 4 FOOT DEPTH	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-060-1	M	1	Open	\$7,397	REPLACE BENCH WITH WOOD SLATS, STEEL PEDESTALS AND BARSTOCK, 8' LONG	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-080-1	M	1	Open	\$9,317	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-081-1	M	1	Open	\$3,894	REPLACE WOVEN WIRE FENCING, UP TO 4 FEET HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-M-083-1	M	1	Open	\$4,614	REPLACE WOOD PANEL FENCE WITH 6" X 6" POSTS, UP TO 8'	AME Requested Backlog				N/A	M-1
Navajo Region	N33-22	Greyhills High School	Ground	N33-22-X01-S-002-1	S	1	Open	\$9,887	REPLACE STEEL PIPE RAIL	AME Requested Backlog				N/A	S-1
Navajo Region	N36-11	Hunters Point Boarding School	410	N36-11-410-M-001-1	M	1	Open	\$14,671	Fluorescent lighting fixtures are 30+ years old, inefficient and have a high probability of containing PCB ballast	Energy upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	423	N36-11-423-M-013-1	M	1	Open	\$2,803	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL HANDICAP	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	423	N36-11-423-M-014-1	M	1	Open	\$16,301	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	423	N36-11-423-M-015-1	M	1	Open	\$10,933	REPLACE STEEL EXTERIOR DOOR WITH VISION LITE, FRAME AND HARDWARE, UP TO 3' X 7'	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	423	N36-11-423-M-018-1	M	1	Open	\$18,792	REPLACE SHOWER MIXING VALVE UNIT AND SHOWER HEAD, EXPOSED TYPE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	423	N36-11-423-M-020-1	M	1	Open	\$19,230	REPLACE WALL MOUNTED LAVATORY WITH FAUCET AND DRAIN, 19" X 17"	Inspected by AME: BORKMAN 17-MAY-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-004-1	M	1	Open	\$9,141	REPLACE UP TO 18" THICK CUT STONE SITE WALL, MORTAR SET	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-009-1	M	1	Open	\$195,504	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-011-1	M	1	Open	\$16,481	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-014-1	M	1	Open	\$4,543	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-016-1	M	1	Open	\$4,141	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-017-1	M	1	Open	\$18,115	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-018-1	M	1	Open	\$4,888	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-019-1	M	1	Open	\$181,135	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-021-1	M	1	Open	\$73,035	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-022-1	M	1	Open	\$87,665	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-023-1	M	1	Open	\$10,525	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-025-1	M	1	Open	\$10,987	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-026-1	M	1	Open	\$8,356	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-028-1	M	1	Open	\$12,159	REMOVE UNDERGROUND FUEL OIL STORAGE TANK UP TO 2500 GALLON	AME Requested Backlog				N/A	M-1
Navajo Region	N36-11	Hunters Point Boarding School	Ground	N36-11-X01-M-029-1	M	1	Open	\$31,921	REPLACE CONCRETE BASKETBALL COURT	Inspected by AME: DAUENHAUER 17-MAY-1999				N/A	M-1
Navajo Region	N35-07	Lukachukai Boarding School	1385	N35-07-1385-M-002-1	M	1	Open	\$5,987	Building needs structural upgrade	Structural upgrade	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	1385	N35-07-1385-M-004-1	M	1	Open	\$4,357	Building needs electrical upgrade	Upgrade	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	1702	N35-07-1702-M-003-1	M	1	Open	\$5,217	Building needs electrical upgrade	Upgrade	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	1703	N35-07-1703-M-003-1	M	1	Open	\$5,217	Building needs electrical upgrade	Upgrade	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	201	N35-07-201-F-001-2	F	2	Open	\$104,078	Building needs fire protection upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	201	N35-07-201-M-021-1	M	1	Open	\$933,540	Building needs the mechanical systems upgraded	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	201	N35-07-201-M-022-1	M	1	Open	\$765,749	Building needs renovation structurally and architecturally	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-F-001-2	F	2	Open	\$195,136	Building needs fire protection upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-M-010-1	M	1	Open	\$65,057	Building needs structural upgrade	Structural upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-M-012-1	M	1	Open	\$800,284	Building needs renovation architecturally	Architectural upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-M-013-1	M	1	Open	\$1,485,290	Building needs the mechanical system upgraded	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-M-014-1	M	1	Open	\$734,482	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-M-015-1	M	1	Open	\$1,488,709	Building needs preparatory demo and site work before renovation	Site upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-S-001-1	S	1	Open	\$5,776	REPLACE EXTERIOR GRADE CARPET	PLATFORM GROUNDS DETERIORATED AND TORN.	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-S-002-1	S	1	Open	\$5,189	Install fire alarm control panel	Not operational	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-S-003-1	S	1	Open	\$3,246	Install strobe/alarm devices	Missing throughout building	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	202	N35-07-202-S-004-1	S	1	Open	\$12,972	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	DAMAGED AND BINDING AT THE FOUR EXTERIOR DOORS	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	203	N35-07-203-F-001-2	F	2	Open	\$5,532	repairs on fire alarm system throughout building	repair fire alarm system for student and staff safety.	Occupied	BIA Education	Dormitory, School	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	203	N35-07-203-F-002-2	F	2	Open	\$78,185	Building needs fire protection upgrade	Upgrade	Occupied	BIA Education	Dormitory, School	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	203	N35-07-203-M-022-1	M	1	Open	\$2,300,178	Building needs mechanical systems upgrade	Upgrade	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	203	N35-07-203-M-023-1	M	1	Open	\$830,328	Building needs electrical system upgrade	Upgrade	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	203	N35-07-203-M-024-1	M	1	Open	\$158,046	Building needs structural renovation and repair	Structural upgrade	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-F-001-2	F	2	Open	\$84,972	Building needs fire protection upgrade	Upgrade	Occupied	BIA Education	Kitchen	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-M-012-1	M	1	Open	\$16,463	Building needs structural upgrade	Structural upgrade	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-M-013-1	M	1	Open	\$1,209,361	Building needs mechanical upgrade	Mechanical upgrade	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-M-014-1	M	1	Open	\$318,831	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-S-004-1	S	1	Open	\$8,812	REPLACE EXIT LIGHT W/BATTERY BACKUP	INOPERATIVE/DAMAGED THROUGHOUT BUILDING	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-S-005-1	S	1	Open	\$17,752	REPLACE DRYWALL CEILING WITH FIRE RATED DRYWALL	DAMAGED IN DINING ROOM	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-S-008-1	S	1	Open	\$9,984	REPLACE VINYL ASBESTOS FLOOR TILES WITH 12" X 12" VINYL FLOOR TILES	DAMAGED SUSPECTED ASBESTOS FLOOR TILE	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-S-007-1	S	1	Open	\$5,189	REPLACE FIRE ALARM CONTROL PANEL	INOPERATIVE IN BUILDING	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	208	N35-07-208-S-009-1	S	1	Open	\$3,210	REPLACE SYSTEM SMOKE DETECTOR	MISSING THROUGHOUT ROOMS	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	220	N35-07-220-M-003-1	M	1	Open	\$3,488	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	221	N35-07-221-M-005-1	M	1	Open	\$3,488	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	222	N35-07-222-M-003-1	M	1	Open	\$5,018	Building needs structural/architectural upgrade	Structural/architectural upgrade	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	222	N35-07-222-M-004-1	M	1	Open	\$3,488	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	222	N35-07-222-M-005-1	M	1	Open	\$51,810	Building needs mechanical upgrade	Upgrade	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	224	N35-07-224-M-008-1	M	1	Open	\$81,287	Building needs structural and architectural upgrade	Structural/architectural upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	224	N35-07-224-M-009-1	M	1	Open	\$168,862	Building needs mechanical upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	224	N35-07-224-M-010-1	M	1	Open	\$81,878	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	224	N35-07-224-S-001-1	S	1	Open	\$3,064	DUPLICATE BACKLOG -- INSTALL STROBE AND HORN, WIRED TO EXISTING SYSTEM	NO ACCESSIBLE STROBES THROUGHOUT BUILDING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	224	N35-07-224-S-003-1	S	1	Open	\$3,932	REPLACE 3' X 7' FIRE DOOR AND FRAME, UP TO 45 MINUTE RATING	REPLACE FIRE DOOR THAT ARE OLD, BINDING, AND WARPED	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-F-001-2	F	2	Open	\$43,471	Building needs fire protection upgrade	Upgrade	Occupied	BIA Education	Office	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-M-014-1	M	1	Open	\$13,859	Building needs structural upgrade	Structural upgrade	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-M-015-1	M	1	Open	\$425,941	Building needs mechanical upgrade	Upgrade	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-M-016-1	M	1	Open	\$183,778	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-S-001-1	S	1	Open	\$5,438	REPLACE FIRE ALARM CONTROL PANEL	NOT OPERATIONAL THROUGHOUT BUILDING	Occupied	BIA Education	Office	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	227	N35-07-227-S-002-1	S	1	Open	\$4,029	REPLACE INTERCOM MASTER STATION	DETERIORATED AND NEEDS UPGRADE THROUGHOUT BUILDING	Occupied	BIA Education	Office	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-F-001-2	F	2	Open	\$243,200	Fire system is not working through out campus	Fire protection for schools, students, staff, and general public	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-F-002-2	F	2	Open	\$161,877	Building needs fireprotection upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-M-013-1	M	1	Open	\$1,357,888	Building needs mechanical upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-M-015-1	M	1	Open	\$147,139	Building needs structural upgrade	Structural upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-M-017-1	M	1	Open	\$609,298	Building needs electrical upgrade	Upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-S-001-1	S	1	Open	\$24,029	INSTALL SMOKE DETECTOR, WIRED TO EXISTING SYSTEM	THROUGHOUT BUILDING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-S-003-1	S	1	Open	\$6,582	REPLACE DOUBLE DOOR WITH FRAME	DAMAGED, BENT, HARDWARE BROKEN AT SOUTHWEST EXIT, BY BOILER ROOM 327.	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-S-004-1	S	1	Open	\$5,438	REPLACE FIRE ALARM CONTROL PANEL	SYSTEM NOT OPERATIONAL THROUGHOUT ENTIRE BUILDING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	250	N35-07-250-S-005-1	S	1	Open	\$4,028	REPLACE INTERCOM MASTER STATION	NEED TO UPGRADE INTERCOM SYSTEM THROUGHOUT BUILDING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N35-07	Lukachukai Boarding School	287	N35-07-287-M-003-1	M	1	Open	\$8,751	Building needs electrical upgrade	Upgrade	Occupied	Grant Education	School, Elementary, Boarding	Poor	M-1

Region	Loc #	Location Name	Big Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-F-005-2	F	2	Open	\$466,904	Need new fire protection external system (fire hydrants, main water lines, valves and 100k water tank)	New system			N/A	F-2	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-021-1	M	1	Open	\$9,332	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-042-1	M	1	Open	\$75,000	Relocate 4" water line next to sewer lagoon for new lagoon installation	Water line relocation			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-044-1	M	1	Open	\$41,580	MODifications and demobilization for lagoon project	New lagoon			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-045-1	M	1	Open	\$146,920	Clean up old abandoned well site	Clean up old well head			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-046-1	M	1	Open	\$817,513	Preparation for Construction. Remove infrastructure (water lines, sewer lines, trees, fence, pavement and sidewalks)	Site upgrade			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-047-1	M	1	Open	\$163,430	Existing 50k and 75k potable water tanks need cleaning and painting	Upgrade			N/A	M-1	
Navajo Region	N35-07	Lukachukai Boarding School	Ground	N35-07-X01-M-048-1	M	1	Open	\$2,081,570	Need site development including drainage, roadways sidewalks, fence, etc	Site upgrade			N/A	M-1	
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	501	N34-18-501-M-001-1	M	1	Open	\$74,148	REPLACE BUILT-UP ROOFING, 300 SF AND OVER, UP TO 4 PLY AND 2" INSULATION	Inspected by AME: HAWKINS 16-JAN-01	Occupied	Grant Education	School, Other, Day	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	501	N34-18-501-M-003-1	M	1	Open	\$28,014	CUT AND POINT EXTERIOR RANDOM STONE WALL, SPOT POINTING	Inspected by AME: HAWKINS 16-JAN-01	Occupied	Grant Education	School, Other, Day	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	501	N34-18-501-M-014-1	M	1	Open	\$17,301	CUT AND POINT PAINTED EXTERIOR CMU WALLS, ENTIRE ELEVATION	AME Requested Backlog	Occupied	Grant Education	School, Other, Day	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-009-1	M	1	Open	\$24,781	REPLACE SINGLE STEEL BOX LOCKERS, 12' X 15' X 72"	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-020-1	M	1	Open	\$4,415	REPLACE 3' X 7' WOOD EXTERIOR DOOR, FRAME AND HARDWARE, HALF GLASS	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-033-1	M	1	Open	\$6,928	REPLACE LABORATORY FUME HOOD	FACCOM Inspected by AME: SELLERS 19-JAN-99; Inspected by AME: VINSON 18-JAN-01	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-036-1	M	1	Open	\$7,323	CONDUCT STRUCTURAL ENGINEERING EVALUATION	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-037-1	M	1	Open	\$5,089	REPLACE BASKETBALL SCOREBOARD, HIGH SCHOOL	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
									UPGRADE HVAC CONTROLS TO DDC						
									UPGRADE CURRENT HVAC CONTROLS TO DDC IN A 38,053 SF MULTI-PURPOSE BUILDING USED AS SECONDARY DAY SCHOOL. FACILITY MANAGER STATES CURRENT SYSTEM IS BEYOND REPAIR. COST SOURCE IS RS MEANS FACILITIES CONSTRUCTION COST DATA 2010. UPGRADE INCLUDES: DUCT HUMIDITY SENSORS (23 09 23.10 0140), SPACE HUMIDITY SENSORS (23 09 23.10 0160), WATER TEMPERATURE SENSORS (23 09 23.10 0172), WATER FLOW SENSORS (23 09 23.10 0174), DUCT HIGH TEMPERATURE THERMOSTAT ALARMS (23 09 23.10 2160), DUCT SMOKE DETECTORS (23 09 23.10 2170), 32 POINT CONTROLLERS (23 09 23.10 3229), VAV TERMINAL BOXES INCLUDING SPACE TEMPERATURE SENSORS (23 09 23.10 3266), AND HOST COMPUTER PACKAGE INCLUDING PC, KEYBOARD, PRINTER, CRT, MODEM, AND SOFTWARE (23 09 23.10 3282) TOTAL COST \$202,552 X 1.25 (DEMO/CONTINGENCIES/MATERIAL HANDLING= \$273,445	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-051-1	M	1	Open	\$332,051	REPLACE EVAPORATIVE COOLER 4216 UP TO 800 CFM, 1-1/2 HP	AME Requested Backlog	Occupied	Grant Education	Multi-Purpose	Poor	M-1
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	525	N34-18-525-M-052-1	M	1	Open	\$34,306	REPLACE INDUSTRIAL CHAIN LINK FENCE AND POSTS, 3 STRANDS BARBED WIRE, 6' HIGH	AME Requested Backlog			N/A	M-1	
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	Ground	N34-18-X01-M-007-1	M	1	Open	\$36,203	REPLACE CHAIN LINK GATE OVER 144 UP TO 182 SF	AME Requested Backlog			N/A	M-1	
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	Ground	N34-18-X01-M-009-1	M	1	Open	\$6,180		AME Requested Backlog			N/A	M-1	
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	Ground	N34-18-X01-M-017-1	M	1	Open	\$29,452	REPLACE WOVEN WIRE FENCE WITH ONE STRAND OF BARBED WIRE AT TOP, UP TO 4' HIGH	AME Requested Backlog			N/A	M-1	
Navajo Region	N34-18	Na' Neelzhilin Ji'Oita' (Torreon)	Ground	N34-18-X01-M-019-1	M	1	Open	\$46,800	CAP ABANDONED WELL, UP TO 6' CASING	Clean up old well head.			N/A	M-1	
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	520	N33-11-520-M-008-1	M	1	Open	\$3,021	REPLACE STEEL EXTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	520	N33-11-520-M-011-1	M	1	Open	\$105,682	REPLACE STANDING SEAM METAL ROOF (300 SF AND OVER)	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	520	N33-11-520-M-019-1	M	1	Open	\$12,181	REPLACE FIXED SASH WINDOW, ALUMINUM FRAME	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	520	N33-11-520-S-119-1	S	1	Open	\$268,406	REPLACE PLUMBING SYSTEM INCLUDING TOILET AND SERVICE FIXTURES, SUPPLY AND DRAINAGE PIPING	Inspected by AME: VINSON 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-008-1	M	1	Open	\$12,382	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTICAL CEILING TILES, INCLUDING GRID, OVER 500 S	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-013-1	M	1	Open	\$6,358	REPLACE CERAMIC WALL TILE	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-014-1	M	1	Open	\$8,022	REPLACE DRY WALL	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-015-1	M	1	Open	\$3,679	REPLACE DRYWALL CEILING, OVER 5 SF PER LOCATION	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-016-1	M	1	Open	\$23,785	REPLACE WOOD, SOLID CORE, INTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-020-1	M	1	Open	\$3,940	REPLACE CERAMIC FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-M-021-1	M	1	Open	\$36,918	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	Kitchen	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-S-001-1	S	1	Open	\$6,350	Cover gym walls with approved materials	Incorrect material type	Occupied	BIA Education	Kitchen	Poor	S-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	521	N33-11-521-S-051-1	S	1	Open	\$194,415	REPLACE PLUMBING SYSTEM INCLUDING TOILET AND SERVICE FIXTURES, SUPPLY AND DRAINAGE PIPING	Inspected by AME: VINSON 20-SEP-1999	Occupied	BIA Education	Kitchen	Poor	S-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-M-009-1	M	1	Open	\$10,894	REPLACE STAINLESS STEEL SHOWER COLUMN GROUP SHOWER, 6 HEADS	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-M-018-1	M	1	Open	\$13,490	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-M-022-1	M	1	Open	\$224,874	REPLACE STANDING BEAM METAL ROOF (300 SF AND OVER)	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-M-026-1	M	1	Open	\$98,078	REPLACE CARPET	FACCOM Inspected by AME: BRASHAM 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-S-002-1	S	1	Open	\$4,389	REPLACE FIRE ALARM CONTROL PANEL, 8 ZONE	TROUBLE SIGNAL IS ON	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-S-055-1	S	1	Open	\$48,593	INSTALL/REPLACE ELECTRICAL SERVICE AND DISTRIBUTION EQUIPMENT IN COLLEGE DORMITORY	Inspected by AME: VINSON 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	522	N33-11-522-S-052-1	S	1	Open	\$383,267	REPLACE PLUMBING SYSTEM INCLUDING TOILET AND SERVICE FIXTURES, SUPPLY AND DRAINAGE PIPING	Inspected by AME: VINSON 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-M-004-1	M	1	Open	\$6,072	Repair and replace hardware and patch grout on fence, install warning signage, install site ground ring and tie-in with fence and ground coax and control cables	Mindbank Inspection				N/A	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-M-007-1	M	1	Open	\$189,893	LPG tank farm end system needs to be upgraded	Upgrade tank farm				N/A	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-M-017-1	M	1	Open	\$58,524	remove and install complex playground equipment	The playground equipment is not aquitted for the children from grades K-8. The existing jungle gym is to small and does not meet safety code.				N/A	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-M-021-1	M	1	Open	\$7,284	Clean out above ground water storage tank to meet applicable regulations.	Deficiencies have been identified resulting from quality of water at school location. Equipment (dish washer, ice maker faucets and water heaters) have been replaced due to poor water quality. This is the first stage of making corrections to improving the water quality for the school. The existing water storage tank is used for storage of potable drinking water, fire protection and sanitary purposes for the students and staff on daily basis.				N/A	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-M-027-1	M	1	Open	\$37,647	REPLACE BUILT-UP ROOFING, UNDER 300 SF, UP TO 4 PLY	AME Requested Backlog				N/A	M-1
Navajo Region	N33-11	Naa tsis' aan (Navajo Mountain Boarding)	Ground	N33-11-X01-S-999-1	S	1	Open	\$185,542	EXCAVATE AND DISPOSE OF CONTAMINATED SOIL	Inspected by AME: VINSON 20-SEP-1999				N/A	S-1
Navajo Region	N35-09	Nazlini Boarding School	851	N35-09-851-S-001-1	S	1	Open	\$4,147	REPLACE FIRE ALARM CONTROL PANEL	TROUBLE IN THE SYSTEM	Occupied	BIA Education	Shop, Multi-Purpose	Poor	S-1
Navajo Region	N35-09	Nazlini Boarding School	880	N35-09-880-S-001-1	S	1	Open	\$5,096	REPLACE FIRE ALARM CONTROL PANEL	SYSTEM INDICATES TROUBLE LOCATED MAIN OFFICE	Occupied	BIA Education	Dormitory/Bunkhouse/ Barracks, Fire/Forestry	Poor	S-1
Navajo Region	N35-09	Nazlini Boarding School	880	N35-09-880-S-003-1	S	1	Open	\$2,813	low water cut-off replacement	repair boiler for dorm students heating system	Occupied	BIA Education	Dormitory/Bunkhouse/ Barracks, Fire/Forestry	Poor	S-1
Navajo Region	N35-09	Nazlini Boarding School	Ground	N35-09-X01-M-006-1	M	1	Open	\$28,000	Inspection services required for water storage tank upgrade	Inspect water storage tank upgrade				N/A	M-1
Navajo Region	N35-09	Nazlini Boarding School	Ground	N35-09-X01-M-007-1	M	1	Open	\$11,519	Installation of telecommunication support lines in Building 1432.	needed for communications to main building and emergency.				N/A	M-1
Navajo Region	N35-09	Nazlini Boarding School	Ground	N35-09-X01-M-008-1	M	1	Open	\$45,900	Clean up old abandoned well site	Clean up old well head				N/A	M-1
Navajo Region	N35-09	Nazlini Boarding School	Ground	N35-09-X01-M-016-1	M	1	Open	\$3,600	Evaluate condition of elevated water tank and provide a detail list of needs to bring the tank into proper specifications and provide cost estimate	Upgrade domestic water tank				N/A	M-1
Navajo Region	N35-09	Nazlini Boarding School	Ground	N35-09-X01-M-017-1	M	1	Open	\$3,600	Evaluate condition of elevated water tank and provide a detail list of needs to bring the tank into proper specifications and provide cost estimate	Upgrade domestic water tank				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-004-1	M	1	Open	\$11,721	INSTALL DUCTLESS SPLIT SYSTEM, UP TO 1-1/2 TONS	No ventilation system	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-008-1	M	1	Open	\$397,033	Classrooms, gym, kitchen and offices needs a HVAC system to allviate dust, circulate air and make the environment comfortable the students and faculty.	Student learning upgrade	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-010-1	M	1	Open	\$43,740	REPLACE UNBALLASTED SINGLE PLY MEMBRANE, RUBBER/PLASTIC ROOFING, 300 SF AND OVER	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-011-1	M	1	Open	\$9,664	REPLACE FIBERGLASS ROOF PANELS (300 SF AND OVER)	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-012-1	M	1	Open	\$88,974	CUT AND POINT PAINTED EXTERIOR CMU WALLS, SPOT POINTING	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	1314	N36-18-1314-M-013-1	M	1	Open	\$6,951	REPLACE CONCRETE FOUNDATION SKIRT, UP TO 2' WIDE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	815	N36-18-815-M-003-1	M	1	Open	\$7,740	Remodel pump house	Remodel pump house	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-017-1	M	1	Open	\$19,469	INSTALL ADDITIONAL PARKING LOT/AREA 30' LIGHT STANDARD, TWO 400 WATT HID FIXTURES	AME Requested Backlog				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-018-1	M	1	Open	\$5,388	REPLACE CONCRETE DRAINAGE PIPE FROM 15" TO 24" DIAMETER	AME Requested Backlog				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-023-1	M	1	Open	\$42,550	Clean up old abandoned well site	Clean up old well head				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-024-1	M	1	Open	\$76,482	Water line (2") from well to tank needs replaing	New well to tank piping				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-025-1	M	1	Open	\$41,592	Main road needs upgrade	NEW GRAVEL ROAD TO SEWER LAGOON				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-026-1	M	1	Open	\$2,718	REPLACE CAST IN PLACE CONCRETE STAIRS, BASED ON SF OF TREADS AND LANDING	AME Requested Backlog				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-027-1	M	1	Open	\$336,000	This location needs a new water well to supplement the existing in place. Allocation always needs more than one well	New well required				N/A	M-1
Navajo Region	N36-18	Pine Springs Day School	Ground	N36-18-X01-M-028-1	M	1	Open	\$22,400	Old well and site needs evaluation as to use	Evaluate old well site for reuse				N/A	M-1
Navajo Region	N35-10	Pinon Community School	147498	N35-10-147498-M-013-1	M	1	Proposed	\$7,293	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	Contract Education	Office	Poor	M-1
Navajo Region	N35-10	Pinon Community School	147498	N35-10-147498-M-018-1	M	1	Proposed	\$8,861	REPLACE PLYWOOD SUBFLOORING	AME Requested Backlog	Occupied	Contract Education	Office	Poor	M-1
Navajo Region	N35-10	Pinon Community School	147498	N35-10-147498-S-001-1	S	1	Proposed	\$12,630	INSTALL INTERIOR EMERGENCY, EXIT, OR COMBINATION FIXTURE	MISSING THROUGHOUT BUILDING	Occupied	Contract Education	Office	Poor	S-1
Navajo Region	N35-10	Pinon Community School	147498	N35-10-147498-S-002-1	S	1	Proposed	\$12,852	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTICAL CEILING TILES	DAMAGED THROUGHOUT BUILDING	Occupied	Contract Education	Office	Poor	S-1
Navajo Region	N35-10	Pinon Community School	147498	N35-10-147498-S-004-1	S	1	Proposed	\$3,255	REPLACE 3' X 7' STEEL EXTERIOR DOOR	THE EXIT DOOR FRAME IS BROKEN AND BENDING, LOCATED AT NORTHWEST EXIT DOOR	Occupied	Contract Education	Office	Poor	S-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank	
Navajo Region	N35-10	Pinon Community School	147496	N35-10-147496-S-005-1	S	1	Proposed	\$9,926	REPLACE DOOR CLOSER	NOT OPERATIONAL LOCATED AT EXIT AND DOORS TO EXIT ACCESS OF CORRIDOR	Occupied	Contract Education	Office	Poor	S-1	
Navajo Region	N35-10	Pinon Community School	147496	N35-10-147496-S-006-1	S	1	Proposed	\$5,485	SPRAY ROUGH WOOD INTERIOR WALLS WITH FIRE RETARDANT SUBSTANCE.	INTERIOR WOOD PANELING, NO RECORD OF MATERIAL TO BE FIRE RATED CLASS A OR B	Occupied	Contract Education	Office	Poor	S-1	
Navajo Region	N35-10	Pinon Community School	147496	N35-10-147496-S-007-1	S	1	Proposed	\$8,580	REPLACE CARPET	BEAMS LOOSE, OLD, TORN, AND CREATES TRIPPING HAZARD ROOMS 101, 102, 103, 104, 105, 106, 108, AND 109	Occupied	Contract Education	Office	Poor	S-1	
Navajo Region	N35-10	Pinon Community School	308	N35-10-308-M-008-1	M	1	Proposed	\$20,826	REPLACE FIXED SASH WINDOW, OVER 6 SF UP TO 12 SF, INSULATING GLASS, STEEL FRAME	Inspected by AME: CROPPER 21-JUN-1999	Occupied	Grant Education	Multi-Purpose	Poor	M-1	
Navajo Region	N35-10	Pinon Community School	308	N35-10-308-S-001-1	S	1	Proposed	\$41,954	REPLACE VINYL ASBESTOS FLOOR TILES WITH 12" X 12" VINYL FLOOR TILES	DAMAGED NEEDS REPLACEMENT THROUGHOUT INTERIOR ROOMS	Occupied	Grant Education	Multi-Purpose	Poor	S-1	
Navajo Region	N35-10	Pinon Community School	308	N35-10-308-S-017-1	S	1	Proposed	\$15,850	INSTALL/REPLACE ELECTRICAL SERVICE AND DISTRIBUTION EQUIPMENT IN ELEMENTARY SCHOOL	FACCOM	Occupied	Grant Education	Multi-Purpose	Poor	S-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-F-001-2	F	2	Open	\$11,490	Replacement of Personal Protective Turnout Clothing AKA Bunkers	current firefighter PPE is out dated and it's not safe.				N/A	F-2	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-001-1	M	1	Proposed	\$107,262	DEMOLISH ELEVATED WATER TOWER, 100,000 TO 500,000 GAL	Elevated water storage tank no longer needed				N/A	M-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-004-1	M	1	Proposed	\$1,243,901	REPLACE UNDERGROUND STEAM AND CONDENSATE PIPING IN TRENCH BETWEEN BUILDINGS, UP TO 500 LF OF 6" STEAM PIPE	AME Requested Backlog				N/A	M-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-006-1	M	1	Proposed	\$5,147	REPLACE GRAVEL SURFACE, SPREAD BY MACHINE	AME Requested Backlog				N/A	M-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-005-1	M	1	Proposed	\$303,695	Repair water tank by sandblasting exterior and interior, repair leaks, coat inside of tank	Repair water tank				N/A	M-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-015-1	M	1	Proposed	\$50,184	GRADE, SHAPE AND ADD 4" DEEP GRAVEL TO ROAD, UP TO 5,000 SF	AME Requested Backlog				N/A	M-1	
Navajo Region	N35-10	Pinon Community School	Ground	N35-10-X01-M-017-1	M	1	Proposed	\$46,260	Abandoned well to be properly closed	Close well				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-008-1	M	1	Open	\$10,024	REPLACE WALL MOUNTED STAINLESS STEEL HI-LO BARRIER FREE ELECTRIC WATER COOLER	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-034-1	M	1	Open	\$12,850	STUDY TO DETERMINE COST TO BRING 3 PHASE POWER TO SCHOOL	Due to increased usage of computers by students in the classroom, additional outlets needed, and upgrade of electrical service/remodeling needed for the server room with cooling to protect computer equipment.	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-037-1	M	1	Open	\$8,299	REPLACE EXTERIOR WALL JOINT BACKER ROD AND RECAULK	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-040-1	M	1	Open	\$9,881	REPLACE ENCASED WALL HYDRANT, 3/4" TO 1" PIPE SIZE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-041-1	M	1	Open	\$25,754	REPLACE CENTRIFUGAL EXHAUST FAN, 13760 CFM, 35" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-042-1	M	1	Open	\$4,085	REPLACE IN-LINE CIRCULATING PUMP, OVER 1/3 UP TO 3/4 HP	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	528	N32-07-528-M-043-1	M	1	Open	\$42,084	REPLACE EVAPORATIVE COOLER 4216 UP TO 8900 CFM, 1-1/2 HP	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	533	N32-07-533-M-003-1	M	1	Open	\$5,980	REPLACE WELL PUMP UP TO 6" CASING	Inspected by AME: MARCUSON 19-APR-1999	Occupied	BIA Education	Pump House	Poor	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-007-1	M	1	Open	\$79,290	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-008-1	M	1	Open	\$24,976	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-009-1	M	1	Open	\$35,015	PREPARE AND PAINT ELEVATED WATER TOWER	AME Requested Backlog				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-015-1	M	1	Open	\$481,191	REPLACE ELEVATED WATER STORAGE TANK, 100' TO BOTTOM CAPACITY LINE, OVER 60,000 UP TO 100,000 GALLON	Old water tank				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-016-1	M	1	Open	\$6,359	CAP ABANDONED WELL, UP TO 6" CASING	Close well head				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-018-1	M	1	Open	\$18,128	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-022-1	M	1	Open	\$43,205	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, UP TO 6' HIGH	AME Requested Backlog				N/A	M-1	
Navajo Region	N32-07	Red Rock Day School	Ground	N32-07-X01-M-026-1	M	1	Open	\$3,450	Evaluate condition of elevated water tank and provide a detail list of needs to bring the tank into proper specifications and provide cost estimate	Upgrade domestic water tank				N/A	M-1	
Navajo Region	N33-14	Richfield Residential Hall	800	N33-14-800-M-036-1	M	1	Open	\$3,290	REPLACE HALF GLASS ALUMINUM EXTERIOR DOOR WITH FRAME AND HARDWARE, 8' X 7'	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1	
Navajo Region	N33-14	Richfield Residential Hall	800	N33-14-800-M-038-1	M	1	Open	\$45,053	CLEAN BUILDING METAL DUCT SYSTEM	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1	
Navajo Region	N33-14	Richfield Residential Hall	800	N33-14-800-M-040-1	M	1	Open	\$8,071	REPLACE TYPE L COPPER PIPE, 3/8"	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1	
Navajo Region	N33-14	Richfield Residential Hall	800	N33-14-800-M-041-1	M	1	Open	\$35,868	INSTALL ADDITIONAL CIRCUIT, 20 AMP, 120V UP TO 100' CIRCUIT LENGTH	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1	
Navajo Region	N33-14	Richfield Residential Hall	Ground	N33-14-X01-M-002-1	M	1	Open	\$17,151	REPLACE WALKWAY POLE AND LUMINAIRE, UP TO 200W INCANDESCENT	Inspected by AME: EPPERSON 20-SEP-1999				N/A	M-1	
Navajo Region	N33-14	Richfield Residential Hall	Ground	N33-14-X01-M-006-1	M	1	Open	\$41,142	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 6' HIGH	Inspected by AME: LUCE 20-SEP-1999				N/A	M-1	
Navajo Region	N33-14	Richfield Residential Hall	Ground	N33-14-X01-M-009-1	M	1	Open	\$3,185	REPLACE CAST IN PLACE CONCRETE STAIRS, BASED ON SF OF TREADS AND LANDING	AME Requested Backlog				N/A	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-003-1	M	1	Open	\$10,224	REPLACE WOOD, SOLID CORE, INTERIOR DOOR AND HARDWARE	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-007-1	M	1	Open	\$46,713	REPLACE GYM LOCKERS, 12" X 12" X 12", 8 TIER	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-012-1	M	1	Open	\$34,969	REPLACE EVAPORATIVE COOLER UP TO 4215 CFM, 3/4 HP	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-025-1	M	1	Open	\$8,768	REPLACE DOUBLE STEEL BOX LOCKERS, 12" X 15" X 35"	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-028-1	M	1	Open	\$87,155	INSTALL SCHOOL INTERCOM SYSTEM	INSTALL INTERCOM SYSTEM WITH CODED PAGING SIGNAL. BUILDING # 27822 SF. COST PRICING FROM RSM ELECTRICAL D5030 910 0500	Inspected by AME: VINSON 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-030-1	M	1	Open	\$27,985	REPLACE ROOFTOP MOUNTED SPACE HEATERS, GAS-FIRED, OVER 225 UP TO 300 MBH	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-033-1	M	1	Open	\$4,913	REPLACE FURNACE, HOT AIR HEATING, GAS-FIRED, OVER 75 TO 125MBH	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1	

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-038-1	M	1	Open	\$2,745	REPLACE POLE MOUNTED LIGHT FIXTURE, 400W HID	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-037-1	M	1	Open	\$19,285	REPLACE DOUBLE STEEL BOX LOCKERS, 12' X 15" X 36"	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-039-1	M	1	Open	\$4,089	REPLACE ELECTRIC HAND DRYER, 120 VOLT	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-M-148-1	M	1	Open	\$119,800	REPLACE WOOD BLEACHERS WITH STEEL FRAME	Inspected by AME: FALLS 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-S-002-1	S	1	Open	\$5,336	Replace gym wall pads	missing	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-S-003-1	S	1	Open	\$10,775	Replace modified bituminous roofing, torch applied	stained and damaged ceiling indicate a possible leak in roof	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	410	N35-11-410-S-004-1	S	1	Open	\$7,405	replace stage curtains	missing	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	411	N35-11-411-M-039-1	M	1	Open	\$15,448	REPLACE CARPET	Inspected by AME: FALLS 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	411	N35-11-411-M-102-1	M	1	Open	\$18,740	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	Inspected by AME: FALLS 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	411	N35-11-411-S-002-1	S	1	Open	\$24,421	Install magnetic door holder wired to existing fire alarm system	doors are propped or tied open	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	411	N35-11-411-S-003-1	S	1	Open	\$13,288	Replace door closer	missing, in 168, south wing corridor to classrooms, and south wing corridors 100, 101, 112, and 115.	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	414	N35-11-414-M-005-1	M	1	Open	\$6,419	REPLACE 12" X 12" STAPLED OR CEMENTED MINERAL FIBER ACOUSTIC CEILING TILES	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	414	N35-11-414-M-006-1	M	1	Open	\$3,861	REPLACE BASE CABINETS, HARDWOOD, PREFINISHED OR LAMINATE	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	414	N35-11-414-S-003-1	S	1	Open	\$2,583	Replace centrifugal exhaust fan, 4910 CFM	Noisy, short circuit	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	414	N35-11-414-S-004-1	S	1	Open	\$2,566	REPLACE FLUORESCENT FIXTURE, 8' TWO LAMP STRIP, INTERIOR	COMING APART/FALLING HAZARD	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-004-1	M	1	Open	\$32,866	REPLACE WINDOW SCREEN, FABRIC ONLY	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-007-1	M	1	Open	\$33,249	REPLACE 2' X2' POLYSTYRENE ACOUSTICAL CEILING TILES, NO GRID	Inspected by AME: FALLS 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-012-1	M	1	Open	\$2,866	REPLACE DOOR CLOSER, RACK AND PINION SURFACE MOUNTED	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-013-1	M	1	Open	\$6,276	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-017-1	M	1	Open	\$9,165	REPLACE INTERIOR DOOR KEYED, HANDICAPPED LEVER	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-019-1	M	1	Open	\$25,122	REPLACE CERAMIC WALL TILE	AME Requested Backlog	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-027-1	M	1	Open	\$35,332	INSTALL INTERCOM WITH CODED PAGING SYSTEM IN K-12 SCHOOL. BUILDING = 19374 SF. COST PRICING FROM RSM ELECTRICAL D5030 910 0580	Inspected by AME: VINSON 21-JUN-1999	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-M-043-1	M	1	Open	\$164,148	UPGRADE TO DDC CONTROL SYSTEM FOR HVAC FROM PNEUMATIC CONTROL SYSTEM	Inspected by AME: VINSON 21-JUN-1989	Occupied	Contract Education	School, Elementary, Day	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	421	N35-11-421-S-003-1	S	1	Open	\$121,198	Replace modified bituminous roofing, torch applied	stained and damaged ceiling indicate a possible leak in roof	Occupied	Contract Education	School, Elementary, Day	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-M-008-1	M	1	Open	\$2,982	REPLACE CENTRIFUGAL EXHAUST FAN, 4910 CFM, 23" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	Contract Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-M-010-1	M	1	Open	\$7,640	Exterior needs upgrade	Exterior upgrade	Occupied	Contract Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-M-013-1	M	1	Open	\$19,269	INSTALL INTERCOM WITH CODED PAGING SYSTEM	Inspected by AME: VINSON 21-JUN-1999	Occupied	Contract Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-M-019-1	M	1	Open	\$4,772	REPLACE FLUORESCENT FIXTURE, 1' X 4', SURFACE MOUNT, WRAP AROUND LENS, INTERIOR	Inspected by AME: VINSON 21-JUN-1999	Occupied	Contract Education	Multi-Purpose	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-S-001-1	S	1	Open	\$15,200	Replace panic hardware	Missing	Occupied	Contract Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	423	N35-11-423-S-002-1	S	1	Open	\$5,139	Replace fire alarm control panel, addressable	In trouble mode	Occupied	Contract Education	Multi-Purpose	Poor	S-1
Navajo Region	N35-11	Rock Point Community School	430	N35-11-430-M-001-1	M	1	Open	\$3,031	Upgrade building exterior	Upgrade exterior	Occupied	Contract Education	Pump House	Poor	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-001-1	M	1	Open	\$3,994	REPLACE STEEL FUEL STORAGE TANK, ABOVE GROUND, 275 GALLON	Container of water stored tank very thin, and beginning to leak. Rock Point High School campus				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-002-1	M	1	Open	\$228,332	REPLACE 3" POLYETHYLENE PIPE 6Y HORIZONTAL BORING	Upgrade tank term				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-004-1	M	1	Open	\$86,170	OVERLAY EXISTING PAVEMENT WITH 1" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-005-1	M	1	Open	\$109,552	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-030-1	M	1	Open	\$82,518	REPLACE CONCRETE PAVEMENT, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-035-1	M	1	Open	\$2,803	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-038-1	M	1	Open	\$5,240	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-038-1	M	1	Open	\$6,273	REPLACE CABANA, 12' X 12'	AME Requested Backlog				N/A	M-1
Navajo Region	N35-11	Rock Point Community School	Ground	N35-11-X01-M-047-1	M	1	Open	\$91,960	Clean up old abandoned well site	Clean old well head				N/A	M-1
Navajo Region	N35-15	Rocky Ridge Boarding School	19	N35-15-19-M-010-1	M	1	Open	\$84,067	REPLACE UNBALLASTED SINGLE PLY MEMBRANE, RUBBER/PLASTIC ROOFING, 300 SF AND OVER	Roof leaking and non-reparable	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N35-15	Rocky Ridge Boarding School	19	N35-15-19-M-027-1	M	1	Open	\$30,628	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, 545 TO 892 MBH	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N33-15	Rocky Ridge Boarding School	19	N33-15-19-M-028-1	M	1	Open	\$37,851	REPLACE GAS FIRED, CAST IRON BOILER, STEAM/HOT WATER, OVER 893 UP TO 1330 MBH	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	19	N33-15-19-M-029-1	M	1	Open	\$15,488	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 9-7/8" HIGH 1" - 1-1/4" COPPER TUBE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	19	N33-15-19-M-030-1	M	1	Open	\$4,885	REPLACE FAN COIL UNIT, CHILLED WATER AND OR HOT WATER HEATING COILS, HORIZONTAL/VERTICAL, UP TO 1-1/2"	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	19	N33-15-19-M-034-1	M	1	Open	\$300,712	Dormitory needs a HVAC system to alleviate dust, circulate air and make the environment comfortable for live-in students	Student learning upgrade	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	19	N33-15-19-S-002-1	S	1	Open	\$4,251	REPLACE FIRE ALARM CONTROL PANEL	FACP IN ROOM 114 INDICATES TROUBLE MODE	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-15	Rocky Ridge Boarding School	20	N33-15-20-M-028-1	M	1	Open	\$5,048	REPLACE THRESHOLD WEATHERSTRIPPING, DOOR SWEEP, BRUSH STYLE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	20	N33-15-20-M-033-1	M	1	Open	\$521,212	Classroom and gym building needs a HVAC system to alleviate dust, circulate air and make the environment comfortable for the student and faculty.	Student learning upgrade	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	21	N33-15-21-M-016-1	M	1	Open	\$139,513	Kitchen needs HVAC system to alleviate dust, circulate air and make the environment comfortable for the diners	Student learning upgrade	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-001-1	M	1	Open	\$189,145	REPLACE ASPHALT PAVING, ON ROADS OR LARGE PAVED AREAS	The pavement is full of pot holes and damaged, needs to be resurfaced due to the bad weather out in this rural area				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-021-1	M	1	Open	\$253,485	Existing well system for domestic water is falling and recommendation is to tie into new NTUA water system across the road	Replace well				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-023-1	M	1	Open	\$7,690	REPLACE HORIZONTAL LIQUID PROPANE TANK, OVER 575 UP TO 1000 GALLONS	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-024-1	M	1	Open	\$7,690	REPLACE HORIZONTAL LIQUID PROPANE TANK, OVER 575 UP TO 1000 GALLONS	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-025-1	M	1	Open	\$7,690	REPLACE HORIZONTAL LIQUID PROPANE TANK, OVER 575 UP TO 1000 GALLONS	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-026-1	M	1	Open	\$7,690	REPLACE HORIZONTAL LIQUID PROPANE TANK, OVER 575 UP TO 1000 GALLONS	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-040-1	M	1	Open	\$9,719	REPLACE CHAIN LINK ROLLING SERVICE GATE	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-045-1	M	1	Open	\$5,798	REPLACE CHAIN LINK FENCE AND POSTS, INDUSTRIAL, 8' HIGH	AME Requested Backlog				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-049-1	M	1	Open	\$3,690	Elevated water tank needs upgrade	Upgrade elevated water tank				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-050-1	M	1	Open	\$13,889	Water well #1 need filter to clean up water for taste and smell	Eliminate odor and taste				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-051-1	M	1	Open	\$3,075	Elevated water tank level indicator needs repair	Repair water level indicator				N/A	M-1
Navajo Region	N33-15	Rocky Ridge Boarding School	Ground	N33-15-X01-M-052-1	M	1	Open	\$57,833	Location needs parking lot for gymnasium activities	Expand parking lot for gymnasium activities				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	645	N33-16-645-M-007-1	M	1	Open	\$4,812	REPLACE CARPET	AME Requested Backlog	Occupied	BIA Education	School, Other, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	645	N33-16-645-S-001-1	S	1	Open	\$2,896	REPLACE DRYWALL, WITH FIRE RATED DRYWALL	AME Requested Backlog	Occupied	BIA Education	School, Other, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-M-002-1	M	1	Open	\$10,154	REPLACE EXTERIOR INSULATION FINISH SYSTEM (EIFS), SINGLE STORY	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-M-006-1	M	1	Open	\$667,999	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-M-009-1	M	1	Open	\$57,481	REPLACE WINDOW WALL	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-M-014-1	M	1	Open	\$221,150	UPGRADE TO DDC CONTROL SYSTEM FOR HVAC FROM PNEUMATIC CONTROL SYSTEM	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-M-015-1	M	1	Open	\$83,830	REPLACE DOUBLE HUNG WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, ALUMINUM FRAME	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-017-1	M	1	Open	\$29,287	REPLACE CARPET	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-019-1	M	1	Open	\$33,180	REPLACE ALUMINUM HOPPER WINDOW WITH INSULATED GLASS, UP TO 8 SF	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-003-1	S	1	Open	\$4,389	Replace fire alarm control panel	FACP indicates Trouble mode	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-005-1	S	1	Open	\$4,548	Install steel pipe railing	Exterior ramp handrail not compliant at main entrance/exit door	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-006-1	S	1	Open	\$4,548	Duplicate backlog—install steel pipe railing	handrail not compliant	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-007-1	S	1	Open	\$5,741	Replace panic hardware	Missing at exit door next to office and Main entrance/exit door	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	646	N33-16-646-S-157-1	S	1	Open	\$675,463	REPLACE HEATING SYSTEM EQUIPMENT, BOILER, PIPING AND FIN TUBE RADIATORS, REPLACE VENT/EXHAUST CHIMNEY STAINLESS STEEL	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-002-1	M	1	Open	\$9,229	REPLACE EXTERIOR PAINTED SOFFIT BOARD, SINGLE STORY	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-010-1	M	1	Open	\$38,008	REPLACE STAINLESS STEEL KITCHEN SINK, COUNTERTOP MOUNTED, DOUBLE BOWL, WITH FAUCETS AND DRAIN, 33" X 22"	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-014-1	M	1	Open	\$31,853	REPLACE EVAPORATIVE COOLER 4216 TO 6300 CFM, 1-1/2 HP	Inspected by AME: TOBLER 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-018-1	M	1	Open	\$8,912	REPLACE INCANDESCENT FIXTURE, SURFACE MOUNTED, UP TO 150 WATT, INTERIOR	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CalRank
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-024-1	M	1	Open	\$290,100	REPLACE ELECTRICAL SERVICE AND DISTRIBUTION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-030-1	M	1	Open	\$6,907	REPLACE ELECTRICAL SERVICE AND DISTRIBUTION EQUIPMENT, 600 AMP; 3 PHASE, 120/208 VOLT SERVICE IN THE ELEMENTARY SCHOOL BUILDING, (AGED/COMPONENT RENEWAL), THROUGHOUT THE 89,880 SF BUILDING. COST SOURCE: RS MEANS 2008 ELECTRICAL COST DATA	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-041-1	M	1	Open	\$4,399	REPLACE CAST IN PLACE CONCRETE STAIRS	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-050-1	M	1	Open	\$5,597	REPLACE DRYWALL CEILING, OVER 5 SF PER LOCATION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-051-1	M	1	Open	\$4,578	REPLACE FIRE RETARDANT STAGE CURTAIN, VELOUR, MEDIUM WEIGHT	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-052-1	M	1	Open	\$9,312	REPLACE HARDWOOD CABINET DOOR, 5 SF TO 10 SF	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-053-1	M	1	Open	\$4,650	REPLACE DOUBLE HUNG WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, ALUMINUM FRAME	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-054-1	M	1	Open	\$6,468	REPLACE DOUBLE HUNG WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, ALUMINUM FRAME	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-055-1	M	1	Open	\$4,578	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL HANDICAP	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-058-1	M	1	Open	\$5,013	REPLACE HARDWOOD CABINET DOOR, 5 SF TO 10 SF	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-057-1	M	1	Open	\$25,241	REPLACE PLASTIC LAMINATE COUNTERTOP, UP TO 24" WIDE	FACCOM Inspected by AME: STANLEY 20-SEP-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-060-1	M	1	Open	\$5,495	REPLACE INSULATED STEEL EXTERIOR DOOR, FRAME AND HARDWARE, HALF GLASS, 3' X 7'	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-M-063-1	M	1	Open	\$9,161	REPLACE FOOTBALL/SOCCER FIELD SCOREBOARD	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-002-1	S	1	Open	\$5,992	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-004-1	S	1	Open	\$10,160	REPLACE DOUBLE DOOR WITH FRAME	BURNER REQUIRES ADDITIONAL VALVE	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	648	N33-16-648-S-005-1	S	1	Open	\$2,540	INSTALL SHUTOFF VALVE	FIREBOX IS DETERIORATING	Occupied	BIA Education	School, Elementary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	649	N33-16-648-M-004-1	M	1	Open	\$8,433	REPAIR THE REFRACTORY	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	649	N33-16-648-M-005-1	M	1	Open	\$3,541	REPLACE INSULATED STEEL EXTERIOR DOOR, FRAME AND HARDWARE, HALF GLASS, 3' X 7'	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	649	N33-16-648-M-008-1	M	1	Open	\$79,173	REPLACE GLASS STEEL EXTERIOR WITH HARDWARE, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	Multi-Purpose	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	649	N33-16-648-S-002-1	S	1	Open	\$4,389	REPLACE DOUBLE HUNG WINDOW, OVER 12 SF UP TO 24 SF, INSULATING GLASS, ALUMINUM FRAME	FACP INDICATES "TROUBLE" MODE	Occupied	BIA Education	Multi-Purpose	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-M-017-1	M	1	Open	\$5,842	REPLACE FIRE ALARM CONTROL PANEL	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-M-027-1	M	1	Open	\$92,259	REPLACE COMMERCIAL DRYER, 30 TO 50 LBS CAPACITY	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-M-029-1	M	1	Open	\$15,989	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-M-035-1	M	1	Open	\$9,098	REPLACE BATHUB/SHOWER TEMPERATURE CONTROL MIXING VALVE	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-M-039-1	M	1	Open	\$15,804	REPLACE WALL MOUNTED MIRROR WITH STAINLESS STEEL FRAME	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-S-002-1	S	1	Open	\$5,394	REPAIR CRACKS IN EXTERIOR INSULATION FINISH SYSTEM (EIFS)	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-S-024-1	S	1	Open	\$29,901	REPLACE FIRE ALARM CONTROL PANEL	FACP IN OFFICE INDICATES TROUBLE MODE	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-S-114-1	S	1	Open	\$15,392	REPR/REPL 4 H&V UNITS	FACCOM	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	671	N33-16-671-S-117-1	S	1	Open	\$41,124	REPLACE CONTROL SYSTEM 2 STAGE AIR COMPRESSOR, REPLACE CONTROL SYSTEM COMPRESSED AIR DRYER, REPLACE PNEUMATIC THERMOSTAT	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-003-1	M	1	Open	\$369,371	REPLACE EXISTING LOCKSET WITH LEVER HANDLE TYPE, COMMERCIAL KEYS, TO ACCOMMODATE ADA REQUIREMENTS, REPLACE PANIC HARDWARE	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-005-1	M	1	Open	\$7,025	UPGRADE TO DDC CONTROL SYSTEM FOR HVAC FROM PNEUMATIC CONTROL SYSTEM	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-009-1	M	1	Open	\$14,053	REPLACE EXPANSION JOINT	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-012-1	M	1	Open	\$5,792	REPLACE LIGHTING FIXTURE LENS, 2' X 4', RECESSED FLUORESCENT	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-014-1	M	1	Open	\$850,630	REPLACE CERAMIC WALL TILE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-022-1	M	1	Open	\$18,382	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION (300 SF AND OVER)	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-026-1	M	1	Open	\$77,420	REPLACE DOME PLEXIGLASS SKYLIGHT, 3' X 3'	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-031-1	M	1	Open	\$8,468	REPLACE 2' X 4' FIBERGLASS OR MINERAL SUSPENDED ACOUSTIC CEILING TILES, NO GRID	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-036-1	M	1	Open	\$57,048	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL HANDICAP	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-040-1	M	1	Open	\$8,910	REPLACE FIXED SASH WINDOW, OVER 6 SF UP TO 12 SF, INSULATING GLASS, ALUMINUM FRAME	Inspected by AME: HAWKINS 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	674	N33-16-674-M-040-1	M	1	Open	\$8,910	REPLACE WALL MOUNTED MIRROR WITH STAINLESS STEEL FRAME	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N33-16	Shonto Boarding School	874	N33-16-874-S-002-1	S	1	Open	\$5,394	REPLACE FIRE ALARM CONTROL PANEL	BUILDING FACP INDICATES TROUBLE MODE	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	874	N33-16-874-S-003-1	S	1	Open	\$13,970	REPAIR INSULATION	INSULATION NEEDS REPAIRS ON W073-1 AND W073-2	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	874	N33-16-874-S-044-1	S	1	Open	\$29,901	REPR/REPL 4 H&V UNITS	FACCOM	Occupied	BIA Education	Dormitory, School	Poor	S-1
									REPLACE ELECTRICAL SERVICE AND DISTRIBUTION						
Navajo Region	N33-16	Shonto Boarding School	874	N33-16-874-S-130-1	S	1	Open	\$78,708	REPLACE ELECTRICAL SERVICE AND DISTRIBUTION EQUIPMENT, 400 AMP, 3 PHASE; 120/208 VOLT IN THE DORMITORY BUILDING, (AGED/OBSOLETE), THROUGHOUT THE 42,742 SF BUILDING. COST SOURCE: RS MEANS 2008 ELECTRICAL COST DATA	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	Dormitory, School	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-M-002-1	M	1	Open	\$128,816	REPLACE WOOD PLANK ROOF DECKING	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-M-012-1	M	1	Open	\$4,489	REPLACE SERVICE SINK, CAST IRON, WALL/FLOOR MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-M-016-1	M	1	Open	\$187,895	REPLACE ROLL ROOFING (300 SF AND OVER)	PREVENT FURTHER DAMAGE TO BUILDING AND CONTENTS	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-M-021-1	M	1	Open	\$13,376	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR	Inspected by AME: CHRISMAN 20-SEP-1999	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-008-1	S	1	Open	\$5,394	REPLACE FIRE ALARM CONTROL PANEL	RA OFFICE 0-13: FACP IN TROUBLE MODE	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-010-1	S	1	Open	\$2,875	REPLACE FIRE RATED DOUBLE DOOR SYSTEM IN CORRIDOR	DOORS LACK 1-HR FIRE RATED SEPARATION IN CORRIDOR NEXT TO E-2	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-012-1	S	1	Open	\$5,384	REPLACE FIRE ALARM CONTROL PANEL	MANUAL PULL STATION TESTED AND ACTUATION OF ALARM DID NOT OCCUR WITHIN 10 SECONDS AT EXIT DOOR BY A-3	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-018-1	S	1	Open	\$4,584	REPLACE PANIC HARDWARE	LACKS PANIC HARDWARE AT EXIT DOORS BY LIBRARY	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-059-1	S	1	Open	\$29,901	REPR/REPAIR 4 H&V UNITS	FACCOM	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	876	N33-16-876-S-130-1	S	1	Open	\$6,350	INSTALL DUST COLLECTOR	FACCOM	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	789	N33-16-789-M-002-1	M	1	Open	\$16,399	REPLACE PAINTED WOOD SHEET SIDING, SINGLE STORY	AME Requested Backlog	Occupied	BIA Education	Conference	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	789	N33-16-789-M-005-1	M	1	Open	\$16,227	REPLACE 3' X 7' STEEL EXTERIOR DOOR, FRAME AND HARDWARE	Inspected by AME: STANLEY 20-SEP-1999	Occupied	BIA Education	Conference	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	790	N33-16-790-M-003-1	M	1	Open	\$4,814	REPLACE ASPHALT SHINGLES, 300 SF AND OVER	Inspected by AME: STANLEY 20-SEP-1999	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	790	N33-16-790-M-004-1	M	1	Open	\$6,580	REPLACE CARPET	Inspected by AME: STANLEY 20-SEP-1999	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	790	N33-16-790-M-005-1	M	1	Open	\$11,725	REPLACE PAINTED WOOD SHEET SIDING, SINGLE STORY	Inspected by AME: STANLEY 20-SEP-1999	Occupied	BIA Education	Office	Poor	M-1
Navajo Region	N33-16	Shonto Boarding School	790	N33-16-790-S-007-1	S	1	Open	\$2,771	INSTALL INTERIOR EMERGENCY, EXIT, OR COMBINATION FIXTURE	FACCOM	Occupied	BIA Education	Office	Poor	S-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-M-011-1	M	1	Open	\$53,262	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-M-023-1	M	1	Open	\$5,805	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-M-040-1	M	1	Open	\$5,719	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-M-075-1	M	1	Open	\$5,746	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-M-110-1	M	1	Open	\$4,809	REPLACE ASPHALT DRIVEWAY	AME Requested Backlog				N/A	M-1
Navajo Region	N33-16	Shonto Boarding School	Ground	N33-16-X01-S-001-1	S	1	Open	\$9,825	REPLACE PRESSURE RELIEF VALVE	BEYOND AGE LIMIT OF 10 YEARS AT F070-1, F070-2, F070-3, F070-4, AND F070-5				N/A	S-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-F-001-2	F	2	Open	\$216,600	UPDATE FIRE ALARM SYSTEM. OLD SYSTEM IS OUTDATED AND NEEDS REPLACEMENT	OUTDATED FIRE ALARM SYSTEM	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-017-1	M	1	Open	\$11,147	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 5-7/8" HIGH 1"- 1-1/4" COPPER TUBE	FACCOM Inspected by AME: BENDER 19-APR-1999	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-021-1	M	1	Open	\$12,540	Electrical distribution panel in boiler room is obsolete and in need of replacement. 2 panels with old type switches.	Outdated and in need of replacing	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-024-1	M	1	Open	\$249,437	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER, 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-027-1	M	1	Open	\$6,299	REPLACE HOLLOW CORE WOOD INTERIOR DOOR AND HARDWARE, UP TO 3' X 7'	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-029-1	M	1	Open	\$40,510	REPLACE INDOOR AIR-HANDLING UNIT, SINGLE ZONE, OVER 4000 UP TO 6,500 CFM	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-031-1	M	1	Open	\$114,000	ADDITION TO GYMNASIUM WAS DONE BY CONTRACTOR AND IS NOT UP TO BUILDING STANDARDS.	WATER LINES WERE NOT INSULATED, WALLS ARE SEPERATING	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	102	N32-11-102-M-033-1	M	1	Open	\$5,414	REPLACE DRYWALL CEILING, OVER 5 SF PER LOCATION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-F-001-2	F	2	Open	\$216,600	UPDATE FIRE ALARM SYSTEM WITH NEW SYSTEM AND CONNECT WITH OTHER BUILDINGS ON CAMPUS INCLUDING THE FIRE STATION.	OUTDATED FIRE ALARM SYSTEM.	Occupied	BIA Education	School, Elementary, Boarding	Poor	F-2
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-010-1	M	1	Open	\$227,822	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER, 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-013-1	M	1	Open	\$15,413	REPLACE 12' X 12' VINYL FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-015-1	M	1	Open	\$205,200	INSULATE BUILDING USING STUCCO COATING. CURRENTLY NO INSULATION ON EXTERIOR.	BUILDING IS NOT INSULATED. STUCCO COATING NEEDED TO ASSIST WITH HEATING AND COOLING COSTS.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-017-1	M	1	Open	\$4,469	UPDATE INTERCOM SYSTEM TO INCLUDE CLASSROOMS NOT CONNECTED.	INCLUDE CLASSROOMS NOT CONNECTED.	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-018-1	M	1	Open	\$17,885	REPLACE CENTRIFUGAL EXHAUST FAN, 4010 CFM, 23" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	103	N32-11-103-M-020-1	M	1	Open	\$19,185	REPLACE CENTRIFUGAL EXHAUST FAN, 13760 CFM, 35" SQUARE OR ROUND, ROOF OR WALL MOUNTED	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Boarding	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-F-001-2	F	2	Open	\$216,600	UPDATE FIRE ALARM SYSTEM. OLD SYSTEM IS OUTDATED AND NEEDS TO BE REPLACED.	SYSTEM IS OUTDATED AND NEEDS TO BE REPLACED.	Occupied	BIA Education	Dormitory, School	Poor	F-2

Region	Loc #	Location Name	Big Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-014-1	M	1	Open	\$219,026	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER, 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-018-1	M	1	Open	\$4,281	REPLACE BATHTUB/SHOWER TEMPERATURE CONTROL MIXING VALVE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-017-1	M	1	Open	\$57,617	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 8-7/8" HIGH 1"-1-1/4" COPPER TUBE	FACCOM Inspected by AME: BENDER 19-APR-1999	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-021-1	M	1	Open	\$228,000	HEATING AND VENTILATION SYSTEM NEEDS TO BE UPDATED TO PROVIDE COOLING TO BUILDING.	CURRENT SYSTEM DOES NOT PROVIDE COOLING AND IS INADEQUATE FOR THIS BUILDING.	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-022-1	M	1	Open	\$205,200	BUILDING IS NOT INSULATED ON THE EXTERIOR OF BLDG. STUCCO COATING WOULD HELP WITH HEATING COSTS.	INSULATING BUILDING WOULD HELP CUT FUEL COSTS AND KEEP BUILDING WARMER FOR BOTH STAFF AND STUDENTS.	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-025-1	M	1	Open	\$3,119	REPLACE ALUMINUM/VINYL EXTERIOR DOOR WEATHERSTRIPPING	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	104	N32-11-104-M-029-1	M	1	Open	\$2,547	REPLACE ROOFTOP VENTILATOR, RECTANGULAR ALUMINUM/GALVANIZED 12" X 16"	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-F-001-2	F	2	Open	\$87,000	FIRE ALARM SYSTEM IS OLD AND NEEDS TO BE UPGRADED.	FIRE ALARM SYSTEM NEEDS TO BE UPGRADED.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	F-2
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-009-1	M	1	Open	\$14,483	REPLACE 12" X 12" VINYL FLOOR TILE	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-013-1	M	1	Open	\$84,946	REPLACE MODIFIED BITUMINOUS ROOFING, MOP APPLIED, 300 SF AND OVER, 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-018-1	M	1	Open	\$111,070	REPLACE ORIGINAL 1983 HOT WATER HEATING SYSTEM THROUGHOUT THE 5,940 GSF CAFETERIA. CLIENT REPORTED EXCESSIVE MAINTENANCE. COST SOURCE:RS MEANS MECHANICAL 2010, PAGE 606, ITEM D5020-10B-1560 = \$12.16/SF X 5,940 GSF = \$72,171 X 1.35(DEMO/MATERIAL HANDLING/CONTINGENCIES) = \$97,430	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-018-1	M	1	Open	\$9,120	REPLACE STEAM KETTLE	KETTLE IS OUTDATED AND PARTS ARE HARD TO FIND FOR REPAIRS.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-019-1	M	1	Open	\$11,621	REPLACE FOOD MIXER	KITCHEN EQUIPMENT IS OUTDATED AND NEEDS TO BE CHANGED.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-020-1	M	1	Open	\$5,060	PEELER IN KITCHEN IS IN NEED OF REPLACEMENT.	PEELER IS IN NEED OF REPLACEMENT.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-021-1	M	1	Open	\$5,181	REPLACE FOOD SLICER. OLD UNIT IS IN NEED OF REPLACEMENT.	FOOD SLICER IS IN NEED OF REPLACEMENT.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-022-1	M	1	Open	\$10,025	REPLACE BAKE OVENS IN KITCHEN AREA.	BAKE OVENS ARE IN NEED OF REPLACEMENT. BEYOND SERVICE LIFE.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-023-1	M	1	Open	\$9,554	GRIDDLES IN KITCHEN AREA ARE IN NEED OF REPLACEMENT.	GRIDDLES IN KITCHEN AREA NEED REPLACEMENT.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-024-1	M	1	Open	\$4,864	FOOD WARMER ON SERVING LINE IS IN NEED OF REPLACEMENT.	FOOD WARMER IS IN NEED OF REPLACEMENT.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-025-1	M	1	Open	\$3,534	SERVING COUNTER IS IN NEED OF REPLACEMENT. OLD COUNTER IS OUTDATED AND HAS BENT LEGS DUE TO MOVING OF EQUIPMENT.	SERVING COUNTER IS IN NEED OF REPLACEMENT.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-026-1	M	1	Open	\$23,526	DISHWASHER IS OUTDATED AND NEEDS TO BE REPLACED.	DISHWASHER IS OUTDATED AND NEEDS TO BE REPLACED.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-027-1	M	1	Open	\$5,971	GARBAGE DISPOSAL IS OUTDATED AND IN NEED OF REPLACEMENT	DISPOSAL IS IN NEED OF REPLACEMENT	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-028-1	M	1	Open	\$14,197	REPLACE EXHAUST HOODS, EXISTING HOODS ARE OUTDATED AND NEED TO BE REPLACED.	EXHAUST HOODS ARE OUTDATED AND NEED REPLACING.	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-029-1	M	1	Open	\$5,130	REPLACE DEEP FRYER. OLD UNIT IS IN NEED OF REPLACEMENT	DEEP FRYER IS OLD AND IN NEED OF REPLACEMENT	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-030-1	M	1	Open	\$3,135	MILK COOLER HAS HAD NUMEROUS BREAKDOWNS AND NEEDS TO BE REPLACED.	MILK COOLER NEEDS REPLACEMENT	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	105	N32-11-105-M-031-1	M	1	Open	\$3,313	REPLACE FAN COIL UNIT, CHILLED WATER AND OR HOT WATER HEATING COILS, HORIZONTAL/VERTICAL, OVER 1-1/2"	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-M-041-1	M	1	Open	\$40,135	REPLACE 3' CONCRETE RAMP WITH STEEL CURB AND RAILS TO ACCOMMODATE ADA REQUIREMENTS	AME Requested Backlog				N/A	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-M-044-1	M	1	Open	\$4,478	REPLACE CATTLEGUARD, PIT TYPE, 8' X 18' WITH WINGS	AME Requested Backlog				N/A	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-M-046-1	M	1	Open	\$6,430	REPLACE CONCRETE CURB AND GUTTER, STRAIGHT	AME Requested Backlog				N/A	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-M-049-1	M	1	Open	\$399,000	UPGRADE CELL #4 TO CURRENT EPA REGULATIONS. PROPERLY CLOSE CELLS 1 AND 2. INSTALL NEW SEWER LINES FROM EXISTING LINE TO CONNECT DIRECTLY TO CELL #4	SEWER LAGOON CELLS NEED TO BE UPGRADED.				N/A	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-M-055-1	M	1	Open	\$5,846	REPLACE CATTLEGUARD, PIT TYPE, 8' X 20' WITH WINGS	AME Requested Backlog				N/A	M-1
Navajo Region	N32-11	To'haali' (Toadlena) Community School	Ground	N32-11-X01-S-017-1	S	1	Open	\$5,846	REPLACE CATTLEGUARD, PIT TYPE, 8' X 20' WITH WINGS	FACCOM Inspected by AME: BENDER 19-APR-1999				N/A	S-1
Navajo Region	N33-13	Tonalea/Redlake Day School	875	N33-13-875-M-003-1	M	1	Open	\$4,629	REPLACE SUBMERSIBLE PUMP, 2 HP	Inspected by AME: PELEN 20-SEP-1999	Occupied	BIA Education	Pump House	Poor	M-1
Navajo Region	N33-13	Tonalea/Redlake Day School	888	N33-13-888-M-003-1	M	1	Open	\$6,503	REPLACE 12" X 12" STAPLED OR CEMENTED MINERAL FIBER ACOUSTIC CEILING TILES	AME Requested Backlog	Occupied	BIA Education	School, Middle, Day	Poor	M-1
Navajo Region	N33-13	Tonalea/Redlake Day School	886	N33-13-886-S-003-1	S	1	Open	\$11,190	INSTALL FIRE ALARM SYSTEM	MISSING	Occupied	BIA Education	School, Middle, Day	Poor	S-1

Region	Loc #	Location Name	Bidg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank	
Navajo Region	N33-13	Tonalea/Redlake Day School	888	N33-13-888-S-017-1	S	1	Open	\$14,114	REPLACE LIGHTING, ELECTRIC SERVICE AND LOAD CENTER REPLACE ELECTRICAL SERVICE FROM 100AMP TO 200AMP, LOAD CENTER FROM 100AMP TO 200AMP, AND LIGHTING FIXTURES IN MIDDLE SCHOOL. ALL LIGHTING FIXTURES TO HAVE T8 LAMPS AND ELECTRONIC BALLASTS. COST PRICING FROM RSM FAC. 2009, D5010-120-0620 (MODIFIED) AND SPT ITEM 15 AND RSM ELEC. 5010-117 COL. 2 (MODIFIED).	Inspected by AME: PEELEN 20-SEP-1999	Occupied	BIA Education	School, Middle, Day	Poor	S-1	
Navajo Region	N33-13	Tonalea/Redlake Day School	Ground	N33-13-X01-M-003-1	M	1	Open	\$11,491	REPLACE PLAYGROUND, BASIC	The present slide equipment is getting old and may soon be unsafe to use				N/A	M-1	
Navajo Region	N33-13	Tonalea/Redlake Day School	Ground	N33-13-X01-M-022-1	M	1	Open	\$43,700	Clean up old abandoned well site	Clean up well head				N/A	M-1	
Navajo Region	N33-13	Tonalea/Redlake Day School	Ground	N33-13-X01-M-023-1	M	1	Open	\$97,145	REMOVE WATER TOWER, 100,000 TO 500,000 GAL	Unused, old elevated water storage tank at Tonalea Day School schoolgrounds is a hazardous instrument to the students and also the local community teens. The school has had numerous incidents in the past where students & local residents, especially teenagers attempted to climb the old water storage tank with no intentions for safety. The school has a few police reports documenting incidents/accidents pertaining to the school's water tank. The school lacks security during the night time hours due to lack of funding and this is the time when most incidents occur. The perpetrators jump right over the security fence to enter into the location of the tank and have a ladder readily available to climb. To avoid further problems and incidents and for the safety of the students, the water tank needs to be demolished soon to avoid any major accidents in the future.					N/A	M-1
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	162197	N34-16-162197-M-005-1	M	1	Open	\$4,305	REPLACE EVAPORATIVE COOLER 4216 UP TO 8300 CFM, 1-1/2 HP	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	162198	N34-16-162198-M-003-1	M	1	Open	\$7,417	REPLACE BASE CABINETS, HARDWOOD, PREFINISHED OR LAMINATE	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	162199	N34-16-162199-M-008-1	M	1	Open	\$4,305	REPLACE EVAPORATIVE COOLER UP TO 4216 CFM, 3/4 HP	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-F-001-2	F	2	Open	\$40,538	INSTALL FIRE SPRINKLER SYSTEM INSTALL FIRE SPRINKLER SYSTEM IN A 4,415 SF SCHOOL. COST SOURCE: RS MEANS FACILITIES CONSTRUCTION COST DATA PAGE 1194, ITEM D4010 410 1080 ; \$4.48/SF X 4,415 SF= \$19,691 X 1.35(DEMO/CONTINGENCIES/MATERIAL HANDLING) = \$26,583	Currently the buildings are not equipped with sprinkler system, and needs it for fire protection for the building and safety of the students	Occupied	BIA Education	School, Other, Day	Poor	F-2	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-008-1	M	1	Open	\$5,528	REPLACE COMMERCIAL FOOD MIXER, 20 QUART	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-007-1	M	1	Open	\$6,503	REPLACE ELECTRIC HOT-WELL FOR SERVING LINE	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-008-1	M	1	Open	\$3,130	REPLACE STANDARD COMMERCIAL COOKTOP RANGE WITH OVEN	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-011-1	M	1	Open	\$16,464	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 5 TO 7-1/2 TON	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-013-1	M	1	Open	\$16,464	REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, OVER 5 TO 7-1/2 TON	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	401	N34-16-401-M-014-1	M	1	Open	\$6,754	REPLACE 1 COMPARTMENT REACH-IN COMMERCIAL REFRIGERATOR	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	424	N34-16-424-M-005-1	M	1	Open	\$11,181	REPLACE OUTDOOR WALL MOUNTED PACKAGE UNIT, HEATING AND COOLING, UP TO 5 TON, FOR TRAILERS AND MODULARS	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-M-006-1	M	1	Open	\$29,008	REPLACE GRAVEL SURFACE, SPREAD BY MACHINE, 4" THICK	AME Requested Backlog				N/A	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-M-008-1	M	1	Open	\$34,500	Demolish old abandoned water tank	Demolish tank				N/A	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-M-009-1	M	1	Open	\$43,700	CAP ABANDONED WELL, UP TO 6" CASING	Clean up old well head				N/A	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-M-012-1	M	1	Proposed	\$15,180	The elevated tank needs to be fenced to prevent unauthorized personnel entering. Install 150' LF x 8' high chain link fence around the elevated tank.	Currently there's no fence to keep unauthorized personnel entering to prevent them climbing the elevated tower.				N/A	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-M-016-1	M	1	Open	\$63,987	The school does not have Intercom system, in case of emergency there's no communication between one building to another for security purpose.	The school does not have any type of communication between buildings for security purpose and to meet homeland security requirement.				N/A	M-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-S-083-1	S	1	Open	\$15,522	REPLACE REDUCED PRESSURE TYPE BACKFLOW PREVENTER, 1-1/2" TO 2"	Inspected by AME: WATSON 04-DEC-00				N/A	S-1	
Navajo Region	N34-16	Tse'Il'ah'i (Standing Rock) Community School	Ground	N34-16-X01-S-065-1	S	1	Open	\$28,394	CONSTRUCT CHEMICAL STORAGE AT N34-16 CONSTRUCT CHEMICAL STORAGE BUILDING WITH PROPER CONTAINMENT AND SEGREGATION WITH SIGNAGE AND VENTILATION. EXISTING STORAGE AREA IS INADEQUATE. COST SOURCE: RS MEANS BUILDING CONSTRUCTION COST DATA 2010; ITEM 50 87 0010; 3/4 COST; PAGE 815 + BIA 42% SOFT COSTS = \$120.70/GSF X 225 GSF = \$27,155	FACCOM				N/A	S-1	
Northwest Region	P05-02	Coeur D'Alene Tribal School	Ground	P05-02-X01-M-002-1	M	1	Open	\$20,883	REPLACE CONCRETE WALL	AME Requested Backlog				N/A	M-1	
Northwest Region	P05-02	Coeur D'Alene Tribal School	Ground	P05-02-X01-M-008-1	M	1	Open	\$8,504	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog				N/A	M-1	
Northwest Region	P10-02	Quileute Tribal School	101T	P10-02-101T-M-010-1	M	1	Open	\$3,072	REPLACE INTERIOR WALL WOOD TRIM	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1	
Northwest Region	P10-02	Quileute Tribal School	101T	P10-02-101T-M-011-1	M	1	Open	\$2,791	REPLACE STAIR RAILING, STOCK, INTERIOR WALL MOUNTED	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1	
Northwest Region	P10-02	Quileute Tribal School	101T	P10-02-101T-M-019-1	M	1	Open	\$4,049	REPLACE FIXED SASH WINDOW, ALUMINUM FRAME	AME Requested Backlog	Occupied	Grant Education	Office	Poor	M-1	
Northwest Region	P10-02	Quileute Tribal School	101T	P10-02-101T-S-004-1	S	1	Open	\$9,071	DUPLICATE BACKLOG	OUTDATED ELECTRICAL FUSE BOX IS STILL IN USE AND MAY NOT BE ADEQUATE FOR ELECTRICAL LOAD	Occupied	Grant Education	Office	Poor	S-1	
Northwest Region	P10-02	Quileute Tribal School	Ground	P10-02-X01-M-005-1	M	1	Open	\$18,536	REPLACE PAINTED CONCRETE SITE WALL, 9" TO 12" THICK	AME Requested Backlog				N/A	M-1	
Northwest Region	P10-02	Quileute Tribal School	Ground	P10-02-X01-S-002-1	S	1	Open	\$18,338	REPLACE PLAYGROUND, COMPLEX	HAZARDOUS				N/A	S-1	

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Southern Plains Region	B01-02	Riverside Indian School	219	B01-02-219-M-01E-1	M	1	Proposed	\$17,184	REPLACE CAST IRON BOILER, STEAM/HOT WATER, 361 TO 544 MBH	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	219	B01-02-219-M-01E-1	M	1	Proposed	\$45,342	REPLACE RECIPROCATING CHILLER, AIR COOLED, OVER 25 TO 30 TON	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	220	B01-02-220-M-01E-1	M	1	Proposed	\$17,184	REPLACE CAST IRON BOILER, STEAM/HOT WATER, 361 TO 544 MBH	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	220	B01-02-220-M-017-1	M	1	Proposed	\$45,342	REPLACE RECIPROCATING CHILLER, AIR COOLED, OVER 25 TO 30 TON	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	225	B01-02-225-M-01E-1	M	1	Proposed	\$6,079	REPLACE COMMERCIAL WATER HEATER, GAS, 73 UP TO 110 GPH	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	225	B01-02-225-S-001-1	S	1	Proposed	\$24,500	REPLACING THE BOILER	AGING/DETERIORATED	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	225	B01-02-225-S-002-1	S	1	Proposed	\$3,387	Replace fire alarm control panel	trouble light is on	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	233	B01-02-233-S-002-1	S	1	Proposed	\$74,412	Replace existing electrical system with a new system to include wiring, distribution, and branch circuitry	ged and deteriorating which can adversely affect the safe operation of the system	Occupied	BIA Education	Gymnasium	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	233	B01-02-233-S-003-1	S	1	Proposed	\$4,412	replace exit lights and emergency lights	nonoperational/damaged/missing	Occupied	BIA Education	Gymnasium	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	233	B01-02-233-S-019-1	S	1	Proposed	\$107,497	REPLACE COOLING SYSTEM	FACCOM Inspected by AME: MILLER 16-FEB-99	Occupied	BIA Education	Gymnasium	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	233	B01-02-233-S-020-1	S	1	Proposed	\$10,992	REPLACE PLUMBING SYSTEM INCLUDING TOILET AND SERVICE FIXTURES, SUPPLY AND DRAINAGE PIPING	FACCOM Inspected by AME: MILLER 16-FEB-99	Occupied	BIA Education	Gymnasium	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	272	B01-02-272-S-902-1	S	1	Proposed	\$9,800	RENOVATE KITCHEN	FACCOM	Occupied	BIA Education	Office	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	272	B01-02-272-S-903-1	S	1	Proposed	\$9,800	RENOVATE BATHROOM	FACCOM	Occupied	BIA Education	Office	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	272	B01-02-272-S-904-1	S	1	Proposed	\$4,900	REPLACE ALL UTILITY LINES	FACCOM	Occupied	BIA Education	Office	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	272	B01-02-272-S-905-1	S	1	Proposed	\$19,800	INSTALL VINYL SIDING	FACCOM	Occupied	BIA Education	Office	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	279	B01-02-279-M-00E-1	M	1	Proposed	\$10,036	REPLACE 3' X 7' WOOD INTERIOR SOLID CORE DOOR, FRAME AND HARDWARE, VISION LITE	AME Requested Backlog	Occupied	BIA Education	School, Secondary, Boarding	Poor	M-1
Southern Plains Region	B01-02	Riverside Indian School	279	B01-02-279-S-001-1	S	1	Proposed	\$44,691	Replace fire door and frame up to 90 minute rating, Install an additional 200,000 Gal. water tower that will assist with the water demands and pressure that the campus requires for adequate fire protection.	existing louvered doors are not fire or smoke resistant school campus does not have adequate fire protection.	Occupied	BIA Education	School, Secondary, Boarding	Poor	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-013-1	M	1	Proposed	\$977,334	REPLACE 2" X 6" WOOD DECKING FOR EXTERIOR DECK	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-015-1	M	1	Proposed	\$2,886	REPLACE CAST IN PLACE CONCRETE STAIRS	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-017-1	M	1	Proposed	\$2,952	REPLACE ASPHALT PAVING	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-023-1	M	1	Proposed	\$5,153	REPLACE BASKETBALL RIM	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-025-1	M	1	Proposed	\$4,886	REPLACE DOUBLE GATE, CHAIN LINK	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-026-1	M	1	Proposed	\$7,730	Entire Fire Alarm system not working for entire campus.	existing system is not working properly for entire campus				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-032-1	M	1	Proposed	\$182,258	REPLACE 13" TO 16" THICK BRICK SITE WALL	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-050-1	M	1	Proposed	\$6,397	REPLACE ASPHALT PARKING LOT	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-055-1	M	1	Proposed	\$7,085	REPLACE CONCRETE DRIVEWAY, OVER 8 SF	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-M-061-1	M	1	Proposed	\$3,807	REPLACE CONCRETE BENCH, 8' LONG	AME Requested Backlog				N/A	M-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-001-1	S	1	Proposed	\$7,286	Replace panel board cover, indoor, flush or surface	damaged, open, not locked				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-002-1	S	1	Proposed	\$9,131	Replace exit light w/battery backup	(nonoperational/damaged/missing)				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-008-1	S	1	Proposed	\$36,881	Replace existing lockset with lever handle	missing/badly damaged,				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-009-1	S	1	Proposed	\$234,877	duplicate backlog, Replace fire door and frame	badly damaged from vandalism				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-011-1	S	1	Proposed	\$9,131	duplicate backlog, Replace exit light w/battery backup	(nonoperational/damaged/missing)				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-012-1	S	1	Proposed	\$7,286	duplicate backlog, Replace panel board cover, indoor, flush or surface	damaged, open, not locked				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-016-1	S	1	Proposed	\$4,627	duplicate backlog, Replace emergency backup lighting fixture	(loose/not operable)				N/A	S-1
Southern Plains Region	B01-02	Riverside Indian School	Grounds	B01-02-X01-S-018-1	S	1	Proposed	\$2,762	REPLACE WOOD BRIDGE WITH DIMENSIONAL LUMBER, UP TO 10' WIDE	AME Requested Backlog				N/A	S-1
Southwest Region	M20-05	Jemez Day School	Grounds	M20-05-X01-M-00E-1	M	1	Open	\$13,672	PATCH STUCCO ON EXTERIOR SITE WALLS, BASED ON SURFACE AREA	AME Requested Backlog				N/A	M-1
Southwest Region	M20-05	Jemez Day School	Grounds	M20-05-X01-M-013-1	M	1	Open	\$10,500	Jemez Day School playground equipment can not be repair.	Existing playground equipment can not be repair. The school needs new equipment				N/A	M-1
Southwest Region	M21-02	Laguna Elementary School	Grounds	M21-02-X01-M-02E-1	M	1	Open	\$6,973	Repair roofing on Canopy	Roof understructure is deteriorated				N/A	M-1
Southwest Region	M21-02	Laguna Elementary School	Grounds	M21-02-X01-M-027-1	M	1	Open	\$12,426	Excavate and replace water valves	Valves are inoperable, they do not turn				N/A	M-1
Southwest Region	M25-14	Ohkay Owingeh (San Juan) Community School	732	M25-14-732-M-00E-1	M	1	Open	\$6,957	Replace front and back doors, with Fire rated doors and panic hardware.	Both doors are in deteriorated condition also need panic hardware.	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Southwest Region	M25-14	Ohkay Owingeh (San Juan) Community School	732	M25-14-732-M-00E-1	M	1	Open	\$5,740	REPLACE MODIFIED BITUMINOUS ROOFING, TORCH APPLIED	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Southwest Region	M25-14	Ohkay Owingeh (San Juan) Community School	732	M25-14-732-S-001-1	S	1	Open	\$2,857	REPLACE DRYWALL WITH FIRE RATED DRYWALL	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	S-1
Southwest Region	M25-16	Santa Clara Day School	Grounds	M25-16-X01-M-02E-1	M	1	Open	\$11,340	Covered walkways on grounds attached to building numbers 762, 763, 764, 766, 757 need new lighting fixtures for walkways. Light timer are not working and most of the fixtures are not working	Inoperative fixtures.				N/A	M-1
Southwest Region	M25-16	Santa Clara Day School	Grounds	M25-16-X01-M-02E-1	M	1	Open	\$4,272	REPLACE POST AND BOARD RETAINING WALL	AME Requested Backlog				N/A	M-1
Southwest Region	M25-19	Taos Day School	785	M25-19-785-M-001-1	M	1	Open	\$4,494	REPLACE BUILT-UP ROOFING, UNDER 300 SF, UP TO 4 PLY	AME Requested Backlog	Occupied	BIA Education	Pump House	Poor	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Western Region	H57-13	Casa Blanca Day School	Ground	H57-13-X01-M-002-1	M	1	Open	\$4,002	REPLACE CHAIN LINK GATE, UP TO 8' X 16'	AME Requested Backlog				N/A	M-1
Western Region	H57-13	Casa Blanca Day School	Ground	H57-13-X01-M-006-1	M	1	Open	\$10,001	The A/C air ducts have not been cleaned since they were installed in 1989. Thru visual inspection I found an alarming excess of debris present.	Thru visual inspection I determined that an alarming excess of debris is present. I discussed this with Dennis Rodriguez and he commented that there is a viable concern with the IAQ in our buildings. He also stated that in some extreme cases, when funding has not been accessible thru O&M money and a project has been neglected there is a possibility of the scope of the work changing from a preventative maintenance issue (O&M) to a capitol projects (M&R) issue. Dennis went on to explain that a campus wide project may actually reduce the cost of the entire work as opposed to the cost of completing individual buildings. I researched this and found his line of thinking to be true. This backlog will supercede backlogs H57-13-420-M-006-01 (\$9,435.00), H57-13-421-M-018-1 (\$11,955.00), H57-13-422-007-01 (\$14,736.00) and H57-13-423-005-01 (\$9,453.00) These old backlogs total \$45,600.00. The proposal I have on my desk totals only \$10,001.00.				N/A	M-1
Western Region	H64-08	Duckwater Shoshone Elementary School	127T	H64-08-127T-M-005-1	M	1	Open	\$6,536	REPLACE DOUBLE DOOR WITH FRAME, FLUSH STEEL EXTERIOR WITH HARDWARE, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H64-08	Duckwater Shoshone Elementary School	127T	H64-08-127T-M-013-1	M	1	Open	\$7,404	REPLACE ASPHALT SHINGLES, 300 SF AND OVER	Inspected by AME: STANLEY 25-OCT-1989	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H64-08	Duckwater Shoshone Elementary School	127T	H64-08-127T-S-047-1	S	1	Open	\$3,204	ENLARGE WINDOW OPENING AND INSTALL A SLIDING ALUMINUM FRAME 60" X 48" WINDOW WITH INSULATING GLASS SUITABLE FOR EMERGENCY EGRESS	FACCOM	Occupied	BIA Education	School, Elementary, Day	Poor	S-1
Western Region	H64-08	Duckwater Shoshone Elementary School	129T	H64-08-129T-M-006-1	M	1	Open	\$6,533	REPLACE DOUBLE DOOR WITH FRAME, FLUSH STEEL EXTERIOR WITH HARDWARE, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	Gymnasium	Poor	M-1
Western Region	H64-08	Duckwater Shoshone Elementary School	128T	H64-08-128T-M-007-1	M	1	Open	\$4,359	REPLACE ROLLED ROOFING, 300 SF AND OVER	AME Requested Backlog	Occupied	BIA Education	Gymnasium	Poor	M-1
Western Region	H64-08	Duckwater Shoshone Elementary School	128T	H64-08-128T-M-016-1	M	1	Open	\$47,516	REPLACE BUILT-UP ROOFING, 300 SF AND OVER, UP TO 4 PLY AND 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	Gymnasium	Poor	M-1
Western Region	H65-13	Hopi Day School	402-5	H65-13-402-5-M-008-1	M	1	Open	\$5,060	CONDUCT AN ENGINEERING STUDY TO DETERMINE THE CAUSE AND MAKE A CORRECTIVE ACTION RECOMMENDATION.	AME Requested Backlog	Occupied	BIA Education	Office	Poor	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	501	H65-14-501-M-043-1	M	1	Open	\$21,981	REPLACE FIN TUBE BASEBOARD MOUNTED STEAM/HOT WATER 8-7/8" HIGH 1"- 1-1/4" COPPER TUBE	Inspected by AME: SELLERS 22-MAR-1999	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	501	H65-14-501-M-046-1	M	1	Open	\$21,517	REPLACE EVAPORATIVE COOLER UP TO 4215 CFM, 3/4 HP	Inspected by AME: SELLERS 22-MAR-1999	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	508	H65-14-508-M-005-1	M	1	Open	\$3,511	REPLACE EVAPORATIVE COOLER 4215 UP TO 6300 CFM, 1-1/2 HP	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	508	H65-14-508-M-007-1	M	1	Open	\$5,052	REPLACE FURNACE, HOT AIR HEATING, OIL/GAS, OVER 150 TO 200 MBH	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-020-1	M	1	Open	\$3,238	Install first aid equipment, fire extinguisher, cable ladder, warning signage, exterior lighting and pull more slack for drip loop	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-021-1	M	1	Open	\$7,593	Install surge protector, building ground, repair cable entry port, install interior and exterior ground buss, ground kits on existing cables, ground on coax and control cables and top, middle and bottom ground kits on cable.	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-024-1	M	1	Open	\$2,741	Install building halo	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-025-1	M	1	Open	\$7,824	Install fence ground ring	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-028-1	M	1	Open	\$3,185	Install site ground ring	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-027-1	M	1	Open	\$5,306	Install guy anchor grounding, ground bars and repair tower grounding as required	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-028-1	M	1	Open	\$2,513	Install safety climb tower	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-029-1	M	1	Open	\$5,287	Install ice bridge	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-030-1	M	1	Open	\$5,510	Repair cable support and reroute cable	Mindbank inspection				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-033-1	M	1	Open	\$16,788	REPLACE DECK	AME Requested Backlog				N/A	M-1
Western Region	H65-14	Hotavilla Bacavi Community School	Ground	H65-14-X01-M-034-1	M	1	Open	\$167,206	ARRA LMR for Hotavilla/Spider Mound Project: Remove all LMR equipment from Hotavilla site and upgrade new site, and prepare new site at Spider Mound.	ARRA LMR Repair/Upgrade communication equipment and site.				N/A	M-1
Western Region	H52-12	John F. Kennedy Day School	411	H52-12-411-M-011-1	M	1	Open	\$12,442	REPLACE UNBALLASTED SINGLE PLY MEMBRANE, RUBBER/PLASTIC ROOFING, 300 SF AND OVER, 2" INSULATION	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	411	H52-12-411-M-012-1	M	1	Open	\$8,752	REPLACE CARPET	FACCOM Inspected by AME: BANDI 16-FEB-99; Inspected by AME: VERA CRUZ 23-APR-01	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	411	H52-12-411-M-013-1	M	1	Open	\$4,386	REPLACE STAINLESS STEEL KITCHEN SINK, COUNTERTOP MOUNTED, DOUBLE BOWL, WITH FAUCETS AND DRAIN, 33" X 22"	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	411	H52-12-411-M-015-1	M	1	Open	\$15,751	REPLACE BASE CABINETS, HARDWOOD, PREFINISHED OR LAMINATE	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	415T	H52-12-415T-M-002-1	M	1	Open	\$18,360	REPLACE PAINTED WOOD SHEET SIDING, SINGLE STORY	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	413T	H52-12-413T-M-008-1	M	1	Open	\$10,168	REPLACE CONCRETE SIDEWALK, OVER 8 SF	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	415T	H52-12-415T-M-010-1	M	1	Open	\$2,694	REPLACE ALUMINUM BOX GUTTERS	AME Requested Backlog	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	T30	H52-12-T30-M-013-1	M	1	Open	\$10,139	REPLACE PAINTED EXTERIOR WOOD SKIRT SIDING	Inspected by AME: VERA CRUZ 23-APR-01	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	T30	H52-12-T30-M-014-1	M	1	Open	\$14,407	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	FACCOM Inspected by AME: PEELLEN 16-FEB-99; Inspected by AME: VINSON 23-APR-01	Occupied	BIA Education	School, Elementary, Day	Poor	M-1
Western Region	H52-12	John F. Kennedy Day School	Ground	H52-12-X01-M-016-1	M	1	Open	\$3,172	REPLACE METAL STAIRS WITH PIPE RAILING	AME Requested Backlog				N/A	M-1

Region	Loc #	Location Name	Bldg Num	Backlog Number	Cat	Rank	Backlog Status	Backlog Cost	Backlog Title	Backlog Justification	Structure Status	Maintained By	Structure Use	FCI Condition	CatRank
Western Region	H52-12	John F. Kennedy Day School	Ground	H52-12-X01-M-020-1	M	1	Open	\$5,760	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Western Region	H52-12	John F. Kennedy Day School	Ground	H52-12-X01-M-022-1	M	1	Open	\$16,999	REPLACE STEEL HANDICAPPED RAMP	AME Requested Backlog				N/A	M-1
Western Region	H52-12	John F. Kennedy Day School	Ground	H52-12-X01-M-023-1	M	1	Open	\$41,484	REPLACE CONCRETE BASKETBALL COURT	AME Requested Backlog				N/A	M-1
Western Region	H54-22	San Simon School	911	H54-22-911-M-001-1	M	1	Open	\$8,559	REPLACE UNHEATED AIR CURTAIN UP TO 80" LONG	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1
Western Region	H54-22	San Simon School	911	H54-22-911-M-009-1	M	1	Open	\$3,262	REPLACE EVAPORATIVE COOLER 4216 UP TO 9300 CFM, 1-1/2 HP	FACCOM Inspected by AME; PHELPS 16-FEB-99; Inspected by AME; CROPPER 23-APR-01	Occupied	BIA Education	School, Other, Day	Poor	M-1
Western Region	H54-22	San Simon School	911	H54-22-911-S-005-1	S	1	Open	\$4,012	INSTALL NEW PULL STATION AT THE WEST EXIT	THIS IS A SAFETY ITEM AND NEEDS TO BE ADDRESSED IMMEDIATELY IN ORDER TO COMPLY WITH THE LIFE SAFETY CODE AND NAPA 72 FIRE REQUIREMENTS.	Occupied	BIA Education	School, Other, Day	Poor	S-1
Western Region	H54-22	San Simon School	913	H54-22-913-M-001-1	M	1	Open	\$45,022	REPLACE SINGLE PLY MEMBRANE WITH TAPERED INSULATION, 300 SF AND OVER	Inspected by AME; ACKERMAN 23-APR-01	Occupied	BIA Education	School, Other, Day	Poor	M-1
Western Region	H54-22	San Simon School	913	H54-22-913-M-004-1	M	1	Open	\$7,974	REPLACE HID FIXTURE, RECESSED, UP TO 179 WATT, INTERIOR	AME Requested Backlog	Occupied	BIA Education	School, Other, Day	Poor	M-1
Western Region	H54-22	San Simon School	913	H54-22-913-M-012-1	M	1	Open	\$107,350	Replace 30 YR old roofing, is leaking and deteriorating entire roof structure.	Roof old and deteriorating badly.	Occupied	BIA Education	School, Other, Day	Poor	M-1
Western Region	H54-22	San Simon School	928	H54-22-928-M-009-1	M	1	Open	\$5,838	REPLACE STUCCO, ON CEMENT BOARD	FACCOM Inspected by AME; TRACY 16-FEB-99; Inspected by AME; ACKERMAN 23-APR-01	Occupied	BIA Education	School, Middle, Day	Poor	M-1
Western Region	H54-22	San Simon School	928	H54-22-928-M-017-1	M	1	Open	\$10,899	INSTALL LARGE PORTIAL A/C UNITS FOR THE CLASS ROOM.	THESE UNITS ARE NEED FOR THE CLASS ROOM TO PROVIDE COOL AIR FOR THE STUDENTS, AND TBACHER. CURRENTLY CLASS ROOM IS BEING COOLED BY EVAPORATIVE COOLING BUT THIS SYSTEM IS NOT WORKING PROPERLY AND STUDENTS AND TBACHER WILL BE UNABLE TO CONCENTRATE ON THEIR TEACHING AND LEARNING. SCHOOL WILL START UP ON AUGUST 7, 2008. IT WOULD BE GOOD TO HAVE THEM IN PLACE WHEN THE STUDENTS ARRIVE.	Occupied	BIA Education	School, Middle, Day	Poor	M-1
Western Region	H54-22	San Simon School	Ground	H54-22-X01-M-019-1	M	1	Open	\$4,402	REPLACE POLE MOUNTED LIGHT FIXTURE, 400W HID	AME Requested Backlog				N/A	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-002-1	M	1	Open	\$66,802	CLEAN BUILDING METAL DUCT SYSTEM	Inspected by AME; MENZEL 23-APR-01	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-009-1	M	1	Open	\$559,771	USE A CRANE TO REPLACE OUTDOOR PACKAGE UNIT, HEAT AND COOLING, ON ROOF, OVER 25 UP TO 30 TONS	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-011-1	M	1	Open	\$4,052	INSTALL DOOR ALARM, INDEPENDENT, NOT CONNECTED TO SECURITY SYSTEM	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-012-1	M	1	Open	\$3,742	REPLACE CARPET	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-013-1	M	1	Open	\$2,699	REPLACE LOUVERED EXTERIOR STEEL DOUBLE DOORS WITH FRAME, UP TO 8' X 8'	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-014-1	M	1	Open	\$7,489	REPLACE WATER CLOSET COMPARTMENT, PAINTED METAL	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-016-1	M	1	Open	\$3,897	REPLACE WALL/FLOOR MOUNTED WATER CLOSET, TANK TYPE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-017-1	M	1	Open	\$3,444	REPLACE LAVATORY FAUCET WITH POP-UP DRAIN	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-018-1	M	1	Open	\$2,816	REPLACE WATER COOLER, WALL MOUNTED, WHEELCHAIR TYPE	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	459	H54-21-459-M-019-1	M	1	Open	\$6,814	REPLACE INTERIOR SURFACE MOUNT FLUORESCENT FIXTURE, 1' X 4', WRAP AROUND LENS, 40 WATT, T-12	AME Requested Backlog	Occupied	BIA Education	Dormitory, School	Poor	M-1
Western Region	H54-21	Santa Rosa Boarding School	Ground	H54-21-X01-M-027-1	M	1	Open	\$72,328	CONSTRUCT/ REPLACE BASEBALL FIELD	AME Requested Backlog				N/A	M-1
Western Region	H54-21	Santa Rosa Boarding School	Ground	H54-21-X01-M-028-1	M	1	Open	\$72,328	CONSTRUCT/ REPLACE BASEBALL FIELD	AME Requested Backlog				N/A	M-1
Western Region	H54-11	Santa Rosa Ranch School	202	H54-11-202-M-001-1	M	1	Open	\$4,051	REPLACE ENAMELED CAST IRON KITCHEN SINK, COUNTERTOP MOUNTED, DOUBLE BOWL, WITH FAUCETS AND DRAIN, 33" X 22"	AME Requested Backlog	Occupied	BIA Education	Office	Poor	M-1
Western Region	H54-11	Santa Rosa Ranch School	202	H54-11-202-M-002-1	M	1	Open	\$5,485	REPLACE ASPHALT SHINGLES, CLASS A, 300 SF AND OVER	FACCOM Inspected by AME; FUSS 18-FEB-99; Inspected by AME; VERA CRUZ 23-APR-01	Occupied	BIA Education	Office	Poor	M-1
Western Region	H54-11	Santa Rosa Ranch School	202	H54-11-202-M-009-1	M	1	Open	\$4,041	REPLACE EVAPORATIVE COOLER UP TO 4215 CFM, 3/4 HP	Inspected by AME; VINSON 23-APR-01	Occupied	BIA Education	Office	Poor	M-1
Western Region	H54-11	Santa Rosa Ranch School	Ground	H54-11-X01-M-002-1	M	1	Open	\$9,037	REPLACE CONCRETE BENCH, 8' LONG	AME Requested Backlog				N/A	M-1
Western Region	H54-11	Santa Rosa Ranch School	Ground	H54-11-X01-M-004-1	M	1	Open	\$124,714	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Western Region	H54-11	Santa Rosa Ranch School	Ground	H54-11-X01-M-006-1	M	1	Open	\$39,867	REPLACE ASPHALT PAVING ON ROADS OR LARGE AREAS, 3" BINDER COURSE, 2" WEARING COURSE	AME Requested Backlog				N/A	M-1
Western Region	H52-21	Theodore Roosevelt School	Ground	H52-21-X01-F-001-2	F	2	Open	\$81,000	Remove and replace eleven fire hydrant on campus, they leak and some do not work. Should be replaced to protect the school grounds.	Need replacement fire hydrant per code.				N/A	F-2
Western Region	H52-21	Theodore Roosevelt School	Ground	H52-21-X01-M-007-1	M	1	Open	\$11,308	REPLACE ALUMINUM BLEACHERS	AME Requested Backlog				N/A	M-1
Western Region	H54-25	Tohono O'odham High School (Papago)	801	H54-25-801-M-006-1	M	1	Open	\$2,521	REPLACE 1" BLANKET TYPE DUCT INSULATION, LOCATED UP TO 1' ABOVE GRADE	AME Requested Backlog	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	M-1
Western Region	H54-25	Tohono O'odham High School (Papago)	801	H54-25-801-S-001-1	S	1	Open	\$197,719	REPLACE COMMERCIAL KITCHEN HOOD SYSTEM	Inspected by AME; CROPPER 23-APR-01	Occupied	BIA Education	Cafeteria/Dining Hall	Poor	S-1