


**Complementary Educational Facilities Needs
Summary of Responses
9/30/10**

Alamo Day School
Baca Community School
Betty Ojaye Navajo Preparatory School
Blackfeet Dorm
Bread Springs Day School
Chemawa Indian School -
ChiChilTah Community School
Chickasaw Children's Village.
Chilchinbeto Community School, Inc
Crownpoint Community School
Crystal Boarding School
Dibe Yazhi Habitiin Olta, Inc
Dzilth-Na-O-Dith-Hle Community Grant School
Eufaula Dormitory
Havasupai Elementary School:
Hotevilla/Bacavi Community School
Hunters Point Boarding School, Inc.
Jemez Day School
JJeheedez'a Academy, Inc.,
John F. Kennedy Day School
Jones Academy
Kayenta Community School.
Kickapoo Nation School
Laguna Elementary and Middle School
Lukachukai Community School
Mandaree School
Mariano Lake Community School
Moencopi Day School
Na'neelzhiin Ji'olta (Torreon) School
Northern Cheyenne Tribal School
Ohkay Owingeh Community School
OhkayOwingeh Community School
Pacific Northwest Schools
Pine Hill School
Pine Springs Day School
Pueblo Pintado Community School
Quileute Tribal School
Richfield Residential Hall
RocRocky Ridge Boarding School
Rosebud Dormitory
San Ildefonso Day School

Santa Clara Day School
 Sequoyah Schools
 Shiprock Associated Schools
 Shoshone-Bannock School
 St. Stephens Indian School
 T'siya Day School
 Taos Day School
 Te Tsu Geh Owengeh School
 Tohaai Community School
 Tohaali Community School
 Tohajiilee Community School
 Tonalea Day School
 Tse'ii'ahi (Standing Rock) Community School
 Tuba City Boarding School
 Two Eagle River School
 Yakama Tribal School

Overview



Alamo Day School

Hwy. 169, P.o. Box 907
Magdalena NM, 87825
(505) 854-2635

Category of Need

- Elective/Supplementary Classroom Space

Detailed Explanation

FACE building to replace the existing building that does not meet the FACE guidelines.

Baca Community School

PO Box 509
Prewitt, NM 87045
(505) 876-2769

Category of Need

- facilities space

Detailed Explanation

A bus barn to shelter school buses from the elements with electrical plugs to keep bus batteries charged in the winter months. A building to house a chlorination system is requested for this location.

Navajo Preparatory School

Navajo Preparatory School, Inc.
1220 West Apache Street
Farmington, NM 87401
(505)326-6571

Category of Need

- gymnasium or sports facilities,
- electives space/classroom

Detailed Explanation

In order to complete the Campus Master Plan for Navajo Preparatory School, Inc. additional funds are required for a Fine Arts/Music Building, Maintenance Building, Baseball Field and various site-work that include paving, lighting and fencing. The 83.24-acre school site is

located at 1220 West Apache Street, Farmington, San Juan County, New Mexico. The land is owned by the Navajo Nation. The Navajo Preparatory School was established by the Navajo Nation Council in 1991 as a college preparatory boarding school for Navajo and other Native American students in grades in grades 9-12. Navajo Preparatory School, Inc. sends 95%-100% of its graduates to colleges and universities each year. The School has met Adequate Yearly Progress (AYP) for nine (9) consecutive years since the No Child Left Behind Act was established in 2002.

Campus Master Plan: The Navajo Preparatory School Campus Master Plan is being accomplished in a three-phased construction project costing over \$40 million. The Phase I project was funded at \$7.5 million by the Navajo Nation and includes four new dormitories. Phase II was funded in the amount of \$13 million as a BIA Facility Improvement & Repair Project and includes renovation of three historic buildings and a new gym addition. The \$14 million Phase III project is also completed and occupied in December 2009. It includes a 25,000 sq. ft. Student Center, Football/track field and soft-ball field. The Phase III project is funded by the BIA under Replacement School Construction. Supplemental funds in the amount of \$2.8 million was acquired from the Navajo Nation, State of New Mexico and Abandon Mine Lands to support all three phases of the projects.

The following facilities are required to fulfill school needs in terms of academic curriculum, school safety and support services. Statement of Need to Complete the Campus Master Plan

- *Music/Fine Arts Building \$3.2 million Design 100% complete, Construction ready*
- *Maintenance/Transportation Bldg. \$600,000*
- *Athletic Fields (baseball, sitework) \$350,000*
- *Fencing \$ 85,000*
- *Electrical Work (site lighting) \$100,000*

Total: Need: \$4,335,000

Blackfeet Dorm

Browning, MT

Category of Need

- gymnasium or sports facilities,
- faculty housing
- electives space/classroom

Detailed Explanation

1. Windows throughout the Dormitory need repairs as some of them can't be opened or closed all the way as they are double pain window that are old and are out dated and hard to find replacements as they no longer use these types of windows.

2. *The Old Arts and Crafts Building has been listed as demolished but is still up and is not useable. It has been gutted out as required and special equipment was utilized because of the concerns with abatement issues and removal.*
3. *Repairs to the old apartment that were used for the staff housing need to be completed as there are several needs in each of those including carpeting, bathrooms, closets, Kitchen cabinets, and various other little items.*
4. *Some of the sidewalks are decaying and need repairs or replacement.*
5. *Parking over by the gymnasium need to be surfaced as drivers are destroying our grass around the gym by parking on it.*
6. *We hope to get a new playground and these parking area looks like the best location for that new equipment. If approved a new area for parking will need to be identified.*
7. *Some new doors are needed throughout the dormitory as several need replacement due to wear and tear. Security doors for the exits with alarm system attached would be ideal. As we have no way of knowing who maybe coming in doors that we don't have sight of during the day. We do have a camera system, but we have to be viewing it to know or see someone coming into the building.*
8. *Lighting around the building needs to be improved as there are areas that need additional lighting as they are dark and we do have blind spots in our camera system that we had hope we could solve with upgrading our system. However, do to the Safe and Secure Schools funding not being available we don't have the available funding to complete this project at this time.*
9. *Repairs in the craft room under the gym where the rock polishing equipment sat need to be completed as it is in very poor condition. We are unable to use this area at the present time because of the damages needing to be repaired.*

Bread Springs Day School

PO BOX 1117
Gallup, New Mexico

Category of Need

- facilities space

Detailed Explanation

A transportation and maintenance office is needed at the newly built facility as none was constructed at the new location.

Chemawa Indian School -

3700 Chemawa Road
Salem, Oregon 97305
(503) 399-5721

Category of Need

- classroom space

Detailed Explanation

Chemawa Indian School is located in Salem Oregon and is the oldest continually run Off Reservation Boarding School (ORBS) in the United States. Chemawa will be celebrating its 131st birthday. The boarding school has a student population from 23 different states that come from over 70 federally recognized tribes.

Chemawa Indian School was last built back in the 1970's. The design of the building was modeled after a southwest building in Arizona. The flat roof is not something that works in the Pacific Northwest as the amount of rain creates leaks and rain is a constant in the Northwest. The material used was to rust over time, again with the amount of rainfall the building started rusting with in the first year of construction and has deteriorated beyond its expected lifetime in an expeditious fashion.

Another design flaw was the academic building was built with no walls separating the classrooms, only partitions separated classrooms. Since then walls replaced the partitions and in doing so created some safety issues. The venting and duct work is not placed where needed after the walls were constructed. You might have a really hot room where another room is getting no heat at all etc... Fire safety is another major concern as there is not an egress system and only a false ceiling in place that would not stop or slow down the spread of a fire.

ChiChilTah Community School

PO BOX 278
Vanderwagen, New Mexico

Category of Need

- dormitory
- electives space/classroom

Detailed Explanation

A new dormitory is being requested to replace the existing dormitory that was built in the 1960s. The school building is in need of a FI&R project to renovation the existing school building. It is recommended that the FACE adult education building to be replaced at it is out dated and run down. The program space is currently congested and if the space guidelines allow a larger facility is needed. The FACE children classroom is also in need of replacement as it is run down and not up to current building code standards.

Chickasaw Children's Village.

Kingston, OK

Category of Need

- gymnasium or sports facilities

- electives space/classroom
- computer
- tutoring room
- student union

Detailed Explanation

The Chickasaw Children's Village is located in southern part of Oklahoma. We provide services seven days a week to approximately 64 students in grades 1st thru 12th. There are approximately fourteen different tribes represented at our school. Our campus is very unique in that our students are housed in quarters, which we call cottages. There are eight students per cottage. The biggest need for a complementary educational facility would be a wellness /multi-purpose center.

The multi-purpose facility would include the following:

- 1) Computer*
- 2) Student union for recreational activities (space for 50-70 students).*
- 3) Wellness /exercise room.*
- 4) Tutoring room*

Currently our students use the computer room for their tutoring room. This is due to lack of space. Computer time is cut down to keep from distracting students in tutoring. At present the students are in need of a place to assemble and to socialize. We also see the need for an exercise/health teaching room.

We see the need for educating our students on the wellness of their body and their minds.

Chilchinbeto Community School, Inc

Kayenta, AZ

Category of Need

- faculty housing,
- electives space/classroom
- facilities space
- administrative space
- recreational/multipurpose

Detailed Explanation

I would like to respectfully add four new houses - 2 three bedroom, 1 two bedroom, and 1 efficiency to our wishlist. Here our need for additional buildings:

- 1. A beautiful new FACE building to complement the area. We have three component programs of FACE, Preschool (early childhood) 15 or more students plus 15 or more parents.*
- 2. Homebase program: 40 or more students, and 40 parents.*

3. *Adult education: 15 or more parents enrolled.*
4. *Governing Board and Parent Center. We really need a large board building and parent center building for meetings, activities, and conferences.*
5. *Storage building. We don't have any storage space.*
6. *Office building. We really need additional office space. The offices we have are very small.*

Crownpoint Community School

Crown Point High School
1500 South Main Street
Crown Point, IN 46307

Category of Need

- facilities space
- electives space/classroom
- special education classroom space

Detailed Explanation

A new facility was constructed at a new location and without buildings for the transportation and facility maintenance programs. The school also needs a bus barn with electrical plugs in at the new school site. There is also a special education ancillary staff comprised of about 14 staff members needing a building to house their program. The building would need to be equipped with a sound room to test student hearing. In all 3 new buildings and 1 bus barn are being requested for this site.

Crystal Boarding School

Crystal Boarding School
P.O. Box 1288
Navajo, New Mexico 87328

Category of Need

- classroom space
- cafeteria
- dormitory
- electives space/classroom

Detailed Explanation

Crystal Boarding School facilities were built in the early 1930s. It is a K-6 school with an average enrollment of 140 per school year. The buildings are considered historical buildings. The 1st, 2nd, 5th, 6th, Kindergarten, and Special Education are housed in portable buildings. There are two residential halls, however, only one is in use and the other building has many

deficiencies. The multipurpose building where meals are cooked and served has a perpetual leaking roof although it has been repaired many times Therefore, Crystal Boarding School is in DIRE need of new school facilities. School construction design had been submitted several years ago, however, funding was diverted elsewhere.

Dibe Yazhi Habitiin Olta, Inc

Dibe Yazhi Habitiin Olta, Inc
Borrego Pass School
P.O. Box 679
Crownpoint, New Mexico 87313

Category of Need

- classroom space
- cafeteria
- gymnasium or sports facilities
- general maintenance to existing facilities

Detailed Explanation

Main School Building unmet needs as of today's date.

**New doors and locks for all exterior and interior doors.*

**New windows and screens for all rooms in the main school building.*

**Solar energy panels replaced and new ones installed for better energy use and consumption.*

** Wind Driven energy units for our whole school to help defray the high costs of electricity at our school.*

**Refurbish and replace all built in cabinets and cubbies and fixtures in the whole school.*

**All bathrooms upgraded with new handicap accessible fixtures for age appropriate sizes.*

**New carpet in all classes due to old carpet and tile in each classrooms.*

**Cafeteria - replace old and outdated equipment and appliances.*

**Cafeteria - replace all tables with new modern more sturdy units.*

**Gym - replace the bleachers and equipment that came with the gym when it was built.*

**Gym - redo and refurbish the locker rooms and showers since they are outdated and unusable due to sediment in the lines and pipes.*

**Gym - redo the floor and replace worn wood and tiles.*

**Gym - New Lighting and fixtures for all the lights in the gym.*

Modular units - we have one used one and it is in need upgrades with carpet and electrical and floor tiles.

Dzilth-Na-O-Dith-Hle Community Grant School

5 Road 7585, Box 5003
Bloomfield, New Mexico 87413
(505) 960-0356 or (505) 960-3066

Category of Need

- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

Our school is a K-8 school with a residential program. It would be a great benefit to our students if we had facilities for a music room, swimming pool, art room, science lab., indoor recreation room due to harsh winters, and cultural center.

EUFAULA DORMITORY

716 Swadley Drive
Eufaula, Oklahoma 74432
(918) 689-2522

Category of Need

- classroom space
- electives space/classroom
- multipurpose/recreation space

Detailed Explanation

1. Additional classrooms (2) for academic/tutoring programs. Sufficient space for 20 students per classroom.

2. Multi-purpose facility (i.e. Student Union, Rec Hall) for residential program residents. These programs are required to offer recreation/ leisure time activities, group counseling, etc. for residents of these programs per CFR 25 and BIE homeliving requirements. Sufficient space for approximately 60-80 students at any given time.

Havasupai Elementary School:

Lake Havasu City, Arizona

Category of Need

- classroom space
- office/admin space
- gymnasium or sports facilities
- electives space/classroom
- library
- technology

Detailed Explanation

1. School using two portables for classrooms
2. Currently the school has a small space for physical education; 30feet by 30 feet
3. Great need for updated wiring for Internet/technology
4. No classroom for computer lab
5. No classroom for OT; PT; Counseling services;
6. No Nurses' office
7. Using portable as library
8. Portables are deteriorating and are in need of renovation
9. School building does need renovation in the classrooms

Hotevilla/Bacavi Community School

P.O. Box 48
Hotelvilla, AZ 86030

Category of Need

- classroom space
- electives space/classroom

Detailed Explanation

1. School building was built in 1959
2. 6 classrooms are in portable buildings- Buildings are deteriorating and are in violation of building codes
3. Computer Lab portable is in violation of EPA codes and building codes
4. School building is in need up major renovation of ceiling, walls, kitchen facilities; and classrooms
5. No classroom for music, art, etc.

Hunters Point Boarding School, Inc.

P.O. Box 99
St. Michaels, AZ 86511
(928) 871-4439

Category of Need

- classroom space
- library
- computer lab

Detailed Explanation

Hunters Point Boarding School, Inc. is in need of new buildings. We are a K-5 school that would like to expand in grades; however, are not able to due to lack of space for classrooms. We also need a llibrary and a computer lab.

Jemez Day School

Jemez Pueblo, NM

Category of Need

Detailed Explanation

None

Jeehdeez'a Academy, Inc.,

Pinon, Arizona 86510

Category of Need

- facilities space
- computer lab

Detailed Explanation

Our wish list is as follow:

1. Technology: Our new school is equipped with high tech computerized equipment that operates our HVAC systems, Fire Alarms Systems and Security of Buildings. Our position descriptions for our present maintenance workers do not include computer operations. It becomes necessary to hire open- market service contractors using skilled technicians just to keep our educational buildings in operation on a daily basis. These private vendors are draining our small O&M Budget,

Suggestion: Hire Skilled Craftsmen at Agency Level who will service our equipment on a scheduled basis at all BIA funded schools. These Craftsmen will not charge us like private companies.

2. *Warehouses and Maintenance Shop. As stated above regarding our location. We now have to do isolation travel quite a distance to get our supplies, material and repair parts. The new School Constructions omitted these necessary buildings. Cost factor is high for isolation travel but it is necessary to operate and maintain our school programs. OSHA Laws require that all Government funded schools provide a safe work place for employees as well as a safe place to do repairs.*

John F. Kennedy Day School

P.O. Box 130
Whiteriver, AZ. 85941
Phone: (928) 338-4593

Category of Need

- classroom space
- gymnasium or sports facilities

Detailed Explanation

John F. Kennedy Day School is located near Whiteriver, Arizona. The school is almost 50 years old, it was built around 1963. It is located near a wash and sometimes we have flooding. The building is in need of constant repairs or expansion. We have a gymnasium that is too small for our k-8 students. Third - eighth grade are housed in modulars.

We just repaired our kitchen plumbing, along with the restrooms. Currently, we need new air conditioners as our old ones are worn out and needs replacements. Tiles on floors are constantly in need of replacements, the pipes for water, plumbing, electricity, etc. are also always being repaired. Originally, the building, consisted of 1 gym, plus 3 classrooms, and a separate kindergarten classroom. Today we have 10 modular buildings on our campus.

Jones Academy

HCR 74, Box 102-5
Hartshorne, OK 74547
(918)297-2518

Category of Need

- electives space/classroom
- recreational space (indoors)

Detailed Explanation

Jones Academy is a peripheral dormitory located in southeastern Oklahoma. We provide services seven days a week to approximately 185 students in grades 1st thru 12th. We represent approximately thirty tribes from fifteen states. At our location the biggest need for

a complementary educational facility would be multi-purpose facility.

Currently, we have to hold our girls' 7th-12th grade study hall in our cafeteria and the boys' 7th-12th study hall is held in the activity room. We do not believe that these areas lend to a conducive educational experience. We also need a place where the students (boys and girls) can congregate for special assemblies or meetings in relaxed atmosphere.

The multi-purpose facility would include the following:

- 1) Four classrooms for tutoring purposes (space for 20 students per classroom).*
- 2) One large meeting area (space for approximately 80-100 students).*
- 3) Student union for recreational activities (space needed for 100-120 students).*

Kayenta Community School.

P.O. Box 188
Kayenta, Arizona 86033
928) 697-3439

Category of Need

- facilities space
- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

The following buildings are needed but were not funded in our new school construction:

- 1. Classroom for the FACE program*
- 2. Facilities maintenance office*
- 3. Warehouse*
- 4. Firehouse to house our fire truck*
- 5. Track & soccer field*
- 6. School bus garage*

Kickapoo Nation School

Powhattan, Kansas 66527

Category of Need

- gymnasium or sports facilities

Detailed Explanation

We are a small tribal school still adequate education facilities remain a problem. For example, the rooms adjacent to the gym remain partially flooded year round. The school probably built in the 50's is slowly depreciating. The elementary was built in the 70's is outdated and has a leaky roof. We have no sporting complex so to speak just an old football

field that is dire need of attention. We at the Kickapoo Nation School have little amenities or adequate facilities that students can benefit from. In addition, there are several other facilitative items that will lead to an expensive renovation. For example, our boiler is over 30 years old and several other items our in desrepair. I hope this sheds some light on the condition of our facility.

Laguna Elementary and Middle School

10475 E. Lakeview Drive Scottsdale, AZ 85258 480-484-2400

Category of Need

Detailed Explanation

Listed FMIS Catalog of Conditions for Laguna Elementary and Middle School -- in hard copy.

Lukachukai Community School

Navajo Route 13
Lukachukai, AZ 86507
(928) 787-4400

Category of Need

- office/admin space
- facilities space
- electives space/classroom

Detailed Explanation

These are facilities at Lukachukai Community School that do not exist.

- *Bus Garage*
- *Storage Facility*
- *Facility Office*
- *Restroom in the Cafeteria for students*
- *Extra Classroom Space, FACE and BABY FACE Program*
- *Office Spaces*
- *Receiving, Delivery Facility*
- *Transportation Office*

Mandaree School

1 Warrior Circle
PO Box 488

Mandaree, ND 58757
701-759-3311

Category of Need

- classroom space
- faculty housing
- electives space/classroom

Detailed Explanation

Excerpt: Longer documentation with photos in hard copy

Deteriorating facility – We know that the classroom environment impacts student achievement. The original structure was built in 1954 and has many issues. It is challenging to make the environment look and feel welcoming for students. We are struggling with repair and renovation costs and looking for resources. Electrical needs for today’s electronic world are not sufficient. Safety switches are blown on a regular basis. Plumbing issues with old metal pipes keeps us mopping up leaks. Roofing issues gives a definite meaning to, “When it rains it pours.” Classrooms are hot in the summer and cold in the brutal North Dakota winter. Some classrooms rely on space heaters to get the temperature near comfort level. Exterior doors do not close securely. This leaves students and staff unprotected from intruders. Replacement exterior doors are estimated at \$20,000 each and there are 10-14 that need replacing. We have applied for an Energy Efficiency Community Block Grant Application for \$275,000 to repair some heating system deficiencies. This does not even begin to address the many structural issues.

Deteriorating and insufficient housing – Not enough housing existing and existing housi

Mariano Lake Community School

PO BOX 787 in Crownpoint, New Mexico

Category of Need

- classroom space

Detailed Explanation

The school is requesting for 2 new portable building classrooms to house the growing enrollment. For long term an addition to the existing school building to put all the classrooms now in the outlying portable buildings is recommended.

Moencopi Day School

South Highway 264, PO Box 185
Tuba City, AZ

Category of Need

- classroom space, cafeteria
- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

1. 8 classrooms in portable buildings
2. School building is in need for renovation
3. Portable buildings are OK but will eventually be in need of repair
4. Bigger Space for Gym/cafeteria
5. Build school with all classrooms in the building
6. No classroom for music, art, etc.

Na'neelzhiin Ji'olta (Torreon) School

Cuba, New Mexico

Category of Need

- classroom space

Detailed Explanation

An addition to the main school building to house all the programs under one roof is recommended. In the short term there is one portable classroom building that houses 4 classrooms that needs to be replaced as it is old and run down. The portable is requiring a lot of maintenance and repairs.

Northern Cheyenne Tribal School

One Campus Drive P
 Busby MT, 59016
 (406) 592-3646

Category of Need

- cafeteria
- upgrades to existing facilities
- admin/offices space
- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

Main school building #204:

- Building #204 was built in 1968
- 39,902 Square footage
- 19 classrooms, High school and elementary
- Cafeteria is located in building #204
- Front office (principal, NASIS, counselor, registrar)
- Needs: All doors replaced, exterior/interior

All door knobs w/security locks replaced, exterior/interior
All windows needs to be replaced
Fire/smoke alarm system needs to be replaced/updated
New plumbing for the building
Handicap bathrooms need replaced or upgraded
Electrical system needs to be upgraded
All lights and switches replaced
Technology upgrade for each classrooms, smartboards needed.
New flooring is needed throughout the building, halls/classrooms.
Irrigation water wells needed for grounds
All new School building is needed

Gymnasium/Classrooms building #302:

- *Building #302 was built in 2004*
 - *28,300 Square footage*
 - *Gymnasium with three (3) classrooms*
 - *Junior High School, 7Th and 8th grades.*
 - *White Buffalo Center, Alternative Education/Adult Education*
- Needs: Divider curtain needs to be replaced*
Irrigation system needs to be replaced
Water pressure tank needs to be replaced
Flood lights needs to be replaced
Alarm control panels throughout the building needs to be replaced
Technology upgrades needed

Ohkay Owingeh Community School

PO BOX 1077
San Juan Pueblo, NM

Category of Need

- classroom space
- gymnasium or sports facilities
- electives space/classroom
- library

Detailed Explanation

New facilities are needed for:

- *Ohkay Owingeh Community School (needs a new school)*
- *Multi-purpose gym/indoor wellness centers (for winter months) and classrooms with computer labs*
- *School libraries/computer labs are needed (needs library - priority!)*

OhkayOwingeh Community School

Ohkay Owingeh, New Mexico.

Category of Need

- classroom space
- gymnasium or sports facilities,
- library

Detailed Explanation

The bureau has promised this school a new facility for over 12 years and nothing has been done. All of the classrooms are portables, one of the portables is breaking in half, the other is sinking. The electrical wiring is faulty. The facility division at one time destroyed a building and promised to replace it. To date, that has not been done. We have no library and no gymnasium.

We are in dire need of fencing, and pavement. Once again, please help before this becomes a serious is

Ohkay Owingeh Community School is a grant school located in Ohkay Owingeh, New Mexico. Part of the original school was burned down over 15 years ago. The bureau promised the school would get actual buildings to replace these portables. The Bureau replaced the buildings with portables and stuccoed them to make them look like actual buildings. As of today, one of them is literally breaking in half, the other one is sinking, and the last has faulty electrical wiring, all of them a serious safety issue. The students, in my opinion are unhoused. I have reported this several times and to date have received no response.

The bureau demolished an adobe building that was falling down approximately three years ago and to date nothing has been done to restore that building.

The school has increased in enrollment, yet we have no library, no gymnasium and our children are coming to school in deplorable conditions. The entire school is not accessible as is required by ADA. I recently had an individual come to the school in a wheelchair and she needed to use the restroom. We could not get her into the restroom because the doorway was too narrow.

Pacific Northwest Schools

Category of Need

Detailed Explanation

The seven other Bureau funded schools in the Pacific Northwest are relatively new and in excellent shape. Our latest is a 47 million dollar school at Muckleshoot Tribal School that would be considered world class. It is clear that when the students are in a setting to where they are proud of the overall effort to improve is quite evident. PRIDE...

Pine Hill School

P.O. Box 220
Pine Hill, NM 87357

Category of Need

- cafeteria

Detailed Explanation

Pine Hill school had a residential building built about 3 years ago and we lacked a dining hall with kitchen facilities for the residential students. Would this qualify as complementary education facilities?

Pine Springs Day School

Phone: (928) 871-4311

Category of Need

- faculty housing

Detailed Explanation

Pine Springs Day School has an education facility that was built and moved into 1999; however, we have inadequate staff housing to attract highly qualified motivated teachers for our students.

Pueblo Pintado Community School

Cuba, NM 87103.

Category of Need

- facilities space

Detailed Explanation

A new facility was constructed at a new location and without buildings for the transportation, facility maintenance programs. The school also needs a bus barn with electrical plugs in at the new school site. In all new buildings are being requested for this site.

Quileute Tribal School

La Push, Washington

Category of Need

- relocate school for safety reasons

Detailed Explanation

Quileute Tribal School is located in LaPush Washington on the Quileute Indian Reservation. On a good day with a strong arm you can throw a rock into the ocean from the front door of the Quileute Tribal School. On another note you can see the whales pass by depending on the migration and the time of the year. Although this is appealing to the eye it creates safety issues as the school is in harm's way of tsunami's that take place from time to time with the amount of earthquakes that generate unusual wave patterns. It would be in the best interest if the school could be relocated to higher grounds by the newly constructed high school/gymnasium. By doing so this would ensure that the K-8 classrooms and the students would be on safe grounds.

Richfield Residential Hall

(435) 896-5101 office

Category of Need

- gymnasium or sports facilities
- dormitory
- recreational space (indoors)

Detailed Explanation

Richfield Residential Hall is in need of a new dormitory and a gymnasium/multi-purpose facility. Richfield Residential Hall consistently leads BIE residential programs in student performance, achievement and growth and is recognized as one of the top residential programs in the country.

Despite being recognized as one of the leading programs in the country in almost every aspect of educational and social growth, Richfield Residential Hall does not meet federal space and privacy requirements outlined in the CFR. Richfield Residential Hall is housed in the original facility that was constructed between the years of 1954 and 1956. While it is exceptionally maintained, student and program needs have changed drastically since the construction of our current facility some five and a half decades ago. No longer do we only feed an house students as was the case when our dormitory was constructed almost sixty years ago. We now offer a wide range of programs and services for our students.

Research indicates that there is a clear correlation between functional facilities and academic performance. Student behavior and academic performance has been cited as being significantly better when students have comfortable and functional facilities in which to sleep and study.

The students, staff, administration and governing board of Richfield Residential Hall respectfully request your consideration of our need for a new facility.

Also indicated in the opening paragraph is the need for a gymnasium/multi-purpose facility. At this point, we do not have a location to meet with the entire student body at one time. Also of concern is the fact that our only exercise area is an outdoor basketball court. As you are aware, the CFR mandates a minimum of 1 hour of structured physical activity a day with students. Our location is very cold, and often snow covered for 4-5 months out of the school year. An indoor gymnasium would allow us to provide year-round physical education and activity programs for our students as well as a safe way for us to meet with the entire student body at one time. Ideally, this facility would be incorporated into the new dormitory design.

Rocky Ridge Boarding School

P.O. Box 299
Kykotsmovi, AZ 86039
(928) 725-3650

Category of Need

- office/admin space
- facilities space
- gymnasium or sports facilities
- electives space/classroom
- facilities work

Detailed Explanation

Rocky Ridge Boarding School is an old facility (approx. 50 years old) and we are dire need of many items. The following is a list of things I believe the school could use but do not currently have.

- 1. Art Room*
- 2. Music/Band/Orchestra Room*
- 3. Computer Room*
- 4. Industrial Arts Room*
- 5. Fueling Station for Buses on Campus*
- 6. Central Air Conditioning*
- 7. Playground Equipment*
- 8. A Playground that is not just a dirt field*
- 9. A Baseball Field. Not just a backstop fence*
- 10. Storage Area Facility for Equipment*

11. *Science Room*
12. *Weaving Room*
13. *Home Economics Room*
14. *Nurse's Office*
15. *School Nurse*
16. *Early Childhood Room*
17. *Room for Service Providers (PT, OT, PSY. Speech)*
18. *Room for Community Members*
19. *Physical Education Office*
20. *Chain Link Perimeter Fence (not a horse fence)*
21. *Security Cameras (inside and outside)*
22. *Electronic Entrance Gate*
23. *Road Improvements inside the school property*
24. *New Sidewalks*
25. *Tinted Classroom Windows to reduce the heat and glare.*
26. *Public Announcement System*
27. *New Efficient Boiler System*
28. *Playground Tarps to provide Shaded areas for students.*
29. *Back Hoe or Bob Cat*
30. *New Blinds or Curtains for the Classrooms*
31. *New Desks and Locking File Cabinets for all Teachers*
32. *Locker Room for Sports*
33. *New Restroom Facilities for Students*
34. *New Restroom Facilities for Staff*
35. *Wind Breaking Walls to reduce dust and dirt that accumulates in classrooms and buildings.*
36. *More Trees and or Shrubs*
37. *Track & Field Facility*
38. *Volleyball Court (outside)*
39. *A New Educational Facility*

Rosebud Dormitory

P.O. Box 69, Bldg 1001
Mission, SD 57555

Category of Need

- cafeteria
- gymnasium or sports facilities,
- dormitory

Detailed Explanation

Our facility needs range from; need for additional space, to new facilities.

Specific Needs for Existing Building:

BIA Bldg 1003- Kitchen

New facility which meets all codes

Handicap ramp/sinks/restrooms/food service lines/accessible parking area

New fire alarm system that meet all codes

Air conditioning

BIA Bldg. 1001-Dormitory

New Facility which meets all codes

Handicap restrooms/Handicap sleeping rooms/Handicap accessibility to basement

Elementary accessibility restrooms

New fire alarm system that meets all codes

Gym

San Ildefonso Day School

Santa Fe, NM

Category of Need

- classroom space
- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

New facilities are needed

- *Multi-purpose gym/indoor wellness centers (for winter months) and classrooms with computer labs*
- *School libraries/computer labs are needed*

Santa Clara Day School

Santa Clara Pueblo, NM

Category of Need

- classroom space

Detailed Explanation

Santa Clara Day School K-6 (needs space, currently using tribal space)

Sequoyah Schools

Pasadena, California.

Category of Need

- cafeteria, facilities space, electives space/classroom, transportation facility

Detailed Explanation

1. *New Classroom/Education/Arts Building to centralize education programs from remote buildings.*

2. *Cafeteria Expansion/Commons Area for Students combined for a recreation/fitness purpose and/or health/wellness purpose and/or day student gathering area.*

3. *New Maintenance Facility & New Campus Storage/Warehouse Building: The facility could desperately use new, purpose built, Facility Maintenance building to replace the existing. The existing facility has some structural issues, needs fire alarm & fire suppression, not to mention asbestos and being generally a building that they're fitting that purpose into. A new facility would have offices, dedicated mowing & other equipment repair, dedicated welding, carpentry & painting areas with the appropriate safety & fire suppression as well as the necessary storage for cleaners, paints, solvents, and other chemicals and items that current environmental regulations require.*

4. *New Transportation Facility: This building would serve as a maintenance/cleaning/fueling facility for your buses and SHS vehicles that has the appropriate environmental measures put in place for vehicles to be cleaned & serviced on site, rather than in the football parking lot. One of the complaints in the most recent environmental audit was that water from washing was being allowed to run off into storm drains, and thereby the creeks, which is not allowable under current regulations.*

5. *New Football Stadium: The current stadium leaks badly into the dressing facility below & dressing/restroom/concession facilities for both home and visitors are inadequate, have numerous safety violations, and do not meet basic codes. The stadium also has two press boxes that were erected w/o any type of engineering or architectural design and also do not meet safety/egress codes. Further, in order to repair the leaks, the entire stadium would have to be sandblasted/shot blasted to remove the existing paint, patch every joint between every seating riser/seating tread, then coat the entire seating structure with an industrial coating paint to seal the leaks and prevent water from seeping through the concrete. This coating would also have to be replaced every couple of years at a substantial cost. A new stadium would have expanded home and away seating for fans, adequate concession and restroom facilities for both home and visitor sides, as well as adequate dressing/changing areas for players at the stadium.*

6. *New Softball Fieldhouse with restrooms, changing, concessions to comply with Title IX.*

7. *New Water Tower/Water System w/individual building service & meters.*

8. *Improvements to Campus Entries for traffic safety/campus security.*

9. *General Campus "Mainstreet" improvements.*

Shiprock Associated Schools

Category of Need

- dormitory

- School bus transportations

Detailed Explanation

see longer report in hard copy

Shoshone-Bannock School

P.O. Box 790
Fort Hall, ID 83203

Category of Need

- dormitory

Detailed Explanation

A dorm. We have not conducted a surveys, there has been no formal meetings, there has been no land surveys or cost analysis.

St. Stephens Indian School

128 Mission Road, Po Box 345
St Stephens, WY, 82524-0345
(307)856-4147

Category of Need

- classroom space
- gymnasium or sports facilities
- electives/additional classroom space
- cafeteria

Detailed Explanation

We have a waiting list for kindergarten every year of students that we can't accept because of limited space. We only have space for one kindergarten classroom. To assure school readiness we would like to have a pre-school project. Not all of our students can attend Headstart to help them prepare for kindergarten. Space and age appropriate facilities are necessary for a pre-school program.

At the Middle School we need to expand because our population in grades 6-8 is increasing every year. Currently our Middle School is housed in our Elementary building. A separate building would be much better and would free up space to accommodate more programs and activities in the Elementary. We also need to offer more elective classes to the middle school students such as consumer/family science, industrial arts, drafting and other technology related subjects. These classes could be housed in a Middle School facility. A Middle School that had a gymnasium/auditorium could provide our entire school system K-12 with options for programs and activities. A cafeteria in the Middle School building that could address the

entire school would certainly benefit our needs. Currently both our elementary and high school cafeterias are operating at maximum capacity.

Our school looks to supplement our programs with grants which in some cases we can't go after because of space constraints. The majority of these need space to house at least the personnel associated with them. The addition of a Middle School could help us alleviate that problem. We have our track and football field (that serves our whole school system) being built at this time. We will have a cement slab to serve as a platform but we do not have an announcer's stand a concession booth and restroom facilities.

At our new High School the one area that we have identified as being a concern is the lack of an outdoor recreational area for students during lunch break. An area with basketball courts, tables and benches would be fine.

T'siya Day School

Zia Pueblo, New Mexico
(505) 867-3553

Category of Need

- maintenance to existing spaces

Detailed Explanation

Our school has a serious roof problem that will take an entire roof replacement to fix. Facilities is aware of it and has requested the money to fix/replace it. The other part of the problem is that until it is fixed, every time we have a rain or snowstorm, water comes into the building. It sometimes works its way into heating and cooling systems and causes the motors to burn out. I imagine its only a matter of time until it starts affecting other wiring.

Because of a reported failure of the tribe to provide consistent quality inspections, our foundation is cracking and you can feel the cracks in the floors of several classrooms. In the tiled hallways, you can see where the tiles are separating from one another.

The builders also failed to put any speakers or public address system outside the building. This could be disastrous in an emergency situation where we need to get children inside quickly.

Our internet system is down a lot, and just slow even more often.

Taos Day School

Taos, New Mexico

Category of Need

- classroom space
- gymnasium or sports facilities
- electives space/classroom

Detailed Explanation

- *needs a new school*
- *Multi-purpose gym/indoor wellness centers (for winter months) and classrooms with computer labs*
- *School libraries/computer labs are needed for:*

Te Tsu Geh Owengeh School

Category of Need

- classroom space
- gymnasium or sports facilities

Detailed Explanation

Te Tsu Geh Owengeh School K-6 (needs new school, currently has inadequate space for playground) Multi-purpose gym/indoor wellness centers (for winter months) and classrooms with computer labs

Tohaai Community School

PO BOX 9857
Newcomb, New Mexico

Category of Need

- classroom space
- cafeteria
- office/admin space
- facilities space
- gymnasium or sports facilities

Detailed Explanation

The entire campus comprised of dormitories, kitchen, academic/gymnasium, maintenance, transportation and fire station are all in need of replacement. It is recommended that the entire facility be replaced at this location.

Tohaali Community School

Po Box 9657
Newcomb, NM 87455

Category of Need

- new school

Detailed Explanation

see longer attached document

Tohajiilee Community School

Canoncito, NM

Category of Need

- classroom space
- facilities space

Detailed Explanation

The school is need of an additional classroom wing to get all the outlying portable classrooms under one roof with the main academic facility. A new water treatment facility is needed for this location to house a chlorination unit.

Tonalea Day School

P.O. Box 39

Tonalea, AZ 86044

(928) 283-6325

Category of Need

- classroom space
- cafeteria
- facilities space
- gymnasium or sports facilities
- dormitory
- faculty housing
- electives space/classroom
- computer lab

Detailed Explanation

1. Classroom building that meets all structural, environmental, and technological expectations to carry the students into the 21st century.

2. Science building reflective of modern scientific inquiry.

3. Play ground area and equipment that is safe and stimulating.

4. Paved highways enabling access to the remote locations many of our reservation families live.

5. Adequate highway maintenance to keep main and secondary roads open through inclement weather.

6. Dormitories that have infrastructure to enable comfort and access to technology.

7. *Utility infrastructure that delivers consistent, reliable and available service.*
8. *Site specific and community access to 21st century communication systems.*
9. *Humane animal control capable of effectively keeping packs of stray dogs and cats off school campuses.*
10. *Sport stadiums, athletic fields and tracks,*
11. *Cafeterias and food service prep and storage facilities that is modern and environmentally safe.*
12. *Utilization of green technology in buildings and systems.*
13. *Maintenance facilities capable of supporting campus.*
14. *Modern apartment buildings for residential housing with recreation amenities that entice high quality educators to live and work at remote schools.*
15. *Theater, studios and auditorium with modern systems and infrastructure capable of supporting guest presenters and related school programs.*
16. *Swimming pool.*
17. *Modern security systems and campus lighting.*
18. *Paved parking.*
19. *Vehicle garage with capability to perform planned maintenance and minor body, mechanical and tire repair.*
20. *Fueling stations.*
21. *Administrative buildings supporting state of the art technology and communications.*
22. *Environmentally clean environments.*
23. *Environmentally clean communities.*
24. *Modern Libraries.*
25. *Native cultural facilities or cultural areas preserving the heritage and connecting to the future.*
26. *Hope.*

Tse'ii'ahi (Standing Rock) Community School

Crownpoint, New Mexico

Category of Need

- classroom space, facilities space

Detailed Explanation

The school is requesting for a new facility to replace the existing facility which is comprised of 13 portable buildings and 2 historic stone buildings. A building to house a chlorination system is requested for this location.

Tuba City Boarding School

Category of Need

- gymnasium or sports facilities, dormitory, recreational space (indoors)

Detailed Explanation

Our need is to provide energy efficient heating and cooling residential facilities, with student study halls, home economic learning facilities, computer/internet facilities, recreational facilities, canteen areas, office areas, nurse's station, isolation rooms, and councilor's facilities, private shower/bathrooms, dressing facilities, washer/dryer facilities and other away from home living facilities for remote living students.

Conditions of these two structures have been backlogged for deficiencies and non code compliance due to the age of these facilities, replacement would be cost effective in operations/maintenance and educational program needs to meet the Act of No Child Left Behind of 2001, in providing a safe and secure campus living for our 1250 students.

Two Eagle River School

Po Box 160
Pablo, MT, 59855

Category of Need

- classroom space
- office/admin space

Detailed Explanation

D13C02-Two Eagle River School: A storage unit and shop for student to learn wood working and other hand on projects: Size-50X100 building with a 12'X12' overhead door and walk in door. Part of this building would be use to store items we cannot destroy (student/personnel records), and things that are on a seasonal basis.

Yakama Tribal School

Toppenish, Washington

Category of Need

- classroom space
- cafeteria

Detailed Explanation

Yakama Tribal School is located on the Yakama Reservation in Toppenish Washington. Yakama just received ARRA funds to help in renovating a dilapidated building. The replacement of windows, gym floor, kitchen equipment, tanks, etc... is a good start but so much more is needed to help the staff meet the student's needs. There is no designated area to eat lunch in the current building as the students are required to eat lunch in the entrance area with portable tables. Office and classroom space is another concern as the student population is growing. A visit to the school would show the need

for replacement.