

Yakama Tribal School

Backlogs for FMIS Priority Ranking - 2008 Five Year Plan

27 Total Backlogs
\$1,105,898 Total - Backlog Estimated Cost

Location Name	Location/ Structure	Building Estimated Replacement Cost	Backlog Number	Category	Rank	Backlog Estimated Cost	Planned Corrective Action
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-E-002-2	E - Energy	2	\$102,274	Replace classroom and office light fixtures with high efficiency units
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-E-003-2	E - Energy	2	\$34,649	Replace light fixtures with high efficiency units
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-E-004-2	E - Energy	2	\$6,781	Replace incandescent fixtures with high efficiency fluorescent fixtures
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-H-003-1	H - Handicapped	1	\$63,280	Install new bleachers seating for 250 persons with ADA compliance
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-025-1	M - Physical Plant	1	\$246,534	Redesign and remodel kitchen utilizing existing space of rooms 40, 41, 42, 43, 44, 45, & 46
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-026-1	M - Physical Plant	1	\$71,826	Upgrade electrical distribution system, add circuits and outlets
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-027-2	M - Physical Plant	2	\$29,776	Refinish and restripe gymnasium floor
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-028-1	M - Physical Plant	1	\$31,640	Replace fire detection / alarm system with state-of-the-art system
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-029-1	M - Physical Plant	1	\$31,640	Install state-of-the-art fire sprinkler system
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-030-1	M - Physical Plant	1	\$94,242	Install a state-of-the-art intercom system and master clock system
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-M-031-1	M - Physical Plant	1	\$29,338	Replace ceramic tile floor and wall coverings in both restrooms
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-S-003-2	S - Safety	2	\$10,071	Install insulation on boiler tank, fittings and piping
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-S-007-1	S - Safety	1	\$20,227	Install wheelchair lift
Yakama Tribal School	Loc-School, Day	\$4,335,188	P11-20-1T-S-008-1	S - Safety	1	\$74,300	Replace window with fire exit door in each classroom (9) and office (6)
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-E-001-2	E - Energy	2	\$7,972	Replace HVAC System
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-E-002-2	E - Energy	2	\$4,517	Replace light fixtures with high efficiency units
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-H-002-1	H - Handicapped	1	\$3,741	Remodel restrooms to meet ADA Standards
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-M-005-1	M - Physical Plant	1	\$16,154	Replace roofing
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-M-006-2	M - Physical Plant	2	\$8,422	Replace carpet throughout building
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-M-007-2	M - Physical Plant	2	\$5,031	Repaint/refinish interior wall surfaces
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-M-008-1	M - Physical Plant	1	\$7,283	Upgrade electrical distribution system, add circuits and outlets
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-S-001-1	S - Safety	1	\$15,419	Install door, door opener and access ramp and landing
Yakama Tribal School	Loc-School, Day	\$160,160	P11-20-2T-S-002-1	S - Safety	1	\$3,106	Replace existing and install one new exit sign with battery backup
Yakama Tribal School	Loc-Grounds		P11-20-X01-C-001-1	C - Construction	1	\$15,508	Replace a cover with 10x10 pump house building
Yakama Tribal School	Loc-Grounds		P11-20-X01-C-002-2	C - Construction	2	\$46,059	Construct a 20' x 30' building with over head door and 3 double pane windows (3' x 3') and 12' high walls.
Yakama Tribal School	Loc-Grounds		P11-20-X01-M-003-2	M - Physical Plant	2	\$119,690	Remove and replace sidewalks
Yakama Tribal School	Loc-Grounds		P11-20-X01-M-004-2	M - Physical Plant	2	\$6,418	Remove concrete slab and install security fencing for electrical hookup