




2D SEISMIC LINES

NAME	PROD	MILES	LOC	SHOT
400-1	F, S, M	3.75	T41S R23E	1990
400-10	F, S, M	6.06	T42S R24E	1990
400-10S	F, S, M	5.83	T42S R24E	1990
400-11	F, S, M	5.58	T42S R24E	1990
400-11S	F, S, M	6.18	T42S R24E	1990
400-12	F, S, M	7.33	T42S R24E	1990
400-12S	F, S, M	7.43	T42S R24E	1990
400-13	F, S, M	7.83	T42S R24E	1990
400-13S	F, S, M	7.72	T42S R24E	1989
400-14	F, S, M	8.53	T42S R24E	1989
400-14S	F, S, M	7.89	T42S R24E	1989
400-15	F, S, M	10.66	T42S R24E	1989
400-1S	F, S, M	3.71	T41S R23E	1990
400-2	F, S, M	3.66	T41S R23E	1990
400-29	F, S, M	9.66	T42S R24E	1989
400-2S	F, S, M	3.71	T42S R24E	1990
400-3	F, S, M	3.73	T42S R24E	1990
400-3S	F, S, M	3.52	T42S R24E	1990
400-4	F, S, M	3.33	T42S R24E	1990
400-4S	F, S, M	2.81	T42S R24E	1990
400-5	F, S, M	4.06	T42S R24E	1989
400-5-S	F, S, M	3.79	T42S R24E	1990
400-6	F, S, M	4.24	T42S R24E	1990
400-6S	F, S, M	3.87	T42S R24E	1990
400-7	F, S, M	4.09	T42S R24E	1990
400-7S	F, S, M	4.29	T42S R24E	1990
400-8	F, S, M	4.55	T42S R24E	1990
400-8S	F, S, M	5.12	T42S R24E	1990
400-9	F, S, M	5.83	T42S R24E	1990
400-9S	F, S, M	5.96	T42S R24E	1990
600-1	F, S, M	3.25	T41S R23E	1990
600-10	F, S, M	3.16	T41S R23E	1990
600-10S	F, S, M	3.13	T41S R23E	1990
600-11	F, S, M	3.25	T41S R23E	1990
600-11S	F, S, M	3.64	T41S R23E	1990
600-12	F, S, M	4.08	T41S R23E	1990
600-12S	F, S, M	4.17	T41S R23E	1990
600-13	F, S, M	4.33	T41S R23E	1990
600-14	F, S, M	2.50	T41S R23E	1990
600-15	F, S, M	3.08	T41S R23E	1990
600-16	F, S, M	5.41	T41S R23E	1990
600-17	F, S, M	5.75	T41S R23E	1990
600-18	F, S, M	5.83	T41S R22E	1990

NAME	PROD	MILES	LOC	SHOT
600-19	F, S, M	10.08	T41S R21E	1990
600-1S	F, S, M	3.04	T41S R23E	1990
600-2	F, S, M	2.91	T41S R23E	1990
600-20	F, S, M	6.39	T41S R22E	1990
600-21	F, S, M	7.04	T41S R21E	1990
600-22	F, S, M	2.12	T41S R22E	1990
600-2S	F, S, M	2.67	T41S R23E	1990
600-3	F, S, M	2.44	T41S R23E	1990
600-3S	F, S, M	2.58	T41S R23E	1990
600-4	F, S, M	2.79	T41S R23E	1990
600-4S	F, S, M	2.92	T41S R23E	1990
600-5	F, S, M	3.08	T41S R23E	1990
600-5S	F, S, M	3.21	T41S R23E	1990
600-6	F, S, M	3.16	T41S R23E	1990
600-6S	F, S, M	3.22	T41S R23E	1990
600-7	F, S, M	3.29	T41S R23E	1990
600-7S	F, S, M	2.98	T41S R23E	1990
600-8	F, S, M	2.66	T41S R23E	1990
600-8S	F, S, M	2.63	T41S R23E	1990
600-9	F, S, M	2.66	T41S R23E	1990
600-9S	F, S, M	2.97	T41S R23E	1990
900-1	S, M	4.48	T42S R24E	1991
900-10	S, M	1.76	T41S R23E	1991
900-11	S, M	2.73	T42S R24E	1991
900-1S	S, M	4.44	T42S R24E	1991
900-2	S, M	4.91	T42S R24E	1991
900-2S	S, M	4.92	T41S R23E	1991
900-3	S, M	5.69	T41S R23E	1991
900-3S	S, M	4.98	T41S R23E	1991
900-4	S, M	5.69	T41S R23E	1991
900-4S	S, M	4.82	T41S R23E	1991
900-5	S, M	5.57	T41S R23E	1991
900-5S	S, M	3.72	T41S R23E	1991
900-6	S, M	5.63	T41S R23E	1991
900-6S	S, M	1.15	T41S R23E	1991
900-8	S, M	4.06	T41S R23E	1991
900-9	S, M	1.76	T41S R23E	1991
900-9S	S, M	1.24	T41S R23E	1991
MULE SWATH	F, S	3.88	T42S R24E	1996

